

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4 N. R. 12 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

CORNER CODE INDEX

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	A
B																										B
C																										C
D																										D
E																										E
F																										F
G																										G
H																										H
J																										J
K																										K
L																										L
M																										M
N																										N
O																										O
P																										P
Q																										Q
R																										R
S																										S
T																										T
U																										U
V																										V
W																										W
X																										X
Y																										Y
Z																										Z

FULTON TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT WITNESS MONUMENT

BEARINGS ARE BASED ON: _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE U-23(1)

FU612^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1836 (JULY) BURNHAM EAST RANDOM BETW. 25 & 36
5238.42 INT. RANGE LINE AT STAKE
SAME
WEST MARKED LINE BETW. 36 & 25
NO STATIONS
2618.88 SET 1/4 SEC POST BUR OAK 14 N20W 15.18' BUR
OAK 10 S48E 25.08'
2694.78 BUR OAK 10" IN DI.
5238.42 TO CORNERS
- 1864 LOCKE VOL 1 PG 220 & #1341 FD N. BT. STAKE SET HARD
HEAD 20X14X8 ON N VAR 8-05 2620.2 TO SE COR SEC 25,
VAR 7-30 2647.26 TO CEN SEC 25, VAR 7-15 2647.26 FROM
CEN SEC 25 TO N 1/4 COR SEC 25
- 1867 LOCKE VOL 1 PG 297 & 1482 FD N.B.T. & STONE SET BY SELF
(SEE SEC 25), VAR 7-15 2655.84 TO CEN SEC 36,
- 1947 SUNNY #1478 CALLS FOR COR BUT STATES NOTHING ABOUT
MON. 2628.X TO NE COR SEC 36, 2655.8X TO CENTER OF
SEC 36 (SET IRON PIPE FOR SURROUNDED BY 4 HH), 5304.7X
TO S 1/4 COR SEC 36
- 1966 BATTERMAN FIELD BOOK #135 PG 21. SHOWS 8" STONE
CALLS FOR PK TIES OF 6.00' TO THE SE & SW OF FD STONE.
- 1966 BATTERMAN VOL 4 PG 276 FD LARGE HH ON END 20X14X8
REF. SAME. ON LINE N/S FENCE ON NORTH SIDE OF RD.
- 1972 SHARKEY CSM VOL 2 PG 209 STATES NOTHING ABOUT MON.
FIELD NOTES CALLS FOR 1315.62 FROM 1/16TH COR TO S 1/4
COR SEC 25. LEGEND CALLS FOR SETTING OF PIN @ N 1/4 COR
SEC 36
- 1974 SCHROEDER CSM VOL 4 PG 192 STATES NOTHING ABOUT
MON. 199.50 WESTERLY ALONG SEC LINE TO SE COR OF LOT
- 1994 SCHROEDER CSM VOL 17 PG 289 STATES NOTHING ABOUT
MON. WESTERLY 190.00' TO NE COR OF LOT 1
- 1994 SCHROEDER CSM VOL 17 PG 344 STATES NOTHING ABOUT
MON. SE COR OF LOT 1 IS 33.00 NORTH OF S 1/4 COR SEC 25.
ANGLE 90-37-32 @ S 1/4 COR SEC 25 FROM SW COR SEC 25 TO
CENTER OF SEC 25. 199.50 WEST ALONG SECTION LINE TO SW
LOT COR
- 2004 BARNES V-23 FD R/R SPIKE & REPLACED WITH POLY. REF.
SAME. S89-32-20W 2631.06 TO C.I. @ NW COR SEC 36 & N89-
11-31E 2625.76 TO CUT L.S. @ NE COR SEC 36. FD PIN @
N 1/16TH COR OF NW 1/4 OF SEC 36. PIN IS N89-32-40E
1315.44 FROM NW COR SEC 36.
- 2005 COMBS CSM VOL 28 PG 293 ALUM 2625.62 TO CUT STONE @
NE COR SEC 36, 5306.33 TO ALUM @ S 1/4 COR SEC 36, &
ANGLE 90-59-03 FROM NE COR SEC 36 TO S 1/4 COR SEC 36.
- 2004 BARNES V-23 SPIKE 0.4' DEEP AND FD PK 0.2' DEEP & 6.00'
SW OF FD R/R SPIKE. THE SPIKE IS ON LINE WITH THE FD PKs
FOR THE CSMS TO THE WEST & AT THE DISTANCE SHARKEY
CALLED FOR IN 1972. REPLACED FD R/R SPIKE WITH POLY
MON. 24" DEEP FOUND OLD ASPHALT PIECES OF ROAD FROM
OLD DIG. THE FD RECORD TIES ARE NOT IN HARMONY WITH
THE R/R SPIKE. THE RECORD TIE DISTANCES TO THE SW AND
SE REFERENCE PIPES ARE THE SAME, WHICH MIGHT INDICATE
ONE OF THEM IS IN ERROR.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD POLY

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal

SHEET 1 OF 2

Donald Barnes

Emboss

CORNER CODE V-23 (1)

A.E. 7.08 REQUIREMENT

12/03/07

