Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

T. $\frac{1}{2}$ N. R. $\frac{1}{2}$ E. 4th P.M.	WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT REV 10/23/2004 USMONREC.DWG
CORNER CODE INDEX A 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 B C D E F G H J K L M	B ROCK COUNTY WI C IF AVAILABLE E ROCK COUNTY COORDINATES PERFERRED F G H North Elev. J K East L M
NO P Q R S T U V W X Y Z 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 7 18 19 20 21 22 23 22 PLACE MONUMENT SYMBOL AT PROPER	O
CORNER MONUMENT (a)	WITNESS MONUMENT

BEARINGS ARE BASED ON:______

FIELD BOOK _____ PAGE # _____ OF SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.
PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

FU629^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1835 (JAN7) MULLETT& BRINK WEST ON SOUTH SIDE SECTION 35

T4N R12E

ENTER MARSH
LEAVE MARSH

1582.02 B. OAK 18

2640 SET ¼ SECTION POST BUR OAK 16 N50W 23.1'

BUR DAK 12 N71E 39.6'

3243.9 BUR DAK 12 5109.72 BUR DAK 10

5280 SET POST COR SECTIONS 34 & 35 BUR OAK

16 N44W 64.68 BUR DAK B N27E 61.38'
LAND BROKEN 2ND RATE BUR W & B DAK

1835 (JAN7) MULLETT & BRINK WEST ON SOUTH SIDE OF SECTION
34

2640 SET 1/4 SECTION POST BUR DAK 12 N35W 69.3' BUR DAK 14 N34E 23.1'

4436.52 BUR DAK 10

5280 SET POST COR SECTIONS 33 & 34 B. DAK 7 N56W 23.76' B. DAK 16 N46E 44.22' LAND GENTLY ROLLING 2^{ND} RATE W. B. & BUR DAK

1836 (JULY 11) BURNHAM NORTH BETWEEN SECTIONS 34 & 35

1568.82 BUR OAK 10 IN DI

2640 SET 1/4 SEC POST BUR OAK 18 524 1/2W 29.7'

BUR OAK 16 N22E 80.52'

4305.18 BUR OAK 10 IN DI

5280 SET POST COR TO 26,27,34, & 35 BUR OAK 12

N37E 49.5' BUR DAK 24 S7W 34.98' FIRST

RATE BUR DAK DPENINGS

1836 (MAR) D. LYON NORTH BETWEEN SECTIONS 2 & 3 T3N R12E

2057.88 BUR OAK 15 INCHES IN DIAMETER

2640 SET QUARTER SECTION POST {BUR DAK 18

N73E 34.98' BUR OAK 9 N30W 38.28'

2983.86 BUR DAK 12 INCHES IN DIAMETER 3385.8 BUR DAK 14 INCHES IN DIAMETER

4618.02 BUR OAK 10 INCHES IN DIAMETER

4684.68 BUR OAK 12 INCHES IN DIAMETER

5586.9 INTERSECTED NORTH BOUNDARY AT POST

BEARINGS {BUR DAK 12 S14E 11D.22' BUR DAK S35W 50.82' LAND ROLLING & 2ND RATE

TIMBER BUR DAK UNDER GROWTH DAK &

GRASS

- 1843 PIERCE TWP RD BK 1 PG 3 BEGINNING AT THE SE COR OF THE SEC 34 AND THE SW COR OF SEC 35 TOWN 4 R12 FROM SAID PLACE OF BEGINNING ON THE SEC LINES; NORTH 12,672' THEN N40-45W 1089'; THEN N26-45W 1287' THEN N12-45W 330'; THEN N8-15E 528' MAKING 16,995' INTERSECTING ANOTHER RD MAGNETIC VARIATION 7-15E
- 1851 JVN RD BK 1 PG 161 COMMENCING AT THE NW COR OF SEC 2 ON SECTION LINES 2 AND 3, 10 AND 11 RUNNING 6303' ON SAID LINE. """"" DECLARE THE ABOVE ROAD TO BE A PUBLIC HIGHWAY 66' WIDE.
- 1870 RUGER VOL 2 PG 20 & #6639 FD SW & NW BEARING TREES. VAR 7-10 2658.48' TO N $\frac{1}{4}$ COR SEC 2. N $\frac{1}{4}$ COR SEC 2 WAS ESTABLISHED FROM SEC CORNERS. MID WAY
- 1875 RUGER VOL 2 PG 188 FD OLD STAKE & STUMP OF N.W. BT STUMPS OF THE OTHER BTS DUG OUT. SET LIMESTONE 18X12X2 SURROUNDED IT BY 4 HH STONES. VAR 5-46 2640.50 TO W 1/4 COR SEC 35
- 1875 RUGER VOL 2 PG 189 & 6571 SEE PAGE 143 2682.9 TO S 1/4 COR SEC 34.
- 1878 RUGER VOL 2 PG 240 CALLS FOR BUT STATES NOTHING ABOUT MON @ NE COR SEC 3 JANESVILLE TWP. VAR 6-55 2946.02 FROM NE COR SEC 3 TO E 1/4 COR SEC 3.

SHEET 1 OF 2

CORNER CODE Z-17

Duell Pares Doc 13, 2007

FU629

- 1886 RUGER VOL 2 PG 418 CALLS FOR BUT STATES NOTHING ABOUT MON. 2955.15 TO E 1/4 COR SEC 3 JANESVILLE TWP
- 1966 BATTERMAN VOL 4 PG 299 DUG & FD LS SURROUNDED BY HHS AND REMAINS OF STAKE. REF. SAME.
- 1977 BARNES VOL 5 PG 345 FD NAIL & REF. TIES. SET ALUM. MON. 3' WEST OF N/S CENTER PVMT & 4 NORTH OF E/W FENCE LINE
- 1978 NORTHROP CSM VOL 8 PG 14 ALUM. MON BEARINGS ARE REFERENCED TO TRUE NORTH BY SOLAR DBSERVATIONS MADE ON JUNE 21, 1978. S89-48-37W 2676.10 TO S 1/4 COR SEC 34
- 1978 NORTHROP CSM VOL 5 PG 443 2643.49 TO E $\frac{1}{4}$ COR SEC 34 & 2676.12 TO S $\frac{1}{4}$ COR SEC 34.
- 1980 COMBS CSM VOL 10 PG 166 FD ALUM. MON. CREATED SPLIT ON N/S 1/4 LINE OF SEC 35.
- 1980 BARNES VOL 6 PG 17 SHOWS RECORD DISTANCES
- 1987 BARNES VOL 6 PG 365 N89-01-38E 2643.51 TO 5 1/4 COR SEC 35 & S1-13-02E 2954.13 TO W 1/4 COR SEC 2
- 1987 BARNES A-17 FD ALUM. & REF. SAME. 2.7 WEST OF N/S CENTER PVMT.
- 1993 COMBS CSM VOL 16 PG 286 ALUM. MON 2643.55 TO E $\frac{1}{4}$ COR SEC 34
- 1994 LATHROP #9776 STATES NOTHING ABOUT MON 2678.22 FROM N 1/4 COR SEC 3 TO NE COR SEC 3
- 1995 COMBS #9363 ALUM AT NW COR SEC 2
- 1996 COMBS "LOCKWOOD THIRD ADDITION" BK 32 PG 306 ALUM.
 AT NW COR SEC 2 2954.16 TO W 1/4 COR SEC 2
- 1997 COMBS CSM VOL 20 PG 241 ALUM. @ NE COR SEC 3, 2954.16 TO E 1/4 COR SEC 3
- 1997 COMBS CSM VOL 20 PG 422 ALUM. @ NE COR SEC 3, 2954.16 TO E $\frac{1}{4}$ COR SEC 3
- 1998 COMBS CSM VOL 21 PG 30 ALUM. @ NE COR SEC 3, 2954.16 TO E $\frac{1}{4}$ COR SEC 3
- 1999 KREBS CSM VOL 23 PG 20 ALUM. 2643.45 TO E 1/4 COR SEC 34, 2676.22 TO S 1/4 COR SEC 34, & ANGLE 90-45-24 @ SE COR SEC 34 FROM S 1/4 COR SEC 34 TO E 1/4 COR SEC 34. WESTERLY 35.00 ALONG SEC LINE TO PROPERTY COR, & NORTHERLY 251.50 ALONG SECTION LINE TO PROPERTY COR.
- 2004 COMBS CSM VOL 27 PG 250 ALUM. MON. 2643.45 TO ALUM @ E 1/4 COR SEC 34
- 2005 COMBS #15158 ALUM MON 2643.45 TO ALUM @ E 1/4 COR SEC 34

FD ALUM. MON. & REFERENCE MONUMENTS.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FOUND MONUMENTS.

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 2 OF 2

Dans

CORNER CODE Z-17

Pec (3 200) A.E. 7.08 REQUIREMENT