Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

T. N. RE. 4th P.M. CORNER CODE INDEX A	B ROCK COUNTY WI C D IF AVAILABLE ROCK COUNTY COORDINATES PERFERRED F G H North Elev K East Hor. Datum Vert. Datum P LATITUDE ELLIPS. HT R S LONGITUDE V NAD83(91) NETWORK ADJ. YR W GPS (X) TRAVERSE (X) Y RASED ON THE FOLLOWING CONTROL:
Z 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX CORNER MONUMENT (a)	

BEARINGS ARE BASED ON:______

ſ					
			/		3
FIELD BOOK PAGE # _	SI	HEET		OF	
SHOW A PLAN VIEW DRAWING DEPI	CTING THE CORNER MONUMENT AND SUR	RROUNI	DING		
PHYSICAL FEATURES, INCLUDING TI	HE EXCAVATION AREA AND DEPTH.				
PLANNING & ZONING COMMITTEE AI	OOPTED THIS FORM ON 12/2/1982		۸		/-

PO508 N1/4CORSEC3

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 (SEP) BRINK & MULLETT T5N R11E WEST ON SOUTH SIDE SECTION 34

607.20 TRAIL @ SE

2640.00 SET QUARTER SECTION POST BUR OAK 11 N57E 67.98'; BUR OAK 8 N54W 244.2'

3102.0 ENTER PRAIRIE

4884.0 LEAVE PRAIRIE & ENTER MARSH

5280.00 SET POST CORNER SECTION 33 & 34 WILLOW 6
NBE 69.30'; ASPEN B N34W 69.30' LAND
ROLLING SECOND RATE WHITE, BLACK, AND
BUR OAK LAND PRAIRIE AND MARSH

1833 ORIG GOV PLAT NW COR SEC 2 PORTER TWP IS 23.10 EAST OF SW COR SEC 35 DUNKIRK TWP.

1833 ORIG GOV PLAT NW COR SEC 3 PORTER TWP IS 24.42'
EAST OF SW COR SEC 34 DUNKIRK TWP.

1872 LEE VOL 2 PG 82 & #3551 & #6839 SET BR O. STAKE 2 FT HIGH & 4" IN DIAMETER. SHOWS 2657.82 TO NW AND NE CORNERS OF SECTION 3. FOUND STONE & STUMPS OF BTS AT S 1/4 CORNER OF SECTION 34 DUNKIRK TWP. SHOWS A VAR OF 8-00 FOR NORTH LINE OF SECTION. PLACED W.O. STAKE WITH HHS AT E 1/16TH CORNER OF THE NW 1/4. SHOWS A DISTANCE OF 1292.50 TO E 1/16TH CORNER AND 2596.11 TO CENTER OF SECTION 3.

1872 BARNES VOL 6 PG 417 VOL2 PG 82 WAS COPIED INCOORECTLY FROM ORIGINAL COUNTY SURVEYORS RECORD VOL 2 PG 50. THE NORTH LINE OF THE NE 1/4 SHOULD READ 40.27(2657.82) INSTEAD OF 40.29(2659.14)

1882 LEE VOL 2 PG 372 & #6836 FOUND REMAINS OF STAKE SET BY SELF IN 1872. SET A HH 17X14X9. SHOWS 1288.48 TO E 1/16TH CORNER OF THE NW 1/4 THAT HE PLACED IN 1872. SHOWS 2596.11 TO CENTER OFSECTION 3. ALSO SHOWS 2649.90 TO NE CORNER OF SECTION 3.

- 1872 GRAVES VOL 6 PG 355 [BARNES-COPIED FROM DANE COUNTY SURVEYORS' RECORDS BK 5 PG 566.] SURVEYED ON THE 24 & 25 DAYS OF APRIL 1872 THE ABOVE PLATTED SECTION. COMMENCED AT SOUTH QRT CORNER. STONE SET RUN THROUGH TO NORTH QUARTER COR STAKE GONE ONE STUMP FD SET CORNER IN HIGHWAY. WEST QRT COR GONE RUN THROUGH THE WHOLE LINE DIVIDED THE DISTANCE EQUAL SET STONE IN QRT CORNERS: RUN THROUGH TO EAST QRT CORNER: SET STONES AT NO. 1,2,3,4,5. S.W. GRAVES COUNTY SURVEYOR. SURVEY IS OF SEC 34 T5NR11E. 1326.60 FROM STONE @ S 1/4 COR SEC 34 TO STONE @ S 1/16TH COR OF SE 1/4 SEC 34, 2653.20 TO SE COR SEC 34. 1327.26 TO STONE @ S 1/16TH COR OF SW 1/4 SEC 34, & 2653.86 TO SW COR SEC 34.
- 1885 RUGER #6837 STATES NOTHING ABOUT MON BUT USED IT TO SUBDIVIDE SEC 3.
- 1991 BARNES A-15 DUG SEVERAL VERY LARGE HOLES. COR IS 1'
 SOUTH OF PVMT CENTER. ELDERLY PROPERTY OWNER
 STATED THAT MANY YEARS AGO, SOMEONE WITH A BACKHOE
 ALSO TRIED TO FIND THE CORNER AND THE S 1/4 COR OF
 SEC 34. OWNER ALSO STATED THAT THEY DUG FOR THE N
 1/16TH COR OF THE NE 1/4. I FOUND OLD SPOILS WHILE
 DIGGING. ESTABLISHED COR AT MID POINT BETWEEN THE
 NE & NW CORNERS OF SEC 3. USED THE CENTER OF THE RD
 TO CONTROL N/S POSITION OF COR. THIS IN HARMONY WITH
 THE FENCE INTERSECTION AT THE E 1/16TH COR AT THE NE
 & NW 1/4 OF SEC 3 IS PROJECTED TO THE CENTER OF THE
 PVMT. ALSO DUG & FD NOTHING AT THE S 1/4 COR OF SEC
 34. OWNER ALSO STATED THAT THE HIGHWAY DEPARTMENT

SHEET 1 DF 2

CORNER CODE A-15(1)

Bacno Nov 5 2009

P0508

GRADED ABOUT 1 TO 2 FEET OFF THE TOP OF THE ROAD SURFACE. COUNTY COORDINATES OF 328,725.14; E/W 450,724.93

1991 NORTHROP VOL 6 PG 417 N 1/4 COR OF SEC 3 WAS ESTABLISHED BY USING NORTHROP'S SURVEY OF SEC 3. S89-04-18W 2658.20 TO NW COR SEC 3 & N88-40-00E 2658.20 TO NE COR SEC 3

- 2007 PALMER #15694 STATES FD 1 PIPE @ N 1/4 COR SEC 3 (PROBABLY THE S 1/4 COR SEC 34) N88-39-25E 2646.09 TO SET PIPE @ SE COR SEC 34. FD 1" PIPE 1614.59 EASTERLY OF FD PIPE @ S 1/4 COR SEC 34.
- NORTHROP CSM32-122 FD 1" PIPE OF REC @ S 1/4 COR SEC 2008 34 T5N R11E.

FD ALUM AT S 1/4 COR SEC 34 AND N 1/4 COR SEC 3.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD ALUM. MONUMENTS.

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 2 OF 3

CORNER CODE A-15(1)

A.E. 7.08 REQUIREMENT

