

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4 N. R. 11 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

CORNER CODE INDEX

PORTER TWP

ROCK COUNTY WI

IF AVAILABLE

ROCK COUNTY COORDINATES PREFERRED

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	A
B		6					5					4					3				2				1	B
C																										C
D																										D
E																										E
F																										F
G																										G
H																										H
J																										J
K																										K
L																										L
M																										M
N																										N
O																										O
P																										P
Q																										Q
R																										R
S																										S
T																										T
U																										U
V																										V
W																										W
X																										X
Y																										Y
Z																										Z

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

BEARINGS ARE BASED ON: _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE 2-19

P0630 S1/4SEC35

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

**1833 (SEP 15) MULLETT & BRINK T4N R11E 4TH MERIDIAN WEST
ON SOUTH SIDE SEC 35**

**2640.0 SET QUARTER SECTION POST BUR OAK 12
N63E 34.98'; BUR OAK 12 N62W 14.52'**

3531.0 TRAIL

**5280.0 SET POST CORNER SECTION BLACK OAK 24
N81E 31.02'; BUR OAK 12 N70W 20.46'
LAND SAME AS LAST MILE**

**1833 ORIG GOV PLAT NW COR SEC 2 CENTER TWP IS 58.74' WEST
OF SW COR SEC 35 PORTER TWP.**

**1833 ORIG GOV PLAT NW COR SEC 1 CENTER TWP IS 125.40' WEST
OF SW COR SEC 36 PORTER TWP.**

**1869 LEE VOL 1 PG 355 & #0683 FD E BT & STUMP OF W. BT VAR
7-15 2601.56 TO SE COR SEC 35, & VAR 8-00 2601.56 TO
SW COR SEC 35. SHOWS N 1/4 COR SEC 2 AS 110.88 WEST
OF S 1/4 COR**

**1883 RUGER VOL 2 PG 411 & #684 CENTER TWP SET HH 17X6X4
& SURROUNDED BY 3 HH, 2648.58 TO SE COR SEC 35,
2686.20 TO SW COR SEC 35, 110.88 EAST OF N 1/4 COR
SEC 2 CENTER TWP. 2634.06 FROM N 1/4 COR SEC 1 TO NE
COR SEC 1 & 2634.06 TO NW COR SEC 1.**

**1971 LEE VOL 4 PG 502 (APRIL) STATES NOTHING ABOUT MON.
REFERENCED SAME. 110.85 EAST OF N 1/4 COR SEC 2.
STATES HE DUG & FD NOTHING AT THE N 1/4 COR SEC 2
BUT STATES SHIMEALL IN MAY 1971 SET THE CORNER.**

**1983 COMBS #8013 & #13047 FD PIPE @ N 1/4 COR SEC 2
CENTER TWP**

**1990 WOODMAN CSM VOL 14 PG 498 FD 1" PIPE N00-44-00W TO 1
1/4 PIN @ N 1/4 COR SEC 35.**

**1991 SCHROEDER CSM VOL 15 PG 327 STATES NOTHING ABOUT
MON @ N 1/4 COR SEC 2 CENTER TWP.**

**FD PIPE @ EACH COR. E/W FENCE ON SOUTH R/W LINE THAT IS
WEST OF COR. IS GONE. PLACED NEW REFERENCE MONUMENTS.
PIPES ARE IN THE DITCH LINE ON NORTH SIDE OF RD. RECORD
DISTANCES SHOWS THE N 1/4 COR SEC 2 IS MIDWAY BETWEEN THE
NE & NW CORNERS OF SEC 2.**

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

**FD PIPES ARE IN HARMONY WITH PRORATION OF RECORD
DISTANCES & ON LINE WITH SW & SE CORNERS OF SEC 35**

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

NONE

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal
Donald Barnes
Emboss

SHEET 1 OF 2

CORNER CODE **Z-19**

6-09-09

A.E. 7.08 REQUIREMENT

