

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4 N. R. 11 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

CORNER CODE INDEX

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	
A																									A
B	6					5					4				3					2				1	B
C																									C
D																									D
E																									E
F																									F
G	7					8					9				10					11				12	G
H																									H
J																									J
K																									K
L	18					17					16				15					14				13	L
M																									M
N																									N
O																									O
P																									P
Q	19					20					21				22					23				24	Q
R																									R
S																									S
T																									T
U																									U
V																									V
W																									W
X																									X
Y																									Y
Z																									Z

PORTER TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

BEARINGS ARE BASED ON: _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE X-17

PO618

FYA 3A

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 HARRISON (NOV) T4N R11E 4TH MER. NORTH
BET. 34 & 35

2640.0 SET POST FOR COR TO QUARTER SEC
{BURR OAK 18 N85W 34.98'; RED OAK 10
S80E 62.70' {RED OAK 10; BURR OAK
18} MARKED

4339.50 RED OAK 10 IN DIAM.

4639.14 TRAIL CRS N.E.

5280.0 SET POST FOR COR TO SECS 26,27,34,35
BURR OAK 8 N60E 34.98'; BURR OAK 12
N21W 29.70'; RED OAK 10 S65E 27.72';
BURR OAK 12 S30E 42.24'
LAND GENTLY ROLLING 2ND RATE TIMBER
MOSTLY BURR OAK SOME RED OAK- ????
??? GRASS & WEEDS

1855 STEBBINS PORTER TWP RD REC BK 1 PG 7 BEGINNING AT THE 1/4 POST ON THE SEC LINE BETWEEN SECTIONS 22 AND 23; THENCE SOUTH ON THE SEC LINE 8,712' TO A POINT ON THE CENTER OF THE HIGHWAY RUNNING EASTERLY AND WESTERLY THROUGH SEC 34 & 35, SAID POINT BEING 792' SOUTH OF THE SW COR OF SEC 26, T4NR11E. THE LENGTH OF SAID ROAD IS 8712'; SAID ROAD IS 66 WIDE. COURSES GIVEN ACCORDING TO THE TRUE MERIDIAN. VARIATION OF NEEDLE 7 3/4. H. STEBBINS-SURVEYOR

1861 RUGER VOL 1 PG 156 SET HARDHEAD 25X7X13 SURROUNDED IT WITH 4 HARD HEADS. VAR 8-25 1317.03 TO HH 15X9X7 SURROUNDED 4 HH @ E 1/16TH COR OF SE 1/4 SEC 34, 2634.06 TO SE COR SEC 34, VAR 8-25 1322.48 TO HH 10X7X6 SURROUNDED BY 4 HH @ N 1/16TH COR OF SE 1/4 SEC 34, 2644.95 TO HH 16X8X7 SURROUNDED BY 4 HH @ CENTER OF SEC 34, & VAR 8-25 5289.90 TO W 1/4 COR SEC 34

1971 LEE VOL 4 PG 502 FD HH 25X9X13 OF RUGERS UNDER WEST EDGE OF BLACK TOP. REFERENCED SAME

1977 BARNES VOL 5 PG 269 2637.24 TO SE COR SEC 34

1995 KARNS CSM20-172 STATES NOTHING ABOUT MON 2637.24 TO SE COR SEC 34

FD HH 25X9X UNDER WEST PVMT EDGE. HH IS 1' BELOW PVMT SURFACE. PLACED 2 MAGNETS ON EAST SIDE OF HH 15" DEEP. FD HH IS IN HARMONY WITH 2 FOUND REFERENCE PIPES.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD HH.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

NONE

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal

SHEET 1 OF 2

Donald Barnes
Embos
May 6, 2008

CORNER CODE X-17

A.E. 7.08 REQUIREMENT

