Paper weight-110# (minimum)

Black nonfading ink required

U.S.

PUBLIC LAND SURVEY MONUMENT RECORD

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT For Public Land Survey Corners In: USMONREC.DWG T. 4 N. R. 11 E. 4th P.M. CORNER CODE INDEX **PORTER ROCK COUNTY WI** \mathbf{C} IF AVAILABLE D D ROCK COUNTY COORDINATES PERFERRED E F G H J K L M N O P Q R S T U V W E F G North H K East L M Hor. Datum _____ Vert. Datum LATITUDE ELLIPS. HT. Q LONGITUDE _ Т U V NAD83(91) _____NETWORK ADJ. YR____ GPS (X) ____ TRAVERSE (X) ____

◆ CORNER MONUMENT

2 3 4 5 6 7 8 9 10 11 12 13 14 PLACE MONUMENT SYMBOL LOCATION ON ABOVE INDEX

O WITNESS MONUMENT

BASED ON THE FOLLOWING CONTROL:

BEARINGS ARE BASED ON:_______

(a)

	CYTERE	/ OF	3
FIELD BOOK PAGE #	SHEET		
SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AN	D SURROUN	DING	
PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.			
PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982		_ /3	
CORNER	CODE	24	

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 (SEP 15) MULLETT & BRINK T4N R11E 4TH MERIDIAN WEST
ON SOUTH SIDE SEC 34

2640.0 SET QUARTER SECTION POST BUR DAK 16 N76E 42.90'; BUR DAK B N71W B6.46'

5280.00 SET POST CORNER SECTIONS 33 & 34 BUR
OAK 10 N32W 23.76'; BUR OAK N70E 43.56'
LAND ROLLING SECOND RATE TIMBER WHITE
BLACK & BUR OAK

1833 (SEP 15) MULLETT & BRINK T4N R11E 4TH MERIDIAN WEST
ON SOUTH SIDE SEC 33

2640.0 SET QUARTER SECTION POST BUR OAK 14 N34W 35.64'; BUR OAK B N52E 47.52'

5280.0 SET POST CORNER SECTIONS 32 & 33
BUR DAK 12 N86E 184.80'; DOUBLE BUR
DAK 20 N82W 80.52' LAND ROLLING FIRST

RATE TIMBER BUR OAK RED ROOT ROSIN 1833 HARRISON (NOV) $T4NR11E4^{TH}MER.NORTH$ BET. 33 & 34

2640.0 QUARTER SEC COR. {BURR OAK 12 SB6E 29.04'; BURR OAK 12 N87W 29.7' {BURR OAK 12; BURR OAK 12}

5280.0 SET COR TO SECS 27,28,33,34 {BURR OAK 12 S36W 44.22'; BURR OAK 12 N71W 63.36'; BURR OAK 10 N33E 56.76'; BUR OAK 12 S2BE 165.0'
LAND ROLLING 2ND RATE WITH TIMBER OF BURR & RED HICKORY, ??? ???? GRASS & WEEDS

1833 HARRISON (NOV) T3N R11E 4TH MER. NORTH

BET. 3 & 4

949.74 BURR OAK 12

2640.0 SET 1/4 SEC COR IN EAST EDGE OF SMALL PRAIRIE {BURR OAK 18 N7E 263.34'; BUR OAK 12; BURR OAK 18} MARKED

2849.88 TRAIL CRS S.W.

3180.54 BURR DAK 12

5030.52 N BDY 44.88' WEST OF POST {BURR OAK 12 S65W 44.88'; BURR OAK 18 S28E 75.24' LAND LEVEL 2ND RATE TIMBER ALL BURR OAK

1833 ORIG GOV PLAT NW COR SEC 3 CENTER TWP IS 44.88 WEST OF SW COR SEC 34 PORTER TWP.

1884 PORTER TWP RD REC BK 3 PG 8 BEGINNING AT THE JUNCTION OF THE SOUTH-EAST CORNER OF SEC 34 IN SAID TOWN OF PORTER AND THE NE COR OF SEC 3 IN SAID TOWN OF CENTER AND RUNNING; THENCE WEST ON THE SEC LINE OF SAID SEC 2607; THENCE WEST 1/4 MILE TO INTERSECTION OF HIGHWAY RUNNING NORTH & SOUTH THROUGH THE CENTER OF SW 1/4 OF SAID SEC 34 IN SAID TOWN OF PORTER.

BEGINNING AT THE JUNCTION OF THE SE COR SEC 34 IN SAID TOWN OF PROTER AND THE NE COR OF SEC 3 IN SAID TOWN OF CENTER AND RUN THENCE WEST ON THE SECTION LINES OF SAID SECTIONS 2607; THENCE ANGLE TO NORTH SIDE OF SAID TOWN LINE; THENCE WEST 1/4 MILE TO INTERSECTIONS OF HIGHWAY RUNNING NORTH AND SOUTH THROUGH THE CENTER OF SW 1/4 OF SAID SEC 34 IN SAID TOWN OF PORTER THE SAME BEING AN ACCURATE SURVEY THEREOF, AND SAID HIGHWAY BEING UPON THE TOWN LINE BETWEEN SAID TOWNS OR AS NEAR THERETO AS THE SITUATION OF THE GROUND WILL ADMIT. THE LINE OF SAID SHEFT 1 OF 3

SHEET 1 OF 3 / 5 CORNER CODE Z-11

Darl Barres 3-26-2009

- PO627 SEC33/34
 - SURVEY IS THE CENTER OF SAID HIGHWAY AND THE SAME IS LAID OUT OF THE WIDTH OF 49.5' AND WE DO FURTHER ORDER
- 1977 BARNES VOL 5 PG 269 44.88 EAST OF NW COR SEC 3, 2649.78 TO N 1/4 COR SEC 3.
- 1977 BARNES VOL 5 PG 272 DUG FOR BOTH CORS AND FD NOTHING. OCCUPATION AGREED WITH ORIG. GOV. SURVEY NOTES. SET ALUM. MON. & REFERENCED SAME. SW COR SEC 34 IS 44.78 EAST OF NW COR SEC 3. SW 34 IS ON LINE WITH N/S FENCE AND ON SOUTH SIDE OF E/W FENCE.
- 197? LEE VOL 5 PG 466 & 467 OCCUPATION AT NW COR SEC 3 IS 277,681; 2,217,371
- 1979 SCHNEEBERGER CSM VOL 8 PG 501 & #689 STATES NOTHING ABOUT MON @ NW COR SEC 3 CENTER TWP. 2649.22 TO N 1/4 COR SEC 3 CENTER TWP
- 1979 BARNES VOL 6 PG 5 SHOWS IT AS 44.88 EAST OF NW COR SEC 3.
- 1980 SCHNEEBERGER CSM VOL 9 PG 222 & #691CALLS FOR NW COR SEC 3 CENTER TWP WHICH IS 66.00 WEST OF A FD ROD. ROD MAY BE PROPERTY COR.
- 1984 COMBS CSM VOL 11 PG 646 ALUM.
- 1987 COMBS CSM VOL 12 PG 572 ALUM
- 1987 COMBS CSM VOL 13 PG 142 STATES NOTHING ABOUT MON.
- 1987 COMBS CSM VOL 13 PG 430 ALUM MON
- 1988 COMBS CSM VOL 13 PG 444 ALUM. @ NW COR SEC 3
 CENTER TWP. FD PIN 2649.90 TO ALUM @ S 1/4 COR SEC
 34. 48.65' WEST OF SW COR SEC 34 FD IRON PIN 0.9
 NORTH & 0.55 EAST OF SET PIN
- 1999 BARNES A-11(1) SBB-47-36W 2643.49 TO ALUM @ N 1/4 COR SEC 4.
- 2001 COMBS CSM VOL 24 PG 290 ALUM 2605.08 TO ALUM @ N 1/4 COR SEC 3 CENTER TWP
- 2002 LATHROP CSM VOL 25 PG 263 ALUM EAST 2656.80 TO ALUM @ S 1/4 COR SEC 34, EAST 1328.40 TO 1/16TH COR THENCE NO-11-15E 1322.09

I USED MY 1977 & 1999 OBSERVATIONS TO THE FD ALUM. MON.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED ALUM. MON.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

NONE

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

 $N\Box$

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 2 OF 3

CORNER CODE Z-11

Harly Emboss Barres 3-26-2009

A.E. 7.08 REQUIREMENT

