

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4 N. R. 12 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

CORNER CODE INDEX

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	A
B																										B
C																										C
D																										D
E																										E
F																										F
G																										G
H																										H
J																										J
K																										K
L																										L
M																										M
N																										N
O																										O
P																										P
Q																										Q
R																										R
S																										S
T																										T
U																										U
V																										V
W																										W
X																										X
Y																										Y
Z																										Z

FULTON TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

BEARINGS ARE BASED ON: (a) _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 3

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE T-21(1)

FU599 ^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1836 (JULY) BURNHAM NORTH BETWEEN SECTIONS 25 & 26

1279.08 DOUBLE W. OAK 20 IN DI
2640 SET 1/4 SEC POST BUR OAK 12 S22W 41.58';
BUR
OAK 8 N43W 36.96'
2970 BUR OAK 12 IN DI
4847.7 Y. OAK 30 IN DI
5280 SET POST COR TO 23,24,25&26 W. OAK 12
S56 1/2E 39.6', W. OAK 18 S33 1/2W 25.74'
SOUTH HALF FIRST RATE BUR OAK OPENINGS
NORTH HALF VERY BROKEN W. Y & BUR OAK
OPENINGS

- 1864 LOCKE VOL 1 PG 220 & #1341 FD S.B. TREE & STUMP OF N.B. TREE. SET STAKE WITH HARD 16X11X7 ON W AND HARD HEAD 16X12X9 ON EAST VAR 7-50 2643.3 TO NW COR SEC 25, VAR 7-45 2637.36 TO SW COR SEC 25, VAR 8-14 2622.84 TO CEN SEC 25, 5245.68 TO E 1/4 COR SEC 25
- 1966 SHIMEALL #1385 STATES NOTHING ABOUT MON. 1319.65 TO PIPE AT N 1/16TH COR OF SE 1/4 SEC 26 & 2639.30 TO CEN SEC 26.
- 1972 COMBS #1347 FOUND MON BUT STATES NOTHING ABOUT TYPE OF MON ANGLE OF 90-14-35 @ E 1/4 COR SEC 26 FROM E/W 1/4 LINE SEC 26 TO THE EAST LINE OF THE NE 1/4 OF SEC 26
- 1972 COMBS #13245 FD SPIKE NAIL WITH # HH STONES E & W OF IT. 2646.40 TO NE COR SEC 26
- 1972 LEE #1388 LEGEND SHOWS PIPE SET. 2649.73 TO CEN SEC 26, 5297.77 TO W 1/4 COR SEC 26, ANGLE 90-26-21 @ W 1/4 COR SEC 26 FROM E 1/4 COR SEC 26 TO SW COR SEC 26, 2646.47 TO SE COR SEC 26.
- 1972 COMBS CSM VOL 2 PG 296 STATES NOTHING ABOUT MON. 660.86 SOUTH OF CENTER OF COX RD.
- 1975 SCHROEDER CSM VOL 5 PG 155 STATES NOTHING ABOUT MON. SOUTHERLY 286.80 TO PIPE
- 1975 SCHROEDER #1340 CALLS COR FOR BUT STATES NOTHING ABOUT MON.
- 1976 SCHROEDER #1361 CALLS FOR COR BUT STATES NOTHING ABOUT MON.
- 1976 SCHROEDER CSM VOL 5 PG 299 STATES NOTHING ABOUT MON. 1/4 COR IS ALSO THE NE COR OF LOT 1. SOUTHERLY 268.80 TO PIPE @ LOT COR, WESTERLY 278.49 TO PIPE AT LOT COR, & ANGLE 84-29 @ E 1/4 COR SEC 26 FROM EAST LINE OF SE 1/4 OF SEC 26 TO NORTH LINE OF SE 1/4 OF SEC 26.
- 1976 SCHROEDER CSM VOL 6 PG 123 STATES NOTHING ABOUT MON. ANGLE 90-14-35 @ E 1/4 COR SEC 26 FROM SOUTH LINE OF NE 1/4 OF SEC 26 TO EAST LINE OF NE 1/4 OF SEC 26.
- 1976 COMBS #1381 CALLS FOR COR BUT STATES NOTHING ABOUT MON.
- 1977 SCHROEDER #1369 & #1360 CALLS FOR COR BUT STATES NOTHING ABO
- 1977 SCHROEDER CSM VOL 6 PG 289 STATES NOTHING ABOUT MON.
- 1977 SCHROEDER CSM VOL 6 PG 290 STATES NOTHING ABOUT MON. 1/4 COR IS ALSO THE NE COR OF LOT. WESTERLY 311.30 TO LOT COR, SOUTHERLY 288.40 TO LOT COR, & ANGLE 89-26-29 @ E 1/4 COR SEC 26 FROM EAST LINE OF SE 1/4 OF SEC 26 TO NORTH LINE OF SE 1/4 COR SEC 26.
- 1977 BARNES VOL 5 PG 287 THERE IS A PROBLEM WITH THE CENTER OF SEC 26. MR. SHIMEALL SUPPOSEDLY SET THE CENTER AT THE INTERSECTION OF THE E/W & N/S 1/4 LINES. SINCE THEN MANY SURVEYS BY MR SHIMEALL AND OTHER

PAGE 1 OF 3

CORNER CODE T-21(1)

11-28-07
Dwight Barnes

FU599

SURVEYORS HAVE BEEN TIED TO THIS POINT. I WAS REQUESTED TO VERIFY THE LOCATION OF THE E 1/4 COR AND THE CENTER. I TRAVERSED THE SECTION AND TIED INTO THE QUARTER CORNERS, SE COR, AND CENTER OF SEC 26 AS SET BY SHIMEALL AND LEE INDICATES THEY USED THE SAME CORNER. THE N 1/4 COR AGREES WITH THE SHORT TIES THAT MR SHIMEALL HAD ON A PLAT OF SURVEY. MY COMPUTATIONS SHOW THAT THE INTERSECTION OF THE E/W AND N/S 1/4 LINES IS AS RECORDED BY LEE ON THE PLAT OF SURVEY DATED OCT 30 1872.

- 1977 BARNES VOL 5 PG 288 FD CI 2636.8 TO FD PIPE @ CEN SEC 26, 2646.24 TO SE COR SEC 26.
- 1978 SCHROEDER CSM VOL 8 PG 191 STATES NOTHING ABOUT MON. WESTERLY 1319.65 TO 1/16TH COR.
- 1979 THOM CSM VOL 9 PG 71 FD C.I.
- 1979 COMBS "CURHAKEN ESTATES" BK 31 PG 1 4" CAST IRON MON. S85-31-50W 883.29 TO PIPE; THENCE S85-31-50W 872.64 A PIPE AT THE NW COR OF SUB.
- 1983 SCHROEDER #5296 CALLS FOR COR BUT STATES NOTHING ABOUT MON.
- 1986 COMBS #13342 CALLS FOR COR BUT STATES NOTHING ABOUT MON.
- 1988 COMBS VOL 13 PG 218 FD SPIKE NAIL. NORTHERLY 440.36' TO PIPE (PROPERTY COR), 825.76 TO SOUTH R/W LINE OF COX RD
- 1988 COMBS VOL 13 PG 257 CI ANGLE 90-32-30 @ W 1/4 COR SEC 25 FROM NW COR SEC 25 TO FD L.S. AT CEN OF SEC 25.
- 1989 COMBS CSM VOL 14 PG 254 COR IS THE SW COR OF LOT 2. C.I.I. ANGLE 89-27-30 @ W 1/4 COR SEC 25 FROM WEST LINE OF NW 1/4 TO SOUTH LINE OF NW 1/4 SEC 25. EASTERLY 418.12 TO CENTER OF KIDDER RD. FD L.S. AT CENTER OF SEC 25.
- 2002 COMBS CSM VOL 25 PG 279 FD CAST IRON MON. ANGLE OF 89-35-50 @ SW COR SEC 25 FROM W 1/4 COR SEC 25 TO SE COR OF THE SW 1/4 OF THE SW 1/4 OF SEC 25
- 2002 LATHROP #14391 FD CAST IRON MON
- 2002 COMBS #14509 FD CI 2645.71 TO CI @ SW COR SEC 25. ANGLE 98-43-15 @ E 1/4 COR SEC 26 FROM SE TO MON. ON E/W LINE 310.35 S85-32-15W OF E 1/4 COR SEC 26.
- 2002 BARNES T-21 THE ALLIANT ENERGY COMPANY PROVIDED THE FOLLOWING STATE PLANE COORDINATES. THEY WERE DETERMINED BY RTK GPS. I CONVERTED THEM TO ROCK COUNTY PROJECTION. NAD83(91). 305,221.86N/S 490,483.52E/W
- 2004 COMBS CSM VOL 27 PG 322 FD CI 2645.75 TO CI @ SW COR SEC 25.

USED MY 1977 OBSERVATIONS.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD C.I.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal

SHEET 2 OF 3

Emboss

11-28-07
Donald Barnes

CORNER CODE **T-21(1)**
A.E. 7.08 REQUIREMENT

NE COR
SEC 26
FD CI

N00-13-30W 2646.61

E 1/4 COR
SEC 26
FULTON TWP
T4N R12E

CENTER OF
SEC 26
FD MON.

FD CI

S89-41-11W 2637.63

N89-14-05E 5269.50

EMBOSSED
SEAL

Donald Barnes

11-28-07
60-22-11

(1)12-1

SHEET 3 OF 3

S00-03-41E 2646.24

SE COR
SEC 26

FD CI

POLY MON
E 1/4 COR
SEC 25