

# U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4 N. R. 12 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

### CORNER CODE INDEX

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	A
B		6																								B
C			5																							C
D				4																						D
E					3																					E
F						2																				F
G							1																			G
H								7																		H
J									8																	J
K										9																K
L											10															L
M												11														M
N													12													N
O														13												O
P															14											P
Q																15										Q
R																	16									R
S																		17								S
T																			18							T
U																				19						U
V																					20					V
W																						21				W
X																						22				X
Y																							23			Y
Z																							24			Z
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	

FULTON TWP  
ROCK COUNTY WI

IF AVAILABLE  
ROCK COUNTY COORDINATES PREFERRED

North \_\_\_\_\_ Elev. \_\_\_\_\_

East \_\_\_\_\_

Hor. Datum \_\_\_\_\_ Vert. Datum \_\_\_\_\_

LATITUDE \_\_\_\_\_ ELLIPS. HT. \_\_\_\_\_

LONGITUDE \_\_\_\_\_

NAD83(91) \_\_\_\_\_ NETWORK ADJ. YR \_\_\_\_\_

GPS (X) \_\_\_\_\_ TRAVERSE (X) \_\_\_\_\_

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL  AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

BEARINGS ARE BASED ON: (a) \_\_\_\_\_

FIELD BOOK \_\_\_\_\_ PAGE # \_\_\_\_\_

SHEET 1 OF 3

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE A-79(1)

FU510

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1833 (SEP21ST) MULLETT & BRINK EAST ON SOUTH SIDE SECTION  
35 T5N R12E  
1668.48 WHITE OAK 12 IN DIAMETER  
2640 SET QUARTER SECTION POST WHITE OAK 18 N72W  
38.94' WHITE OAK 24 N68E 48.18'  
2772 ENTER MARSH  
3514.5 LEAVE MARSH  
4097.28 WHITE OAK 14 IN DIAMETER  
5280 SET POST CORNER SECTIONS 35 & 36 BUR OAK 14  
N74W 41.58' BUR OAK 18 N62E 8.58' LAND  
ROLLING SECOND RATE WHITE BLACK AND BUR OAK
- 1876 TWP RD BK 1 PG 53 COMMENCING 49.5' SOUTH OF SOUTH  
QUARTER STAKE OF SEC 2 OF THE TOWN OF FULTON, &  
24.75' WEST OF SAID QUARTER LINE; THENCE NORTH ON  
LAND OF JAMES WELCH, JOHN SHERMAN AND PATRICK  
QUIGLEY 5478' TO HIGHWAY AND 24.75' WEST OF PARALLEL  
WITH SAID QUARTER LINE, SAID LINE BEING THE CENTER OF  
SAID HIGHWAY WHICH IS LAID OUT 49.5' WIDE AND \$60.00  
DAMAGES IS AWARDED TO PATRICK QUIGLEY.
- 1911 HINTZE ALBION T5N R12E S89-55W 2675.6' TO SE COR SEC  
35, S89-15W 2685.6 TO SW COR SEC 35, WD N22-30E 11.3';  
W.O. N75E 54.9'; SET S 1/4 COR SEC 35, 18.8' WEST OF ROCK  
COUNTY COR.  
AT DANE COUNTY CORNERS, HINTZE INSTALLED CONCRETE  
MONUMENTS.  
THE DIFFERENCE IN BEARING OF LINES BETWEEN SECTION  
CORNERS GIVES THE TRUE DEVIATION FROM THE STRAIGHT  
LINE. SOME OF THE BEARINGS ARE MAGNETIC, CHECKED BY  
MEASUREMENTS, AND THE REST ARE TRANSIT LINES  
CHECKED BY OBSERVATIONS ON POLARIS. I  
HEREBY CERTIFY THAT THE DISTANCES AND BEARINGS ARE  
CORRECT ACCORDING TO SURVEY MADE UNDER THE  
PROVISIONS OF CHAPTER, 39 SECTION 825 OF THE REVISED  
STATUTES OF WISCONSIN AND IN ACCORDANCE WITH THE  
RULES ESTABLISHED BY THE UNITED STATES LAND OFFICE.
- 1984 BARNES VOL 6 PG 326 COORDINATE BY SANDSNES  
310,377.82; 21,256,657.13 N89-16-51E 2647.88 TO NE  
COR SEC 2, S89-17-51W 2647.87 TO NW COR SEC 2, 38.30  
EAST OF S 1/4 COR SEC 35, 310,377.34; 2,256,618.84 @ FD  
CONC. MON S 1/4 COR SEC 35, S89-17-44W 2630.71 FROM S  
1/4 COR SEC 35 TO SW COR SEC 35, N89-16-47E 2669.68  
FROM S 1/4 COR TO SE COR SEC 35.
- 1985 BARNES A-19 @ S 1/4 COR SEC 25 FD CONCRETE MON 1.5'  
ABOVE GROUND, 310,377.34 N/S; 2,256,618.84' E/W, N89-  
55-58E 38.30 FROM S 1/4 COR SEC 35 TO N 1/4 COR SEC 2, N  
1/4 COR SEC 2 POLY MON. 310,372.82 N/S; 2,256,657.13  
E/W, REFERENCED CORNERS. I DID NOT FIND ANY RECORD  
EVIDENCE THAT THE N 1/4 COR SEC 2 WAS SET. I SET THE COR.  
AT MID POINT BETWEEN THE NE & NW CORNERS OF SEC 2  
AND ON LINE WITH THE S 1/4 COR SEC 35/
- 1985 BARNES VOL 6 PG 342 S89-57-04W 2648.09 TO NW COR SEC  
2, N89-56-01E 2648.09 TO NE COR SEC 2, S89-56-01W  
38.30 TO S 1/4 COR SEC 2 (REC HINTZE 18.8), FD CONC. MON.  
@ S 1/4 COR SEC 35, N89-55-58E 2669.88 (REC 1912 HINTZE  
N89-55E 2675.6) FROM S 1/4 COR TO SE COR SEC 35, S89-57-  
01W 2630.89 (REC 1912 HINTZE S89-15W 2685.6) FROM S 1/4  
COR SEC 35 TO SW COR SEC 35.
- 1997 NORTHROP #8447 & 8450 FD POLY N89-16-54E 2648.18 TO  
NE COR SEC 2, S1-09-13E 2731.05 TO GEN SEC 2, &  
5357.05 TO S 1/4 COR SEC 2.

SHEET 1 OF 3

CORNER CODE A-19(1)

*Ronald Barnes*  
12-11-06

FU510

1997 NORTHROP #8449 & 8446 ALUM. 2648.18 TO NE COR SEC 2,  
2731.05 TO CENTER SEC 2, 5357.05 TO S 1/4 COR SEC 2,  
EASTERLY OF S 1/4 COR SEC 35, 2669.73 FROM S 1/4 COR SEC  
35 TO SE COR SEC 35

1997 WOLLEN 6-450 S 1/4 COR SEC 35 310,248.56'; 2,256,964.65'  
NB9-10-40E 2637.00 FROM POINT 3901

AT S 1/4 COR SEC 35 FD CONC. MON 1.5' ABOVE GRADE. THERE IS A  
METAL POST WITH SIGN SOUTH OF MON. FD ALUM. MON. WITH  
YELLOW CARSONITE POST AT N 1/4 COR SEC 2. THE 3/8" PIN IN THE  
CONC. MON. IS ABOUT 0.1' SE OF THE CENTER OF CONC. & THE  
MON IS LEANING SLIGHTLY TO THE SE.

*B) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?*

IN HINTZE'S FIELD NOTES HIS CALL OF 18.8' TO THE N 1/4 COR SEC  
2 DOES NOT CALL FOR A MONUMENT. THE 1876 TWP RD REC CALLS  
FOR A N/S ROAD WITH THE WEST R/W LINE 24.75' WEST OF THE N/S  
QUARTER LINE (FENCE IS 19.6' WEST OF ALUM). THE ROAD IS 49.5'  
WIDE. ACCEPTED FOUND ALUM. MON.

*D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.*

*(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.*

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

*Donald Barnes*  
12-11-06  
Seal  
Emboss

SHEET 2 OF 3

CORNER CODE **A-19(1)**  
A.E. 7.08 REQUIREMENT

