

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners in:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 1 N., R. 11 E

CORNER CODE INDEX

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B	6				5					4				3						2					1
C																									
D																									
E																									
F	1				8					9				10					11					12	
G																									
H																									
I																									
J	18				17					16				15					14					13	
K																									
L																									
M																									
N																									
O																									
P	19				20					21				22					23					24	
Q																									
R																									
S	30				29					28				27					26					25	
T																									
U																									
V																									
W	31				32					33				34					35					30	
X																									
Y																									
Z																									

NEWARK TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON:

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

CORNER CODE R-15

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1834 MILLER EAST RANDOM BETWEEN SECS 22 & 27
- 1980 ENTER MARSHY GROUND SW
- 4290 LEAVE SAME
- 4818 BROOK 6.6 S
- 5276.04 INTERSECT SEC LINE 12.54' NORTH OF POST
LAND LEVEL MOSTLY LOW AND WET 2ND RATE TIMBER OAK &
HICKORY
- 2638.02 SET 1/4 SEC POST YELLOW OAK 6 IN N52E 134.64'; BUR OAK 5 IN N35E
168.96'
- 4536.84 BUR OAK 18 IN
- 5276.04 SEC COR.

- 1871 COLLINS REMONUMENTATION NOTES
WEST BETWEEN 22 & 27 VARIATION 4-30
ON OFFSET 11.88' SOUTH
- 2655.18 INTERSECT 1/4 LINE 5.94' NORTH OF CORNER. SET 1/4 STONE BY
WITNESS TREE AND STUMP CORRECTED VARIATION 4-38
CONTINUED WEST VARIATION 3 ON OFFSET 13.2' NORTH
- 5313.66 INTERSECT SECTION LINE 24.42' NORTH OF CORNER CORRECTED
VARIATION 3-15
- 1930 BATTERMAN VOL 3 PG 174 N86-50W 1327.6 FROM NE COR SEC 27 TO N 1/16TH
COR OF NE 1/4 SEC 27. FD STONE MON.
- 1930 BATTERMAN VOL 3 PG 175 FD STONE MON.
- 1931 SUNNY VOL 3 PG 191 FD 6X6 CUT STONE MON 6" ABOVE GROUND, 3' SOUTH OF
E/W FENCE LINE, 1082.9' NORTH OF CENTER OF PVMT.
- 1955 SHIMEALL #3218 & 3217 2655.2 TO NE COR SEC 27
- 1979 BARNES VOL 5 PG 537 2646.61 TO CENTER OF SEC 27, 5294.92 TO S 1/4 COR SEC
27, 2654.91 TO NE COR SEC 27

FOUND CUT LIMESTONE BROKEN LENGTHWISE. 0.3' SOUTH OF THE E/W FENCE. SET R/R IN CENTER OF LIMESTONE, MAGNETS 1' DEEP ON SOUTH & WEST FACE, & CARSONITE POST ON NORTH SIDE.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FOUND LIMESTONE

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

seal

Number of included sheets 1

emboss
Donald Barnes

NOV 10 2000

CORNER CODE -R-15'

