

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners in:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 1 N., R. 11 E

CORNER CODE INDEX

A	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B	6																							
C		5																						
D																								
E																								
F	1																							
G		8																						
H																								
I																								
J																								
K	18																							
L		11																						
M																								
N																								
O																								
P	19																							
Q		20																						
R																								
S																								
T	30																							
U		29																						
V																								
W																								
X	31																							
Y		32																						
Z																								

NEWARK TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL  AT PROPER LOCATION ON ABOVE INDEX

 CORNER MONUMENT  WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON:

OBSERVATION SHEETS 202 & 203

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 1

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

CORNER CODE 15

NE608

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1834 MILLER PG 20 EAST RANDOM BETWEEN SEC 27 & 34.

1007.82 BROOK 1.32' NE

4356 CREEK 9.9' SE

4468.2 SAME CREEK NE

4554 SAME CREEK SE

4752 LEAVE CREEK BOTTOM

5273.4 SEC LINE 8.58' SOUTH OF POST

WEST CORRECTED BETWEEN SEC 27 & 34

1290.96 BUR OAK 12

2622.18 BUR OAK 12

2636.7 SET 1/4 SEC POST BUR OAK 18 N87E 42.9'; BUR OAK 15 S1W
67.98'

2818.86 BUR OAK 10 IN DIA

5260.2 SEC COR.

1863 LOCKE VOL 1 PG 176 SET STAKE & 3 LIMESTONES. BEARING TREES GONE.
VAR 5-10 2657.16 TO SE & SW CORNERS OF SEC 27, 2649.24 TO CENTER OF SEC
34, & 5298.48 TO S 1/4 COR SEC 34.

1871 COLLIN'S REMONUMENTATION NOTES

PG 163 EAST BETWEEN 27 & 34 VARIATION 5-15

2645.94 SET 1/4 STONE IN PLACE OF STAKE AND STONES AGREEING WITH
STUMPS OF WITNESS TREE.

CONTINUED EAST VARIATION 4-30

3965.94 OFFSET 577.5' SOUTH AT RIGHT ANGLE

5292.54 OFFSET NORTH AT RIGHT ANGLE INTERSECTING SEC CORNER AT
584.76. CORRECTED VARIATION 4-20

1871 COLLIN'S VOL 5 PG 550 2649.24 TO CENTER OF SEC 27 & 5298.48 TO N 1/4 COR 27.

1974 BATTERMAN VOL 4 PG 375 FD CUT STONE 8-23-74 & REFERENCED SAME.

1979 BARNES VOL 5 PG 537 5294.92 TO N 1/4 COR SEC 27, 2642.40 TO SE COR SEC 27, AN
ANGLE OF 92-29-44 @ S 1/4 COR SEC 27 FROM N 1/4 COR SEC 27 TO SE COR SEC
27, 2648.31 TO E/W 1/4 LINE OF SEC 27.

1979 BARNES VOL 5 PG 550 DUG & FOUND CUT LIMESTONE 2' DEEP. PLACED I.P.
HORIZONTALLY ON NORTH SIDE OF STONE. SET ALUM MON ON TOP OF
STONE. REFERENCED SAME. COR 2' SOUTH OF CENTER PVMT, 10.00' NW TO
PK & 10.00 NE TO PK.

1980 LEUENBERGER #3225 1321.28 EAST TO 1/16TH COR

FD ALUM. USED MY 1979 OBSERVATIONS. FD TIES OF RECORD IN VOL 5 PG 550.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FOUND PERPETUATED LOCATION.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

seal

emboss
Donald Barnes
7-06-01

sheet 1 of 1

CORNER CODE V-15

A-E 7.08 REQUIREMENT