,rn1.mum)

Black non SUR

required

PUBLIC LAND MONUMENT RECORD

CORNER CODE INDEX						NEWARIC TWP	
6						ROCK COUNTY WI	
141	17					IF AVAILABLE	
						ROCK COUNTY COORDINATES PERFERRED	
	8	9	AO.		12	North Elev	
18	N.	1/0	AÓ	1	13	East	
						Hor. Datum Vert, Datum	
19	20	2	22	23	24	LATITUDE ELLIPS.	
20	09	08	1	06	05	LONGITUTE	
194	4	4	4		7	GPS (X) TRAVERSE (X)	
	02	a 3	aA	25	ag	BASED ON THE FOLLOWING CONTROL:	
+7+	H $\overline{1}$ $+$	1171	H				

BEARINGS ARE BASED ON:

(a)

_PAGE #

SHEET

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

NE514

(B)Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 MULLETT

NORTH ON EAST SIDE SECTION 1

539.22 BLACK OAK 12 IN DIAMETER

2640 SET QUARTER SECTION POST BLACK OAK 18 N36W 65.34', BLACK OAK 8S64W 177.54'

3794.34 BUR OAK 10 IN DIAMETER

5280 SET TEMPORARY 6 MILE POST LAND ROLLING SECOND RATE WHITE & BUR OAK SEP 4TH 1833

1871 COLLINS REMONUMENTATION NOTES (NOV 4TH 1871)

PG 208 NORTH ON TH

NORTH ON THE WEST LINE OF SEC 6. VARIATION 6-45

2661.78 SET 1/4 STONE BY WITNESS TREES.

CONTINUED NORTH VARIATION 6-30

5068.14 STONE AT SW COR SEC 31 TOWN 2 R 11

- 1963 BATTERMAN VOL 4 PG 164 FD CUT STONE @ COR. & REFERENCED SAME.
- 1985 LEE CSM 12 PG 59 SET R/R SPIKE AT W 1/4 COR SEC 6. SURVEYED EXISTING SMALL PARCEL IN SEC 1 ADJACENT TO CORNER. DID NOT STATE ANYTHING ABOUT CORNER.
- 1987 BARNES A-25 FD R/R SPIKE
- 1993 BARNES A-1(1) CALLS FOR 2406.19 TO NW COR SEC 6 AND AN ANGLE OF 90-28-31 AT THE NW COR SEC 6 FROM THE W 1/4 COR SEC 6 TO THE N 1/4 COR SEC 1 AVON TWP.
- 1993 BARNES A-23 SAME AS A-25 MADE IN 1987
- 1997 LATHROP CSM VOL 20 PG 43 CALLS FOR 2405.45 TO NW COR SEC 6

FD BENT PIN 1.0' EAST OF CENTER OF PVMT. IN HARMONY WITH NE REFERENCE PIPE. REPLACED WITH 3/4X24" REROD.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FOUND PERPETUATED MONUMENT.

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.
- I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

seal

Number of included sheets 1

emboss 0// 10/

CORNER CODE C-1

A-E 7.08 REQUIREMENT

