

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners in:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 1 N., R. 11 E

CORNER CODE INDEX

A	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B																								
C	6																							
D																								
E																								
F																								
G	7																							
H																								
I																								
J																								
K																								
L	18																							
M																								
N																								
O																								
P	19																							
Q																								
R																								
S																								
T	30																							
U																								
V																								
W																								
X	31																							
Y																								
Z																								

NEWARK TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON:

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

CORNER CODE E-13

NE527

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1834 MILLER PG 29 EAST RANDOM BETWEEN SECS 4 & 9

5016 ENTER PRAIRIE

5256.9 INTERSECT SEC LINE 6.6' SOUTH POST

LAND GENTLY ROLLING 2ND RATE TIMBER OAK & HICKORY, OAK & HAZEL UNDERGROWTH. PRAIRIE GRASS 2ND RATE

WEST CORRECTED BETWEEN SEC 4 & 9

*

2628.12 SET 1/4 SEC POST. WHITE OAK 4 IN S82E 9.9'; HICKORY N55W 89.1'

3785.1 HICKORY 12 IN DIA

4872.78 WHITE OAK 15 IN DIAMETER.

*2491.5 BUR OAK 16 IN DIA. (BOTTOM OF PAGE)

PG 24 NORTH BETWEEN SECS 3 & 4

2319.9 TRAIL CRS N.W.

2640 SET 1/4 SECS POST IN MOUND OF EARTH AND SOD

5283.3 INTERSECT N. BOUNDARY. 33.66' EAST OF POST. SET POST IN MOUND OF STONE. COR OF SEC 3 & 4. LAND ROLLING 2ND RATE. MARCH 10, 1834

PG 24 EAST RANDOM BETWEEN SECS 3 & 10

2719.2 TRAIL N.W.

5275.38 INTERSECTED SEC LINE 4.62' NORTH POST. LAND DRY ROLLING PRAIRIE 2ND RATE.

WEST CORRECTION

2637.36 SET 1/4 SEC POST IN MOUND OF EARTH AND SOD

5275.38 SEC COR.

PG 23 NORTH BETWEEN 9 & 10

2030.16 HICKORY 12 IN

2244 ENTER PRAIRIE

2640 SET 1/4 SEC POST. YELLOW OAK 15 IN S13W 429'; YELLOW OAK 15 IN S4E 4.69'

5280 SET POST IN MOUND OF EARTH AND SOD COR OF SEC 3,4,9, 10 LAND 2ND RATE SOUTH 1/2 LEVEL TIMBERED WITH OAK & HICKORY OAK & HAZEL UNDERGROWTH. NORTH HALF ROLLING PRAIRIE.

1871 COLLINS REMONUMENTATION

PG 184 EAST RANDOM BETWEEN SECS 4 & 9

2643.96 INTERSECT 1/4 LINE 19.8' NORTH OF CORNER. SET 1/4 STONE BY WITNESS TREE IN PLACE OF OLD STAKE. CORRECTED VARIATION 6-12

CONTINUED EAST VARIATION 5

5293.86 SECTION CORNER OCT 28, 1871

PG 172 NORTH BETWEEN 3 & 4 VARIATION 6-30

2682.9 SET 1/4 STONE IN LINE WITH FENCES EAST & WEST.

CONTINUED NORTH VARIATION 6-25

5134.8 SET STONE FOR CORNER OF 3 & 4. 33.66' EAST OF PLYMOUTH CORNER.

PG 171 EAST BETWEEN 3 & 10 VARIATION 2-05

2685.54 SET 1/4 STONE IN OLD MOUND AS SHOWN BY MR. POWERS.

CONTINUED EAST SAME VARIATION

5320.92 SECTION CORNER.

PG 170 NORTH BETWEEN 9 & 10 VARIATION 5-57

2677.62 SET 1/4 STONE IN PLACE OF STAKE SET BY MESSER SAID BY SHOEMAKER TO HAVE BEEN THERE 20 YEARS

Donald Barnes
7-03-01

NE527

CONTINUED NORTH VARIATION 5-30

- 5344.68 SET STONE FOR CORNER OF 3,4,9,10 IN INTERSECTION OF HIGHWAY.
1873 RUGER VOL 2 PG 117 STONE MON. 2678.28 TO A STONE MON AT THE S 1/4 COR SEC 3 & 2676.3 TO A STONE MON AT THE W 1/4 COR SEC 3
1882 HOLMES VOL 2-348 CALLS FOR A MON. 2645.94 TO S 1/4 COR SEC 4 & 2662.44 TO E 1/4 COR SEC 9
1882 RUGER VOL 2 PG 403 SEE PG 75. 2676.52 TO W 1/4 COR SEC 3.
1966 BATTERMAN VOL 4 PG 271 FD LARGE HH OVER 6X6 CUT L.S. BROKEN OFF. REFERENCED SAME.
1977 BARNES VOL 5 PG 332 FD REFERENCE PIPES

FD ALUM. MON. & TIES AS RECORDED IN VOL 4 PG 271.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FOUND PERPETUATED LOCATION.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

seal

Donald Barnes

emboss

7-03-01

SHEET 2 OF 2

CORNER CODE **E-13**

A-E 7.08 REQUIREMENT