

Paper weight _____ (minimum)

Black non-_____ required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners in:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 1 N., R. 11 E

CORNER CODE INDEX

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B	6																								
C																									
D																									
E																									
F																									
G	1																								
H																									
I																									
J																									
K																									
L	18																								
M																									
N																									
O																									
P																									
Q	19																								
R																									
S																									
T																									
U																									
V																									
W																									
X																									
Y																									
Z																									

NEWARK TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____


Hor. Datum _____ Vert. Datum _____


LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL  AT PROPER LOCATION ON ABOVE INDEX

 CORNER MONUMENT  WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON:

Fd TIES IN Vol 4 pg 27

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

CORNER CODE VQ

NE605-SECORSEC29

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1834 MILLER PG 31 EAST RANDOM BETWEEN SEC 29 & 32
5299.8 INTERSECT SEC LINE 5.94' NORTH POST LAND LEVEL 2ND RATE OAK & HICKORY TIMBER OAK & HAZEL USG.
WEST CORRECTED BETWEEN SEC 29 & 32
- 531.3 BUR OAK 20
2649.9 1/4 SEC POST BUR OAK 12 S10W 8.58'; BUR OAK 16 N43W 46.86'
3464.34 WHITE OAK 22 IN DIA
5045.7 BUR OAK 12 IN DIA
5299.8 SEC CORNER
PG 26 NORTH BETWEEN SEC 28 & 29
- 330 ENTER MARSH C E
990 LEAVE SAME
1227.6 BUR OAK 18 IN
2640 SET 1/4 SEC POST YELLOW 6 IN S2W 165'; BUR OAK 12 IN N4-30E 300.96'
4563.9 BUR OAK 14 IN DIAMETER
4940.1 YELLOW OAK 14 IN DIA
5280 SET POST COR SECS 20,21,28,29 YELLOW OAK 22 IN N87E 133.32'; BUR OAK 22 IN S65W 232.32' LAND 2ND RATE ROLLING SOIL SANDY TIMBER OAK & HICKORY OAK & HAZEL U.G. PRAIRIE GRASS RED ROOT
PG 25 NORTH BETWEEN SECS 32 & 33
- 1254 BUR OAK 12 IN DIAMETER
2640 SET 1/4 SEC POST BUR OAK 12 IN S1-30W 69.3'; WHITE OAK 22 IN N30E 56.76'
4798.2 BUR OAK 18 IN DIAMETER
5280 SET POST COR OF SEC 28,29,32,33 YELLOW OAK 12 S60W 57.42'; YELLOW OAK 12 N5E 178.86' LAND GENTLY ROLLING 2ND RATE TIMBER SCATTERING OAK & HICKORY SOIL SANDY
PG 25 EAST RANDOM BETWEEN 28 & 33
- 3960 ENTER MARSHY GROUND
5261.52 INTERSECT SEC LINE 2.64' NORTH POST. LAND MOSTLY LEVEL MARSHY TIMBER SCATTERING OAK & HAZEL U.G.
WEST MARKED BACK
- 2630.76 SET 1/4 SEC POST BUR OAK 12 N74E 54.12'; BUR OAK 12 S7W 17.16'
5261.52 SECTION CORNER
- 1871 COLLINS. REMONUMENTATION FIELD NOTES
PG 177 NORTH BETWEEN 28 & 29 VARIATION 7-15
- 2640 INTERSECT 1/4 LINE 11.22' WEST OF CORNER SET 1/4 STONE BY STUMP OF WITNESS TREE. CORRECTED VARIATION 7-30
CONTINUED NORTH VARIATION 6-45
- 5281.32 INTERSECT SECTION LINE 8.58' WEST OF CORNER. SET STONE FOR CORNER OF 20,21,28,29 IN PLACE OF GATE POST BY STUMP OF WITNESS TREE. CORRECTED VARIATION 6-57
PG 187 EAST BETWEEN 29 & 32 VARIATION 7-30
- 2686.2 INTERSECT 1/4 LINE 3.3' NORTH OF CORNER SET 1/4 STONE BY STUMPS OF WITNESS TREES CORRECTED VARIATION 7-34
CONTINUED EAST VARIATION 7-30
- 5350.62 SECTION CORNER
PG 176 EAST BETWEEN 28 & 33 VARIATION 3-30
- 2647.26 INTERSECT 1/4 LINE 5.28' SOUTH OF CORNER SET 1/4 STONE BY STUMP OF WITNESS TREE. CORRECTED VARIATION 3-23
CONTINUED EAST VARIATION 3-30
- 5269.44 SECTION CORNER

Donald Barnes
6-29-01

2748.24 INTERSECT 1/4 LINE 11.22' WEST OF CORNER WEST OF CORNER SET 1/4 STONE BY STUMP OF WITNESS TREE. CORRECTED VARIATION 5-15

CONTINUED NORTH VARIATION 5-15

5507.04 INTERSECT SECTION LINE 28.38' WEST OF CORNER SET STONE FOR CORNER OF 28,29,32, & 33 BY WITNESS TREE & STUMP. CORRECTED VARIATION 5-52

1959 BATTERMAN VOL 4 PG 27 REFERENCED CORNER BUT STATES NOTHING ABOUT IT. SKETCH SHOWS 4' EAST OF EAST PVMT EDGE & ON LINE WITH CENTER E/W RD

1973 LEE CSM 3 PG 251 2684.28 TO S 1/4 COR SEC 29

1973 LEE #4262 ANGLE OF 90-24-08 @ E 1/4 COR SEC 29 FROM SE TO W 1/4 COR SEC 29 & 1318.38 FROM E 1/4 COR SEC 29 SOUTH TO 1/16 TH COR

1979 THOM #3260 2755.62 E 1/4 COR SEC 32

1980 TOWNSEND CSM 10 PG 63 2683.95 TO S 1/4 COR SEC 29

1981 TOWNSEND CSM 10 PG 224 2755.62 TO E 1/4 COR SEC 32

1989 COMBS #1389 2636.76 TO E 1/4 COR SEC 29

1989 LEE #12372 1342.12 WEST TO 1/16TH COR

1998 HOULE #8195 2684.16 TO N 1/4 COR SEC 32

FD 2" PIPE BY CARSONITE. EAST OF EAST EDGE OF PVMT BY SIGN. FD SPLIT L.S. WITH A PIPE IN THE MIDDLE OF THE L.S. DROVE PIPE & DROVE 1/2X24" REROD IN PIPE. SET DISK ON TOP OF REROD

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FOUND PERPETUATED LOCATION.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

seal

SHEET 2 OF 2

emboss

CORNER CODE V-9

Donald Barnes
June 29 01

A-E 7.08 REQUIREMENT