

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:
T. 4N. R. 14E. 4th P.M.
CORNER CODE INDEX

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT
REV 10/23/2004 USMONREC.DWG

PORTER TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	A
B		6				5				4				3				2			1					B
C																										C
D																										D
E																										E
F																										F
G																										G
H																										H
J																										J
K																										K
L																										L
M																										M
N																										N
O																										O
P																										P
Q																										Q
R																										R
S																										S
T																										T
U																										U
V																										V
W																										W
X																										X
Y																										Y
Z																										Z

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

◆ CORNER MONUMENT

○ WITNESS MONUMENT

BEARINGS ARE BASED ON: -----

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 1

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE A-23

PO512 N1/4CORSEC1

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 BRINK & MULLETT (SEP) T5N R11E WEST ON SOUTH SIDE SECTION 36 VAR 9-23

2640.0 SET QUARTER SECTION POST BUR OAK 10 N67W 11.22'; BUR OAK 14 N25E 38.94'

3168.0 BUR OAK 12 IN DIAMETER

4224.0 ENTER MARSH

4488.0 LEAVE MARSH

5280.0 SET POST CORNER SECTION 35 & 36 WHITE OAK 14 N79W 25.08'; BLACK OAK 16 N23E 84.48' LAND SECOND RATE FIRST 1/2 ROLLING LAST 1/2 LEVEL TIMBERED BLACK WHITE AND BUR OAK

1833 ORIG GOV PLAT NW COR SEC 1 PORTER TWP IS 32.34' EAST OF SW COR SEC 35 DUNKIRK TWP.

1847 PORTER BK 1 PG 2 BEGINNING AT THE 1/4 POST ON THE NORTH LINE OF SEC 1 T4N R11E; THENCE SOUTH ON THE CENTER LINE OF SAID SEC 5280.0 TO 1/4 POST ON NORTH LINE OF SEC 12 OF SAID TOWN AND RANGE; THENCE SOUTH ON THE CENTER LINE OF SEC 12 2861.1 TO STAKE ON TERRITORIAL ROAD LEADING FROM JANESVILLE TO MADISON AND THE WHOLE LENGTH OF THE ROAD IS ONE AND HALF MILES AND 221.1'. COURSES GIVEN ACCORDING TO THE TRUE MERIDIAN VARIATION OF NEEDLE 7 3/4. WE HEREBY CERTIFY THAT THE ABOVE RD WAS LAID AND SURVEYED ACCORDING TO OUR ORDERS AND DIRECTION, JULY 12 1847.

1874 RUGER VOL 2 PG 128 EST. COR. FOM SEC CORS. SET STAKE & SURROUNDED IT BY 4 HH STONES. S 1/4 COR SEC 36 T5N R11E FD LIMESTONE ON CORNER ALSO FD WHERE STUMPS OF BT HAD BEEN DUG UP. S 1/4 COR IS 36.96' WEST OF N 1/4 COR SEC 1. VAR 8-18' 2646.60 TO NE COR SEC 1, VAR 8-18 2646.60 TO NW COR SEC 1, N/S 1/4 LINE IS VAR 8-23. N 1/4 COR USED TO SUBDIVIDE SEC 1.

1880 ?? VOL 6 PG 331 THE FOLLOWING ROAD RECORD INFORMATION IS FROM A BOOK THAT IS IN THE COUNTY CLERK'S VAULT. THE RECORDS ARE FROM 1840-1888. SOME OR ALL OF THE ROADS MAY NOT BE USED. THE BEARINGS AND DISTANCES OF THE CENTER LINE ARE RECORDED AS SURVEYED. N 1/4 COR SEC 1 IS 727.32' EAST OF THE CENTER OF THE RD

CORNER IS IN THE MIDDLE OF A PLOWED FIELD. THERE IS NO VISIABLE FENCE LINE.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

DURING THE LAST THREE YEARS I WAS UNABLE TO REACH THE CORNER DUE TO PLANTING, WET CONDITIONS, AND GENERAL PROJECT DEMANDS. THE CORNER WAS NOT ESTABLISHED. THE MONUMENTS NEED TO BE SEARCHED FOR.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

YES. IN 1874 RUGER VOL 2 PG 128 DECLARED IT LOST & ESTABLISHED THE CORNER.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Donald Barnes
Apr 28, 2010