Paper weight-110# (minimum)

Black nonfading ink required

U.S. **PUBLIC** LAND SURVEY MONUMENT RECORD

T. \(\psi_N \)	R// RNER COD 9 10 11 12 13 14	E. 4th P.M E INDEX	•	ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT REV 10/23/2004 USMONREC.DWG TWP ROCK COUNTY WI IF AVAILABLE ROCK COUNTY COORDINATES PERFERRED North Elev.
K L M N O P Q R S T U V W X Y			K L M N O P Q R S T U V W X Y	Hor. Datum Vert. Datum LATITUDE ELLIPS. HT LONGITUDE NAD83(91) NETWORK ADJ. YR GPS (X) TRAVERSE (X)
LOCATION ON AI	T SYMBOL 📤	15 16 17 18 19 20 21 AT PROPER	Z 22 23 24 25	BASED ON THE FOLLOWING CONTROL: VITNESS MONUMENT

FIELD BOOK PAGE #

BEARINGS ARE BASED ON:_

SHEET

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE

P0535

E1/4CORSEC7

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

TAN RIIE 4TH MER. NORTH 1833 HARRISON (NOV) BET. 7 & 8

QUARTER SEC COR (SET POST & RAISED A 2640.0 MOUND OF EARTH & SOD

5280.0 SET POST FOR COR TO SECS 5,6,7,8 MARKED POST & RAISED MOUND OF EARTH

& 80D

LAND 1ST RATE ROLLING PRAIRIE SOIL GOOD, GROWTH GRASS & WEEDS

1870 RUGER VOL 2 PG 25 FD STONE AT COR. USED TO SUBDIVIDE SEC 8

BLEEDORN VOL 2 PG 465 FD LARGE FLAT HH AT COR. THE 1892 SIDES FACING E & W, VAR 5-57 1308.05 TO N 1/16TH COR OF SW 1/4 SEC 8, 2664.09 TO SW COR SEC 8

BARNES G-5 FD 3 1/2X16X40 FLAT HARDHEAD WITH POINT 1984 UP. FLATSIDES FACED EAST & WEST. THE STONE WAS TOO HEAVY TO REPLACE. SET PIPE HORIZONTALLY ON SOUTH SIDE. SET CARSONITE POST & REFERENCED SAME. SW SIDE OF FENCE FENCE INTERSECTION.

1984 COMBS CSM VOL 11 PG 620 FD STONE. USED TO SUBIDIVIDE SEC 8. SET R/R @ CENTER OF SEC 8.

BARNES VOL 6 PG 360 FB#2 PG 50 FD HH OF REC. 80-41-1986 30W 2664.65 TO SE COR SEC 7

BARNES VOL 6 PG 387 NOO-38-41E 2663.14 TO NE COR 1988 SEC 7, SOO-41-30W 2664.65 TO SE COR SEC 7,

1988 BARNES J-5 800-41-30W 2664.65 TO SW COR SEC 8.

KARNS CSM VOL 16 PG 478 STATES NOTHING ABOUT MON. 1993 5305.91 TO E 1/4 COR SEC 8.

1995 SCHROEDER CSM VOL 18 PG 437 STATES NOTHING ABOUT MON. N89-49-10E TO CENER OF SEC 8, NORTH FROM CENTER TO N 1/4 COR SEC 8

USED 1988 OBSERVATIONS TO HH. & ACCEPTED REFERENCE TIES.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED HH

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above. NO

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Emboss

SHEET 1 OF #

CORNER CODE

A.E. 7.08 REQUIREMENT