## U.S. PUBLIC LAND SURVEY MONUMENT RECORD

	WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT  REV 10/23/2004 USMONREC.DWG
T. $\stackrel{\swarrow}{\sim}$ N. R. $\stackrel{\cancel{1}}{\sim}$ E. 4th P.N. CORNER CODE INDEX	
2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20	21 22 23 24 25 <sub>A</sub> FULTON TWP
6 5 4 3 7	ROCK COUNTY WI
	D IF AVAILABLE ROCK COUNTY COORDINATES PERFERRED
1 8 9 10 1	F G
	H North Elev
4 1 16 15 1	K East
	M N Hor. Datum Vert. Datum
29 20 27 27 23	O P I ATITUDE
	Q LATITUDE ELLIPS. H
39 39 38 31 36	S LONGITUDE
	v NAD83(91)NETWORK ADJ. YR
3) 3) 33 4 34 35	W X GPS (X) TRAVERSE (X)
	Y PASED ON THE FOLLOWING CONTROL
2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX	21 22 23 24 25
♦ CORNER MONUMENT	O WITNESS MONUMENT
)	
;   	
,	
	· ***

PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH. PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE \_\_\_

X-13

## FU617^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1836 (AUG) BURNHAM NORTH BETWEEN SECTIONS 33 & 34

YELLOW DAK 18 IN DI 1225.62

SET 1/4 SEC POST BUR DAK 24 S30W 25.74' BUR 2640 DAK 10 N6? 1/2E 16.5'

NO STATIONS

5280 SET POST COR TO 27,28,33,&34 BUR OAK 12 531 1/2W 39.6' BUR OAK 12 N3W 11.88' FIRST RATE BUR DAK OPENINGS

- 1870 RUGER VOL 2 PG 27 FD SOUTH BEARING TREE & STUMPS OF NORTH BEARING TREE. SET STAKE & SURROUNDED IT WITH 4 HARD HEAD STONES. VAR 7-46 2637.03 TO CEN SEC 33, 5270.76 TO W 1/4 COR SEC 33
- 1877 RUGER VOL 2 PG 229 COR SES BY SELF SEE SEC 33 PG 20 VAR 6-30 2638.02 TO CEN SEC 34
- BARNES VOL 5 PG 405 DUG & FD NOTHING., SET ON LINE 1978 WITH THE CENTER & THE N 1/16TH COR OF THE SE 1/4 OF SEC 33. SET ALUM. MON. & REF. SAME.
- 1978 NORTHROP CSM VOL 8 PG 14 ALUM MON. BEARINGS ARE REFERENCED TO TRUE NORTH BY SOLAR OBSERVATIONS MADE ON JUNE 21, 1978. N89-49-13E 2637.26 TO CEN OF SEC 34, N89-49-13E 5310.79 TO E 1/4 COR SEC 34, S00-06-41E 264B.25 TO SW COR SEC 34.
- 1978 NORTHROP VOL 5 PG 443 FD ALUM. MON. 2648.25 TO SW COR SEC 34 & 2637.26 TO CEN OF SEC 34, & 5310.79 TO E 1/4 COR SEC 34
- 1985 BARNES VOL 6 PG 344 SHOWS RECORD DISTANCES.
- 1999 COMBS #7548 ALUM. 510.76 TO E 1/4 COR SEC 34, 2636.95 TO CEN SEC 34

FD ALUM, MON & REFERENCE PIPES. SET CARSONITE POST NEXT TO MDN.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD ALUM. MON.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

NONE

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Verde Emboss Eures 1/19/07

SHEET 1 OF 2

CORNER CODE X-13

A.E. 7.08 REQUIREMENT

