Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

T. \angle N. R. \angle E. 4th P.M. CORNER CODE INDEX	WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT REV 10/23/2004 USMONREC.DWG TWP
A 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 2 B C D E F G H J	ROCK COUNTY WI C
K L B A A A A A A A A A A A A A A A A A A	K East L M N Hor. Datum Vert. Datum O P Q LATITUDE ELLIPS. HT
S T U V V V X Y Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z	Y RASED ON THE FOLLOWING CONTROL.
1 2 3 4 5 6 7 8 9 10 11 12 13 14 \$5 16 17 18 19 20 21 22 23 2 PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX CORNER MONUMENT (a)	

BEARINGS ARE BASED ON:

		,		
FIELD BOOK PAGE #	SHEET		OF	\leq
SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND S	URROUN	DING		
PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.				
PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982				

FU628^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1835 (JAN7) MULLETT& BRINK WEST ON SOUTH SIDE OF

SECTION 34

2640 SET 1/4 SECTION POST BUR OAK 12 N35W

69.3' BUR OAK 14 N34E 23.1'

4436.52 BUR DAK 10

5280 SET POST COR SECTIONS 33 & 34 B. OAK 7 N56W 23.76' B. OAK 16 N46E 44.22' LAND

GENTLY ROLLING 2ND RATE W. B. & BUR DAK

1871 TWP RD JV2 PG 50 BEGINNING AT THE SE CORNER OF THE SW 1/4 OF SEC 34 IN SAID TOWN OF FULTON, RUNNING THENCE EASTERLY ON OR NEAR THE LINE BETWEEN SAID TOWNS OF FULTON AND JANESVILLE AND ON OR NEAR THE LINE BETWEEN THE LANDS OF ROBERT WILEY ON THE NORTH AND FRANCIS PENNYCOOK ON THE SOUTH TO THE SE COR OF THE SW 1/4 OF SAID SEC 34 IN THE TOWN OF FULTON

- 1871 TWP RD BK 1 PG 50 BEGINNING AT THE SOUTH EAST COR OF THE SW ¼ OF THE SW ¼ OF SEC 34 IN SAID TOWN OF FULTON RUNNING EASTERLY ON OR NEAR THE LINE BETWEEN SAID TOWNS OF FULTON AND JANESVILLE AND ON OR NEAR THE LINE BETWEEN THE LANDS OF ROBERT WILEY ON THE NORTH AND FANCIS PENNYCOOK ON THE SOUTH, TO THE SOUTH EAST CORNER OF THE SW ¼ OF SEC 34,
- 1875 RUGER VOL 2 PG 189 FD OLD FENCE POST HOLE AT COR ALSO FD WHERE STUMPS OF BTS HAD BEEN DUG OUT.SET HH STONE 27X20X13 2682.9 TO SE COR SEC 34. VAR 5-33 ALONG N/S 1/4 LINE SEC 34
- 1877 RUGER VOL 2 PG 229 COR EST. BY SELF SEE SEC 34 PG 144 VAR 6-00 ALONG N/S 1/4 LINE SEC 34
- 1878 RUGER VOL 2 PG 240 HH STONE 27X2X3 @ N $\frac{1}{4}$ COR SEC 3, VAR 7-24 2596.77 FROM N $\frac{1}{4}$ TO NW CORNERS SEC 3, VAR 7-09 2881.56 TO CEN SEC 3, & VAR 7-09 5526.51 TO FROM N $\frac{1}{4}$ COR TO S $\frac{1}{4}$ COR SEC 3 JANESVILLE TWP.
- 1978 NORTHROP VOL 5 PG 443 2676.12 TO SE COR SEC 34, 2603.30 TO SW COR SEC 34, 2643.98 TO CEN SEC 34, & 5296.81' TO N $\frac{1}{4}$ COR SEC 34.
- 1978 BARNES VOL 5 PG 445 DUG & FD NOTHING. SET ALUM. MON ON LINE WITH S 1/16TH COR OF THE SW 1/4 SEC 34 & THE SE COR SEC 34 AND AT THE INTERSECTION OF N 1/4 COR AND THE CENTER OF SEC 34. THIS IS IN HARMONY WITH OCCUPATION AND RECORD DISTANCE TO THE SOUTH AND WEST. THE CORNER IS ON LINE WITH THE FENCE TO THE NORTH, THE SOUTH EDGE OF THE ROAD TO THE WEST, THE CENTER OF THE RD TO THE SOUTH, AND 4 SOUTH OF THE FENCE TO THE EAST. REF. SAME.
- 1978 NORTHROP CSM VOL 8 PG 14 ALUM. MON. BEARINGS ARE REFERENCED TO TRUE NORTH BY SOLAR OBSERVATIONS MADE ON JUNE 21, 1978. NO-37-28E 2643.98 TO CEN SEC 34, N89-48-37E 2676.10 TO SE COR SEC 34, S89-48-37W 1301.21 TO IRON STAKE FROM A B.J. SUNNY SURVEY MADE IN 1958, S89-37-52W 1302.11 FROM 1/16TH COR TO SW COR SEC 34. NO2-28-49W 2652.83 FROM CEN SEC 34 TO N 1/4 COR SEC 34
- 1987 BARNES A-15 ALUM & REF @ N 1/4 COR SEC 3. 278,407.02; 2,251,678.00 NAD27
- 1999 KREBS CSM VOL 23 PG 20 ALUM. 2676.22 TO SE COR SEC 34.
- 1999 COMBS #7548 ALUM. 5296.99 TO S $\frac{1}{4}$ COR SEC 27 & ANGLE 89-08-20 @ S $\frac{1}{4}$ COR SEC 27 FROM S $\frac{1}{4}$ COR SEC 34 TO SW COR SEC 27

SHEET 1 DF & Z

CORNER CODE **Z-15**

Devel Boenes 12/11/07

FU628

FD	ALIIM	MIN	& D	FFFD	FNCE	PIPES
Γ	$\mathbf{A} \perp \mathbf{U} \mathbf{W}$.	IVI LI IVI .	α	-	F 1311.F	

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD MON.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.
- I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Emboss

SHEET 2 OF 2

12/1/07

CORNER CODE **Z-15**

A.E. 7.08 REQUIREMENT