

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4 N. R. 12 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

CORNER CODE INDEX

FULTON

TWP

ROCK COUNTY WI

IF AVAILABLE

ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25		
A																											A
B																											B
C																											C
D																											D
E																											E
F																											F
G																											G
H																											H
J																											J
K																											K
L																											L
M																											M
N																											N
O																											O
P																											P
Q																											Q
R																											R
S																											S
T																											T
U																											U
V																											V
W																											W
X																											X
Y																											Y
Z																											Z

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON: _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 3

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE T-1

FU594 ^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 (SEP) MULLETT & BRINK NORTH ON EAST SIDE SECTION 25
T4N R11E 4TH MERIDIAN MT.

2640 SET QUARTER SECTION POST BUR OAK 6 N34W
82.5' WHITE OAK 12 N31E 126.72
2772 LEAVE PRAIRIE AND ENTER WOODLAND
5280 SET POST CORNER SECTIONS 24 & 25
BUR OAK 10 S35W 135.3' BUR OAK 10 N76E
168.3'
LAND ROLLING SECOND RATE LAST HALF THINLY
TIMBERED WITH WHITE BLACK & BUR OAK ELM AND
WHITE MAPLE THE REST PRAIRIE

1854 TWP RD REC PORTER TWP BK 1 PG 6 BEGINNING AT THE 1/4
POST ON THE WEST LINE OF SEC 19 T4N R12E [STH 184];
THENCE RUNNING SOUTH ON THE SECTION LINE 1337.82';
THENCE EAST 446.82'; THENCE S18 1/2E 396'; THENCE S3W
264' TO RED OAK TREE; THENCE S17 3/4W 264' TO BURR OAK;
THENCE S1E 764.94'; THENCE S11W 502.92' TO BURR OAK
TREE; THENCE S6 3/4W 326.04'; THENCE S17E 1158.3';
THENCE S30 3/4W 741.84'; THENCE S41 3/4W 1247.4' TO THE
WEST LINE OF T4N R12E (THENCE SOUTH ON THE TOWN LINE
766.92', THENCE S42 1/2W 924'; [SEC 30 FULTON] THENCE S3
1/4W ? CHAINS; THENCE S32 1/2E 1013.1' TO THE W. LINE OF
T4N R12E; THENCE S. ON THE TOWN LINE 4746.06' TO THE
SW COR OF SEC 31 OF T4N R12E)

1977 BARNES VOL 5 PG 264 & 265 SET ALUM. MON. DUG & FD
NOTHING. IF COR WAS DECLARED LOST AND SET ON A
STRAIGHT BETWEEN THE SE COR SEC 25 & THE E 1/4 COR SEC
24 AT SINGLE PROPORTIONATE DISTANCE, THE FOLLOWING
RELATIONSHIP WOULD EXIST. USED OCCUPATION BECAUSE
OF THE LARGE DISTANCE BETWEEN THE EXISTING CORNERS.
SHOWS MON 1.6' NORTH OF FENCE INT. & ON LINE WITH N/S
FENCE (WESTERLY FENCE TO THE SOUTH). THE LOST POSITION
IS 7' NORTH OF E/W FENCE & 12.9 EAST OF N/S FENCE. REF.
SAME. REFERENCED SAME. PORTER TWP FB #1 PG 52.

1977 BARNES VOL 5 PG 267 2650.1 TO SW COR SEC 30 & 2611.9'
TO NW COR SEC 30

1981 COMBS CSM VOL 10 PG 410 E 1/4 COR SEC 25 PORTER TWP
ALUM. ANGLE 89-33-00 @ SE COR SEC 25 FROM S 1/4 COR SEC
25 TO E 1/4 COR SEC 25

1982 WIDOT VOL 6 PG 240 & 271 & #6625, 11544, 11545, 11546
FOLLOWING INFORMATION WAS COPIED FROM STH PLANS
PROJECT #5972-01-22 SHEET 4.2 ALUM. MON 285,999.98;
2,233,285.31

1982 WIDOT #11544 PROJECT 5972-01-22 SHEET 4.2 CALLS FOR
ALUM MON & NAD27 COORDINATES OF N/S 285,999.98';
2,233,285.31'. INVERSE OF S00-52-20E 2649.94' TO SW
COR SEC 30.

1983 BARNES R-1 2650.37 TO SW COR SEC 19

2000 RIESOP CSM VOL 23 PG 340 E 1/4 COR SEC 25 ALUM. 2649.89
TO SE COR SEC 25 PORTER TWP

SHEET 1 OF 3
CORNER CODE T-1

Donald Barnes
11/14/07

FU594

FD ALUM. MON. & REF. PIPES. SET CARSONITE POST ON SW SIDE OF MON.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD MON.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

NONE

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

NO

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief

Donald
Barnes

Emboss

11/14/07

SHEET 2 OF 3

CORNER CODE **T-1**

A.E. 7.08 REQUIREMENT

W 1/4 COR
 SEC 30
 FULTON TWP
 T4N R12E
 VERTICAL DATUM BASED
 ON DTM MAPS WITH
 W 1/4 COR AS
 848.4

- FD 1" PIPE
- FD ALUM. MON SET CARSONITE ON SW SIDE OF MON.

SHEET 3 OF 3
 EMBOSSED SEAL

Renal Bauney
 11/14/07

