

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4 N. R. 12 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

CORNER CODE INDEX

| | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|----|---|---|---|---|----|---|---|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|---|
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | |
| A | | | | | | | | | | | | | | | | | | | | | | | | | A |
| B | 6 | | | | | 5 | | | | | | | | | | | | | | | | | | | B |
| C | | | | | | | | | | | | | | | | | | | | | | | | | C |
| D | | | | | | | | | | | | | | | | | | | | | | | | | D |
| E | | | | | | | | | | | | | | | | | | | | | | | | | E |
| F | | | | | | | | | | | | | | | | | | | | | | | | | F |
| G | 7 | | | | | 8 | | | | | | | | | | | | | | | | | | | G |
| H | | | | | | | | | | | | | | | | | | | | | | | | | H |
| J | | | | | | | | | | | | | | | | | | | | | | | | | J |
| K | | | | | | | | | | | | | | | | | | | | | | | | | K |
| L | 18 | | | | | 17 | | | | | | | | | | | | | | | | | | | L |
| M | | | | | | | | | | | | | | | | | | | | | | | | | M |
| N | | | | | | | | | | | | | | | | | | | | | | | | | N |
| O | | | | | | | | | | | | | | | | | | | | | | | | | O |
| P | 19 | | | | | 20 | | | | | | | | | | | | | | | | | | | P |
| Q | | | | | | | | | | | | | | | | | | | | | | | | | Q |
| R | | | | | | | | | | | | | | | | | | | | | | | | | R |
| S | | | | | | | | | | | | | | | | | | | | | | | | | S |
| T | 30 | | | | | 29 | | | | | | | | | | | | | | | | | | | T |
| U | | | | | | | | | | | | | | | | | | | | | | | | | U |
| V | | | | | | | | | | | | | | | | | | | | | | | | | V |
| W | | | | | | | | | | | | | | | | | | | | | | | | | W |
| X | 31 | | | | | 32 | | | | | | | | | | | | | | | | | | | X |
| Y | | | | | | | | | | | | | | | | | | | | | | | | | Y |
| Z | | | | | | | | | | | | | | | | | | | | | | | | | Z |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | |

FULTON TWP

ROCK COUNTY WI

IF AVAILABLE

ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

BEARINGS ARE BASED ON: _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 4

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE J-25

FU553 ^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 BURNHAM & BRINK (OCT 17) SOUTH ON EAST SIDE SECTION
12 4N R12

627 ROCK RIVER 396' @ SW SET POST ON RIGHT BANK
WHITE OAK 10 N18 1/2W 102.3' BLACK OAK 10 N56E
129.36' LAND & SAME AS LAST MILE
OCT 17TH 1833

1836 BRINK NORTH ON EAST SIDE SECTION 13 T4N 12E TH
MERIDIAN

2640 SET QUARTER SECTION POST BUR OAK 10 S89W
29.04'

4270.2 BLACK OAK 16 IN DIAMETER

5280 SET POST CORNER SECTIONS 12 & 13 WHITE OAK
20 S46W 50.16' BUR OAK 11 N16W 48.18' LAND &
SAME

1836 BRINK NORTH EAST SIDE SECTION 12 4N 12E

1358.28 BLACK OAK 18 IN DIAMETER

2640 SET QUARTER SECTION POST BUR OAK 30 S22W
87.78' WHITE OAK 7 N37W 60.06'

3102 ARMY TRAIL @ NE

3747.48 INTERSECT LEFT BANK OF ROCK RIVER SET POST
BUR OAK 16 S3W 505.56' BUR OAK 18 S17E 600.6'
LAND & G SAME RIVER 907.5' WIDE RUNNING
SOUTH WEST

1836 JULY BURNHAM EAST RANDOM BET SECS 12 & 13

2211 TRAIL @N.E.

5313 INT. EAST BOUNDY 26.4' NORTH
FIRST RATE W.Y. & BUR OAK OPENINGS
WEST CORRECTED BETWEEN 13 & 12

2656.5 SET 1/4 SEC POST BUR O. 10 S60W 34.98', BU O. 12
N5W 29.7'
?????? YELLOW OAK 14 IN. DIA.

5213 TO CORNERS

1836 HARRISON JULY 8 WEST RANDOM BETWEEN SEC 7 & 18

5051.64 INT. RANGE LINE 33' NORTH BUR OAK 12 S64E
25.74' BUR OAK 8 N53E 96.36

? BUR OAK OPEINING

EAST CORRECTED BETWEEN 18 & 7
NO STATIONS

2411.64 SET 1/4 SEC POST YELLOW OAK 8 S33 1/2 E 31.68'?
NO OTHER BEARING

4209.28 BUR OAK 14 IN DIA

5051.64 TO CORNER

1843 ALLEN TWP RD BK 1 PG 1 BEGINNING ON THE RANGE LINE
BETWEEN 12 & 7, 6.6' SOUTH OF A BURR OAK TREE
STANDING ON SEC 7 MARKED HS SOME 495' SOUTH OF ROCK
RIVER, THENCE BOUNDING ON SAID RANGE LINE S7 1/2E
3000.36' TO THE SEC CORNERS OF 7,12,13,&18, THENCE
S32W 1204.5' TO AN ANGLE STAKE, THENCE S22E 660,
THENCE S49E 844.8' INTERSECTING THE RANGE LINE
BETWEEN SEC 13 & 18, THENCE BOUNDING S7 1/2E ON THE
AFORESAID RANGE LINE 18,905.7' TO THE SOUTH LINE OF
THE AFORESAID TOWNSHIP. WHOLE DISTANCE ??MILES

1871 (AUG23) RUGER MILTON TWP REMON. PG 281 NORTH ON
WEST LINE OF SW 1/4 OF SEC 18 ON A VAR 6-20 AT

2650.56 INTERSECTED 1/4 LINE 6.60' WEST OF 1/4 COR. FOUND
OLD STAKE AT COR. ALSO FOUND STUMP OF S.W.;
BEARING TREE & WHERE STUMP OF N.W. BEARING
TREE HAD BEEN DUG UP. COR VAR 6-11

1871 (SEP8) RUGER MILTON TWP REMON. PG 314 NORTH ON WEST
LINE OF NW 1/4 OF SEC 18 ON A VAR 6-05 OFFSET

WEST 19.80' OFFSET EAST 19.8' AT

Donald Barnes
9-25-07

SHEET 1 OF 4
CORNER CODE J-25

FU553

2609.64 INTERSECTED NORTH BOUNDARY LINE 3.30' EAST OF COR. COR VAR 6-09

PG 313 WEST ON NORTH LINE OF NE 1/4 OF SEC 18 ON A VAR 4-25 OFFSET NORTH 9.90' OFFSET SOUTH 19.80' AT

2647.26 INTERSECTED 1/4 LINE 16.50' SOUTH OF 1/4 COR FOUND OLD STAKE AT COR ALSO FOUND STUMP OF BEARING TREE COR VAR 4-17

PG 313 WEST ON NORTH LINE OF NW 1/4 OF SEC 18, ON A VAR 4-20 OFFSET SOUTH 13.20' AT

2401.08 INTERSECTED WEST BOUNDARY LINE 19.80' SOUTH OF COR. FOUND OLD STAKE AT COR. ALSO FOUND NE & NW & SW BEARING TREES & STUMB OF SE BEARING TREE COR VAR 4-11

PG 314 NORTH ON WEST LINE OF SW 1/4 OF SEC 7 ON A VAR 6-05 OFFSET WEST 6.60' OFFSET WEST 6.60' OFFSET EAST 9.90' AT

2638.35 INTERSECTED 1/4 LINE 3.30' EAST OF 1/4 COR FOUND STUMP OF SW BEARING TREE. ALSO FD WHERE STUMP OF NW BEARING TREE HAD BEEN DUG UP. ESTABLISHED 1/4 COR. FROM THEM. COR VAR 6-13 PLACED 6"X6" CUT LIMESTONE

1911 KERCH VOL 3 PG 65 MON. 2641.1 TO E 1/4 COR SEC 12, 457.8 EASTERLY TO GAS PIPE 2" DIA. ANGLE @ E 1/4 COR SEC 12 FROM MP TO SE COR SEC 12 IS 180-24, & ANGLE @ SE COR SEC 12 FROM E 1/4 COR SEC 12 TO SET GAS PIPE IS 92-21-30

1963 DOT #13510 & 13511 I-90 NOTE: BEARING SHOWN ON PLAT ARE THE AVERAGE TRUE BEARINGS OF EACH TANGENT TO THE NEAREST MINUTE. NOTHING WAS STATED ABOUT THE TYPE OF MON. FD. 2634' EAST OF CENTER OF I-90

1971 LEE VOL 4 PG 538 FD CUT STONE AT INT. OF FENCES.

1979 COMBS #1182 SET PIPE @ S 1/16TH COR OF SE 1/4 SEC 12. @ SE COR SEC 12 (CUT STONE) THENCE S88-27-20W 1336.25 TO 1/16TH COR. @ SE COR SEC 12 THENCE N00-02-30W 2641.73 TO E 1/4 COR SEC 12.

1979 WOODMAN CSM VOL 9 PG 21 FD SQUARE STONE.

1979 WOODMAN CSM VOL 9 PG 53 FD STONE 2671.98 TO N 1/4 COR SEC 13 2611.57 TO E 1/4 COR SEC 13, ANGLE 89-04-16 FROM E 1/4 COR SEC 13 TO N 1/4 COR SEC 13

1980 COMBS CSM VOL 10 PG 96 STATES NOTHING ABOUT MON.

1980 COMBS #6547 CUT STONE. 2641.73 TO E 1/4 COR SEC 12, 1338.62 TO N 1/16TH COR OF NE 1/4 OF SEC 12, & ANGLE 91-08-50 @ SE COR SEC 12 FROM S 1/16TH COR OF SE 1/4 OF SEC 12 TO E 1/4 COR SEC 12, S87-21-34E 2418.86 TO S 1/4 COR SEC 7 MILTON TWP

1982 BARNES J-1 FD CUT LIMESTONE AT INT. OF FENCE LINE FLUSH WITH GROUND. SET CARSONITE.

1983 BARNES J-1(1) FD CUT L.S. & REFERENCED SAME.

1992 COMBS CSM VOL 18 PG 155 FD L.S. 2671.98 TO N 1/4 COR SEC 13

1995 LATHROP CSM VOL 18 PG 359 CUT STONE 2641.73 TO E 1/4 COR SEC 12

2005 COMBS CSM VOL 29 PG 182 FD CUT STONE. 2672.08 TO FD ALUM @ N 1/4 COR SEC 13

SHEET 2 OF 4

CORNER CODE J-25

9-25-07
Daniel Barnes

FU553

FD CUT LIMESTONE, CARSONITE POST, & REFERENCE PIPES. I ALSO FD A 6"X5" LS (UNRECORDED) S88-17-17E 757.51 & A PIPE ABOUT 457.8 TO THE EAST. THE ANGLE FROM THE E ¼ COR SEC 12 TO THE S ¼ COR OF SEC 7 SUPPORTS THE POSITION OF THE CUT LIMESTONE AS FOUND BY KERCH IN 1911. SINCE THE BEFORE MENTIONED FD PIPE IS IN THE CONCRETE @ THE SOUTH FACE OF THE FENCE POST, IT PROBABLE IS NOT IN THE EXACT POSITION THAT KERCH PLACED HIS PIPE.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD L.S. IT IS IN HARMONY WITH THE FD PIPE & LS FOUND 458' TO THE EAST & THE RECORD ANGLES.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

9-25-07
Donald Barnes
Emboss

SHEET 3 OF 4

CORNER CODE **J-25**

A.E. 7.08 REQUIREMENT

