Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In: T. \(\frac{1}{2} \) R. \(\frac{1}{2} \) E. 4th P.M. CORNER CODE INDEX	REV 10/23/2004 USMONREC.DWG
A	ROCK COUNTY WI
T U V X Y Z 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX CORNER MONUMENT (a)	V NAD83(91)NETWORK ADJ. YR

BEARINGS ARE BASED ON:_____

,					
EIELD BOOK	OTTER TO	/	0.5	2	
FIELD BOOK PAGE #	SHEET		OF		
SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND S	URROUN	DING			
PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.			,		
PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982			4.	,	1

FU538^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1834 (MAR/APR) HARRISON NORTH BETWEEN SECS 10 & 11

1412.4 W.O. 18

2254.56 W.O. 18

QUARTER SEC COR. {WO 18 S31E 62.7' W.O. 20 N55W 33' WO. 18 WO 20}

4127.64 WD. 18

4418.04 WO 12

5280 COR TO SECS 2,3,10,11

{W.O. 14 S88W 56.1' W.O. 12 N54W 31.02' W.O. 14 N65E 93.72' W.O. 12 S46E 129.36'

LAND MODERATELY LEVEL 2^{ND} RATE WITH A FEW BODY OF W.O. TIMBER.

- 18?? RUGER "BLEYTHING'S ADDITION TO EDGERTON" {UNRECORDED}

 #3133 SUB STAKE SURROUNDED BY 4 HH, 2632.96 TO NE COR

 SEC 10, 2618.55 TO CENTER SEC 10. ON EAST R/W LINE OF

 HIGHWAY ST
- 1886 TWP RD BK 2 PG 3 BEGINNING AT A POINT 1320' SOUTH OF THE NE COR OF NE 1/4 OF SEC 10 AND RUNNING THENCE SOUTH ON THE SEC LINES BETWEEN 10 & 11 AND 14 &15 TO THE ROCK RIVER; ALSO A STRIP OF LAND 4' WIDE COMMENCING AT THE NE COR OF N 1/2 OF NE 1/4 OF SEC 15 AND RUNNING SOUTH 330', THE SAME BEING AN ACCURATE SURVEY OF SAID HIGHWAY CAUSED BY US TO BE MADE. THE LINE OF SAID SURVEY IS THE CENTER OF SAID HIGHWAY AND THE SAME IS LAID OUT OF THE WIDTH 49.5'
- 1900 BROWN VOL 2 PG 515 & 1136 STAKE SURROUNDED BY 4 HH. 2684.09' TO CENTER OF SEC 10. @ THAT POINT CALLS FOR N/S HWY 49.5' WIDE
- 1958 SUNNY #3842 HAN'S ADD. STATES NOTHING ABOUT TYPE OF MON. @ CENTER OF RIVER RD & E/W RD.
- 1967 CARRINGTON "FIRST ADD. TO DAKHILL SUB" BK 23 PG 31 STATES NOTHING ABOUT MON. CALLS 51.45' EAST OF WEST R/W LINE OF RIVER RD. & IN WATTS SPRING RD.
- 1973 NORTHROP #2091 ASSESSORS PLAT OF EDGERTON OL 275 STATES NOTHING ABOUT MON. IS ALSO SE COR OF OL 275. 2633.70 TO NE COR SEC 10.
- 1973 LEE VOL 5 PG 43 FD 3 HH & LIMESTONE. REF. PKS 10'S & 10' W. SET C.I. MON. REFERENCED SAME. INT. OF PLEASANT VIEW & WATTS SPRING.
- 1976 WEIR CSM VOL 5 PG 339 ROCK COUNTY MON. N1-56-45E 2634.09 TO NE COR SEC 10
- 1977 WEIR BK 29 PG 7 HENDRICK BRASS MON. 302,355.47; 2,254,269.51
- 1978 SANDSNES VOL 5 PG 447 DATA PROVIDED BY ARDEN SANDSNES. SCALE FACTOR 0.99997971 302,355.474 N/S; 2,254,269.512 E/W; ELEV 867.09' NAD29
- 1978 SANDSNES #1119,6576 GROUND CONTROL FOR EDGERTON AIR PHOTO.
- 1979 WEIR BK 30 PG 23 "SUN VALLEY EAST" ALUM. ANGLE 92-42-02 @ NW COR SEC 11 FROM N $^{1}\!\!/_4$ COR SEC 11 TO W $^{1}\!\!/_4$ COR SEC 11
- 1979 SCHROEDER CSM VOL 8 PG 482 STATES NOTHING ABOUT MON.
- 1981 SANDSNES #7158 & 1125 S8-21-41W 2617.73 TO CEN SEC 10 & ANGLE 89-04-46 @ CEN SEC 10 FROM E 1/4 COR SEC 10 TO S 1/4 COR SEC 10
- 1981 NORTHROP CSM VOL 10 PG 434 1" PIPE IN VALUE BAOX 2643.06 TO NW COR SEC 11. NORTH 102.59 TO PIPE. NEAR INT. OF KLUG RD & CTH N.
- 1987 COMBS CSM VOL 13 PG 186 STATES NOTHING ABOUT MON. 472.76 SOUTH OF CENTER LINE STH 59
- 1988 SCHROEDER CSM VOL 13 PG 230 STATES NOTHING ABOUT MON. 1347.40 NORTH OF CENTER OF EDGEWOOD SHORES RD.
- 1988 BARNES VOL6 PG 377 IN VOL 6 PG 3 THE E $\frac{1}{4}$ COR OF SEC 10 SHOULD BE THE W $\frac{1}{4}$ COR OF SEC 10.
- 1988 BARNES G-17 FD C.I. MON. & REFERENCED IT.
- 1988 NORTHROP #11729 SUB FD C.I. 2617.90 TO 1 1/4' SOLID ROD

PAGE 1 OF 2

CORNER CODE G-17(3)

Dusl Barnes 11/04/07

FU538

- AT CEN SEC 10, 2633.94 TO NE COR SEC 10, & ANGLE 88-41-42 @ E $\frac{1}{4}$ COR SEC 10 FROM CEN SEC 10 TO NE COR SEC 10.
- 1990 COMBS #1864 CAST IRON MON.
- 1990 COMBS CSM VOL 14 PG 339 CI 2654.51 TO SE COR SEC 10
- 1990 NORTHROP #11906,11905,2480,&2481 FD CI. 2634.06 TO NE COR SEC 10.
- 1994 SARKO CSM VOL 17 PG 420 ALUM. 302,355.47; 2,254,269.51 2634.13 TO NE COR SEC 10
- 1995 SCHROEDER CSM VOL 18 PG 281STATES NOTHING ABOUT TYPE OF MON.
- 1995 RIESOP CSM VOL 18 PG 483 CI 2654.55 TO ALUM @ SE COR SEC 10
- 1996 FAVORITE CSM VOL 19 PG 435 CI 302,355.474; 2,254,269.512 2634.25 TO NE COR SEC 10
- 1997 THOUSAND G-17(1) I FOUND A IRON MON. DESIGNATED AS A ROCK COUNTY MONUMENT & REFERENCED SAME.
- 1999 BARNES G-17(2) I FOUND A C.I. MON & REFERENCED IT. ESTABLISHED ROCK COUNTY COORDINATES FROM GPS STATIONS. 321,146.77 N/S; 485,339.06 E/W
- 1999 LATHROP CSM VOL 22 PG 216 ALUM. 2655.92 TO SW COR SEC 11
- 2000 REISOP CSM VOL 23 PG 408 CI. 2654.55 TO SW COR SEC 11, 2617.66 TO PIPE @ CEN OF SEC 10, & ANGLE OF 91-17-08 @ E $\frac{1}{4}$ COR SEC 10 FROM SE COR TO CEN OF SEC 10
- 2001 COMBS CSM VOL 24 PG 116 C.I. 2655.92 TO SE COR SEC 10
- 2001 NORTHROP CSM VOL 24 PG 301 CAST IRON MON 2654.52 TO SW COR SEC 11
- 2002 LATHROP CSM VOL 25 PG 58 FD ALUM MON 2655.92 TO SW COR SEC 11. ANGLE 88-41-05@ W 1/4 SEC 11 FROM E/W CENTER LINE SEC 11 TO SW COR SEC 11
- 2003 COMBS CSM26-131 FD CI. 2655.92 TO ALUM @ SW COR SEC 11

FD CI MON. & REFERENCE MONUMENTS.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FOUND C.I. MONUMENT.

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.
- I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 2 OF 2

Emboss

CORNER CODE G-17(3)

A-E 7.08 REQUIREMENT