

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4 N. R. 12 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

CORNER CODE INDEX

FULTON TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	
A																									A
B	6					5					4				3						2			1	B
C																									C
D																									D
E																									E
F																									F
G	7					8					9				10						11			12	G
H																									H
J																									J
K																									K
L	18					17					16				15						14			13	L
M																									M
N																									N
O																									O
P	19					20					21				22						23			24	P
Q																									Q
R																									R
S																									S
T	30					29					28				27						26			25	T
U																									U
V																									V
W																									W
X	31					32					33				34						35			36	X
Y																									Y
Z																									Z

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

BEARINGS ARE BASED ON: _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE R-7(1)

FU584^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1836 (AUG2) BURNHAM EAST RANDOM BETW SEC 20 & 29
429? EAST RANDOM BETW SEC 20 & 29 T4N R12E
1155 ENTER DRY PRAIRIE
5280 INT EAST BOUNDY 64.02' SOUTH
WEST CORRECTION BETWN 29 & 20
BUR OAK 8 IN DIA
2640 SET ¼ SEC POST YELLOW OAK 24 N86E 3.3'
W. OAK 24 S63 ½W 35.64'
NO STATION
5280 TO CORNERS
- 1843 TWP RD BK 1 PG 2 SURVEYED ON THIS INSTANT A PIECE OF RD BEGINNING AT AN ANGLE POST IN A RD (A PART OF WHICH HAS BEEN DISCONTINUED) THE SAID POST STANDS IN THE LINE BETWEEN SEC 20 & 29, THENCE N81-30E BOUNDING THE SAID LINES 1314.06' TO THE [SE COR SEC 20] CORNER OF SEC 20 & 21, 28 & 29, THENCE ON THE LINE BETWEEN SECTION 21 & 28 N81-30E 3923.7 TO AN ANGLE POST. THENCE S63E 4488'; THENCE N84E 3267' TO THE QUARTER STAKE BETWEEN SEC. 26 & 27; THENCE ON THE LINES PASSING THROUGH THE CENTER OF 26 N82-15E 1402.5' TO THE BUR OAK TREE; THENCE N76E 554.4' TO A WHITE OAK, N17-45E 561' TO ANGLE POST, THENCE N47-45E 473.88'; THENCE N66-30E 864.6' INTERSECTING THE ABOVE MENTIONED ROAD 1969.44' S76W OF THE ROAD LEADING FROM JANESVILLE TO LAKE KOSHANONG.
- 1843 TWP RD BK 1 PG 16 BEGINNING AT AN ANGLE POST STANDING ON A LINE BETWEEN SEC 20 & 29, THENCE N81-30E BOUNDING THE SAID LINES 1314.06' TO THE [SE COR SEC 20] CORNER OF SEC 20 & 21, 28 & 29, THENCE ON THE LINE BETWEEN SECTION 21 & 28 N81-30E 3923.7 TO AN ANGLE POST. THENCE S63E 4488'; THENCE N84E 3267' TO THE QUARTER STAKE BETWEEN SEC. 26 & 27; THENCE ON THE LINES PASSING THROUGH THE CENTER OF 26 N82-15E 1402.5' TO THE BUR OAK TREE; THENCE N76E 554.4' TO A WHITE OAK, N17-45E 561' TO ANGLE POST, THENCE N47-45E 473.88'; THENCE N66-30E 864.6' INTERSECTING THE ABOVE MENTIONED ROAD 1969.44' S76W OF THE ROAD LEADING FROM JANESVILLE TO LAKE KOSHANONG. [COX RD]
- 1884 RUGER VOL 2 PG 380 FD TRACES OF OLD STAKE & STUMP OF SW BT & WHERE NE BT HAD BEEN DUG UP. SET LS 24X10X3 SURROUNDED BY 4 HH.VAR 5-05 2658.32 TO GEN SEC 29, VAR 5-05 5322.74 TO S ¼ COR SEC 29
- 1936 SUNNY #1303 FD 24"X10"X3" LIME STONE MON SET BY E. RUGER 1884. 2653 EAST OF N/S FENCE LINE
- 1936 SUNNY VOL 3 PG 287 FD 24"X10"X3" LS. MON SET BY RUGER IN 1884 IN RD & ON LINE WITH N/S FENCE LINE. SET PIPE 111.3 NORTH OF CENTER OF PVMT & CENTER OF RD PRODUCED WEST, WHICH IS 1587.6' WEST OF S ¼ COR SEC 20. N/S FENCE IS 2653' WEST OF S ¼ COR SEC 20
- 1949 SUNNY #1415,6565,6566 FD PIPE 2659.6X TO NW COR SEC 29
- 1971 LEE VOL 4 PG 536 DUG & FD LS 10X3X24 1.2' DEEP SURROUNDED BY 4 HH. REF SAME. IN STONE FARM RD & ON LINE WITH N/S FENCE ON EAST SIDE OF HAUGEN RD. WPL 2 288,797.41; 2,241,052.70
- 1975 WPL #1417 288,797.41; 2,241,052.70 S88-38-26W 2660.03 TO NW COR SEC 29
- 1981 BARNES VOL 6 PG 201 1.2' DEEP FD LS SURROUNDED BY 4 HHS. SET ALUM. MON & REF SAME. IN STONE FARM RD & ON LINE WITH EAST N/S PVMT EDGE OF HAUGEN RD.
- 1981 AERO-METRIC PHOTO CONTROL NGVD 29 ELEVATION 845.11'

11/14/07
Don V Barnes

FU584

1982 BARNES VOL 6 PG 258 FD ALUM. TIED INTO AERO-METRIC PHOTO CONTROL. 288,799.20; 2,241,053.34

1993 SCHROEDER CSM VOL 16 PG 391 STATES NOTHING ABOUT MON.

2001 NOTBOHM #9916 & 9917 "HICKORY RIVER VIEW" ALUM MON. 2660.19 TO SW COR SEC 20 & ANGLE 92-50-30 @ S 1/4 COR SEC 20 FROM SW COR SEC 20 TO N/S 1/4 LINE SEC 20, 3096.40 TO MP ON N/S 1/4 LINE. 288,821.14; 2,209,628.09

2001 MICHAELS R-5 S88-38-26W (NAD83(91)) 2660.19 TO BROKEN POLY. MON. @ SW COR SEC 20.

2001 MICHAELS R-7 FD ALUM CAPPED MON AT S 1/4 COR SEC 20 & 3 REFERENCE MON. REFERENCED SAME. 288,806.50; 2,209,516.06 NAD83(91), IN STONE FARM RD & EAST OF HAUGEN RD.

2005 COMBS CSM VOL 28 PG 229 FD ALUM. 2660.39 TO POLY @ SW COR SEC 20

2005 COMBS CSM VOL 28 PG 280 FD ALUM 2650.40 TO ALUM @ NE COR SEC 29

2005 COMBS BK32-622 FD ALUM. S88-38-26W 2660.39 TO FD POLY @ SW COR SEC 20 & N1-32-52E 3656.74 TO FD SQ BOLT @ MP ON SOUTH SIDE OF ROCK RIVER.

FD ALUM MON & REFERENCE MONUMENTS. IN STONE FARM RD & ON EAST SIDE OF HAUGEN RD

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal

11/14/07

Emboss

Donald Barnes

SHEET 2 OF 2

CORNER CODE

R-7(1)

A.E. 7.08 REQUIREMENT