

PLAT AND RECORD

329

VOL. 6

Of a Survey on Section 1 T 1 R 12 E. of the 4 P. M. in BELOIT Township
Rock County, Wisconsin, made \$ 33 4 10 the UNION 19

I hereby certify that the following is a correct record of said survey ~~as made by me.~~

COUNTY BUILDING
CITY OF JANESVILLE

County Surveyor.

NW & N $\frac{1}{4}$ CORNERS SECTION 1
BELOIT TOWNSHIP T1N R12E

Found copy of ties for these corners in the B-1 file.
Copy dated 12-20-1965. See Section 1 Beloit Twp in
B-1 for copy.

W $\frac{1}{4}$ CORNER SECTION 27:
JANESVILLE TWP
T3~~W~~ R12E

Volume 4 Page 69 of the Beloit and Janesville County
Surveyors Record do not agree. The distance from the
west reference pipe to the north reference pipe is
given as 98.63 or 96.63.

W $\frac{1}{4}$ CORNER SECTION 33:
UNION TWP
T4N R10E

The Beloit CSR and the Janesville CSR, V4 PG 149 & 150
respectively, have differances. The southeasterly
measurement is recorded as 48.29' in the Beloit book
and 48.99' in the Janesville book.

NW CORNER OF NE $\frac{1}{4}$ SE $\frac{1}{4}$:
SECTION 33 UNION TWP
T4n R10E

The Beloit CSR V4 PG149 and the Janesville CSR V4 PG150
have differances. The easterly north-south measurement
is 89.11' in the Beloit book and 80.11' in the Janesville
book.

MICROFILMED