

Paper weight-110# (minimum)

Black nonfading ink required

# U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 3N. R. 13E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

CORNER CODE INDEX

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25		
A																											A
B																											B
C																											C
D																											D
E																											E
F																											F
G																											G
H																											H
J																											J
K																											K
L																											L
M																											M
N																											N
O																											O
P																											P
Q																											Q
R																											R
S																											S
T																											T
U																											U
V																											V
W																											W
X																											X
Y																											Y
Z																											Z

HARMONY TWP

ROCK COUNTY WI

IF AVAILABLE  
ROCK COUNTY COORDINATES PREFERRED

North \_\_\_\_\_ Elev. \_\_\_\_\_

East \_\_\_\_\_

Hor. Datum \_\_\_\_\_ Vert. Datum \_\_\_\_\_

LATITUDE \_\_\_\_\_ ELLIPS. HT. \_\_\_\_\_

LONGITUDE \_\_\_\_\_

NAD83(91) \_\_\_\_\_ NETWORK ADJ. YR \_\_\_\_\_

GPS (X) \_\_\_\_\_ TRAVERSE (X) \_\_\_\_\_

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL  AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT       WITNESS MONUMENT

(a) BEARINGS ARE BASED ON: ROCK COUNTY PROJECTION

FIELD BOOK \_\_\_\_\_ PAGE # \_\_\_\_\_  
OR OBSERVATION SHEET \_\_\_\_\_

SHEET 1 OF 3

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE E. 25 (1)

HA533 NECORSEC12

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1835 MULLETT (DEC 1) NORTH ON EAST SIDE SEC 12  
277.2 BURR OAK 10"  
1361.58 BURR OAK 16"  
2640.00 SET QUARTER SEC POST BURR OAK 12" S69  
1/2W 74.58'; BURR OAK 6" N51W 104.28'  
3300 ENTER POND  
3960 LEAVE SAME  
4588.32 BURR OAK 10"  
5280.00 SET POST CORNER TO SECTIONS 1 & 12  
BURR OAK 10" N56W 60.06'; BURR OAK 13"  
S17W 71.28' LAND ?? SAME AS LAST MILE
- 1835 MULLETT (DEC 1) NORTH ON EAST SIDE SEC 1  
1095.6 BURR OAK 8  
2640.00 SET QUARTER SECTION POST  
BURR OAK 12" S15W 31.02'; BURR OAK 18"  
N57W 17.82'  
3472.92 BURR OAK 14"  
5280.00 SET TEMP SIX MILE POST
- 1870 RUGER REMON PG 30 NORTH ON EAST LINE OF NE QUARTER  
SEC 12 ON A VAR 7-20  
2634.22 INTERSECTED NORTH BOUNDARY LINE 4.95'  
WEST OF COR. COR VAR 7-14
- 1870 RUGER REMON PG 20 SOUTH ON EAST LINE OF SE QUARTER  
SEC 1 ON A VAR 6-53 AT  
2637.36 INTERSECTED SOUTH BOUNDARY LINE 1.98'  
WEST OF COR. FD OLD STAKE ON COR AND SW  
BEARING TREE AND WHERE STUMP OF NW  
BEARING TREE HAD BEEN DUG UP COR VAR 6-  
56
- 1870 RUGER REMON PG 21 WEST ON SOUTH LINE OF SE QUARTER  
SEC 1 ON A VAR 5-10 AT  
2658.04 INTERSECTED QUARTER LINE 3.96' NORTH OF  
QUARTER COR. FOUND OLD STAKE AND HARD  
HEAD STONE ON COR AND SE BEARING TREE  
AND WHERE STUMP OF SW BEARING TREE HAD  
BEEN DUG UP. COR VAR 5-15
- 1883 RUGER VOL 2 PG 358 STONE MON.  
1891 BLEEDORN VOL 2 PG 445 MON 2641.16 TO W 1/4 COR SEC  
6 JOHNSTOWN  
1964 BATTERMAN VOL 4 PG 197 FD CUT STONE MON WITH TOP  
BROKEN OFF. REF SAME.  
1976 BARNES VOL 5 PG 118 SET ALUM ON TOP OF CUT L.S. REF.  
SAME.  
1980 VOL 6 PG 100 VOID  
1981 BARNES VOL 6 PG 139 SET ALUM MON ON TOP OF  
LIMESTONE. REFERENCED SAME. FD RECORD REF PIPE TO  
NW, SW, & SE.  
1981 BARNES VOL 6 PG 168 FD ALUM MON. 2639.37 TO ALUM @  
E 1/4 COR SEC 12.  
1984 BARNES E-25 272,499.46; 2,296,677.81 ELEV 929.2X

FD ALUM IN GOOD CONDITION

Seal  
Emboss  
Darius  
6-20-2012

SHEET 1 OF 3

CORNER CODE **E-25**

HA533 NECORSEC12

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED ALUM THAT IS ON TOP OF CUT L.S.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

NONE

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

NO

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal  
  
Emboss

SHEET 2 OF 3

6-20-2012

CORNER CODE **E-25**

A.E. 7.08 REQUIREMENT

OBSERVATION SHEET #533  
1981 BARNES VOL 6 PG 139  
1964 BATTERMAN VOL 4 PG 197

MONUMENT WILL BE DISTURBED  
BY CTH M PROJECT  
REC:ALUM OVER  
CUT LIMESTONE

ELEV OF ALUM DETERMINED  
FROM AIRPHOTO

NE COR  
SEC 12  
HARMONY TWP  
T3N R13E

SIX CORNERS RD

TARRANT RD

CTH M

SHED

NEAR LARGE  
PINES  
SEARCHED &  
FD NOTHING

COMPUTED  
N39E 100X

SET 3/4X24  
REROD  
ELEV 929.4

*Emold*  
EMBOSSED  
SEA  
*Barnes*  
6-20-2012

1981 83.70  
1964 83.70

N14-04-39E 74.55

ELEV 929.0  
FD ALUM

1981 64.30  
1964 64.30  
N57-57-26E

DECAYED STUMP  
3" DIA  
FLOWERS

ELEV 926.9  
SEARCHED &  
DID NOT  
FD PIPE  
REC 3

S78-52-18E 201.73

1981 53.28  
1964 53.18  
S42-41-27E 52.22

1981 91.73  
1964 91.74

S87-17-36E 90.03 FD 3/8 REROD

0.5"

S89-48-15E 162.53

N85E 1.7X  
COMPUTED

ELEV 924.7  
SET 3/4X24  
REROD

3 OF 3

E-C-J