



Surrounded  
Post by 3  
Hard heads  
S.P. by 3 h.h.

- Fig. 2 Took witness trees White O. 20 S 41°40' W 71  
 Var. 6°20' Br. O. 16 S 73°25' E 117  
 " 4 Br. O. 18 S 0°20' E <sup>86</sup> Var. 6°20'  
 Run thro East & West mile through the Sec. on a Var 4°06'  
 by forward & back sights  
 " 5 Black O. 7 S 82°40' E 51 Bl. O 5 N 30° W 10 1/2  
 Surrounded post by 3 hard heads Var. 6°20'  
 " 6 Surrounded " " "  
 " 7 " " " "  
 " 8 " " " "

All traces of East 1/2 post being gone put it in from  
 Sec. corners

A Record & Plat of a survey made on Sec. 22. T 4 N R  
 14 E Lima June 22<sup>d</sup> 1859 by Edward Rizer  
 Co. Surveyor

COUNTY SURVEYOR  
 RECORD 1859-1906