

Bench	Back Sight	Instr	Fore Sight	Redg	Inter-Sight	Height	Remarks
			15.635				
					11.946	3.689	West Side Middle line of float section flume "Doty Works"
					11.886	3.749	1 st inter. East .. " " " " " "
					11.807	3.828	Average 3.755 2 nd " " " " " "
					11.898	3.737	3 rd " " " " " "
					11.863	3.772	Middle East Side " " " " " "
					11.760	3.875	N.W. cor float section flume, "Doty Works"
					11.760	3.875	1 st inter. East .. " " " " " "
					11.744	3.891	Average 3.875 2 nd " " " " " "
					11.738	3.897	3 rd " " " " " "
					11.797	3.838	North line N.E. cor. " " " " " "
					3.807		Mean Average of bottom of float section of flume "Doty Works"
17.202							Cont bench on upper surface of stone abutment. East end of upper dam.
	1.144		18.346				
					15.586	2.760	Bottom of Jeffelle Wheel. Doty Works.
				5.830			12.516
	2.292		14.808				
					10.900	3.908	N.W. cor float section of flume of Woolen Mill.
					10.932	3.876	Average 3.890 1 st inter. East .. " " " " " "
					10.940	3.868	2 nd " " " " " "
					10.900	3.908	North line N.E. cor. " " " " " "
					10.937	3.871	West Side Middle line of float sec. flume of Woolen Mill
					10.979	3.829	Average 3.852 1 st inter. East .. " " " " " "
					10.955	3.853	2 nd " " " " " "
					10.952	3.856	Middle line East side " " " " " "
					10.926	3.882	S.W. cor float section of flume of Woolen Mill
					10.922	3.886	Average 3.879 1 st inter. East .. " " " " " "
					10.927	3.881	2 nd " " " " " "
					10.940	3.868	South line S.E. cor " " " " " "
					3.874		Mean average of bottom of float section of flume of Woolen Mill
			2.290	12.578			
	0.649		13.167				
					9.746	3.421	Bottom of gate - Wheeler's Woolen Mill,

COUNTY SURVEYOR
RECORD 1859-1906