

County Surveyor's Office
Janesville, Wis
August 13th 1875

I Edward Ruger County Surveyor of Rock County, state of Wisconsin, do hereby certify that on the third day of August A. D. 1875. I took levels from the top surface of the Skewback, next to the wall, at the north west corner of the south abutment of the highway bridge across Rock river at Monterey, and caused marks to be cut as follows: to wit; in the south pier of the railway bridge at Monterey, at the North East corner of said pier; in the wall of the stone Flour Mill at Monterey, at the North west corner of said mill; in the north face of the west wing wall of the south abutment of the highway bridge at Monterey; in the west face of the first pier north of the south abutment of said highway bridge; in the west face of the second pier north of said south abutment in the south face of the parapet wall west of the double pier of said highway bridge, in the East face of the railway pump house, and in the wall of the stone Woolen Mill at Monterey, at the North East corner of said mill. All of the above designated marks were painted with coal tar to further identify them, and they are all in the same level horizontal plane. Eight inches above the upper surface of the Skewback, next to the wall, at the North west corner of the south abutment of said highway bridge across Rock River at Monterey. I also hereby certify that on the Eleventh day of August A. D. 1875. I took levels from the upper surface of the Skewback. Next to the wall at the North west corner of the south abutment of said highway bridge across Rock River to the upper surface of a large and permanent stone