



- Fig. 1 Surrounded post by 4 lime stones & look bearing stones  
 Lime stone 16 in. by 9 broad by 2 thick S 55° 04' E 55 Var. 6° 50  
 " " " " " 8 " " " " " S 48° 08' N 55 " "  
 Put in North 1/4 post by Sec. Corners & surrounded post by  
 3 lime stones  
 " 5 Surrounded post by 4 lime stones & one hard head and  
 planted witness stones lime stone 14 x 8 x 4 - above bench  
 S 73° 30' E 54 Lime stone 10 x 9 S 76° 30' N 55 Var. 6° 45'  
 " 8 Surrounded post by 4 lime stones  
 " 10 " " " " " "  
 Found 1/4 Post  
 " 13 Surrounded post by 4 lime stones  
 " 15 " " " " "  
 " 16 " " " " "  
 " 17 " " " " "

The east line of the Sec. and the line through the  
 Centre North & South were run by forward & back  
 sight on account of local attraction

A Record & Plat of a survey made on Sec. 132 R N  
 13 E, La Prairie May 25. 1859  
 by Edward Rizer Co. Surveyor

REYBRIUS YTHUISI  
 COUNTY SURVEYOR  
 RECORD 1859-1906