


Sec. 23 Beloit.



Gov. Survey. 42.76 to meander corner
43.08

Between track center	5.36 Acres.
Water	1.38 "
Low land	1.98 "

North part of N.W. $\frac{1}{2}$ of
N.W. $\frac{1}{4}$ & Lot 1.
Survey made to determine
the portion damaged
by standing water.
Aug 29 - 1882
J. A. Holmes
Co. Surveyor.

43.99

