



Fig 25 Mt. trees incorrect - look others

" Br @ 24 S 58 1/2 E 95

" 24 N 58 E 94

24 " 18 N 32 1/2 E 15

" 10 S 81 W 35

22 " 14 N 61 W 83

24 N 81 W 89

13 24 S 42 E 147

School house NE cor. S 51 E 47

12 Bl. @ 12 S 42 1/2 E 35 1/2

" 18 N 69 W 110 1/2

17 " 16 S 89 E 6 1/2 Br @ 20 S 78 W 106

16 Bl. @ S 35 E 44 1/2

" " 12 N 52 E 41 1/2

Fig. 5 Trees mostly decayed  
look other trees.

Br @ 20 S 46 W 56

" 16 S 73 1/4 E 88

Fig. 3 Bl. @ 10 S 7 1/4 E 164

Hickory 2 S 19 W 35 1/2

The above survey was made March 18  
1856

Joseph Church  
Co. Surveyor

A Record & Plat of a survey made on Sec. 5 T 4 R 10 E  
Union March 7 1856

Joseph Church  
Co. Surveyor

COUNTY SURVEYOR  
RECORD 1859-1906