

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 2 N. R. 14 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

CORNER CODE INDEX

BRADFORD TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	A
B																										B
C																										C
D																										D
E																										E
F																										F
G																										G
H																										H
J																										J
K																										K
L																										L
M																										M
N																										N
O																										O
P																										P
Q																										Q
R																										R
S																										S
T																										T
U																										U
V																										V
W																										W
X																										X
Y																										Y
Z																										Z

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

BEARINGS ARE BASED ON: _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE E-13(3)

BR527 SECORSEC4

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1871 RUGER VOL 2 PG 64 FD LARGE LIMESTONE PLANTED DEEP. PUT SMALL IRON ROD ON TOP OF LIMESTONE. VAR 6-52 2648.58 TO W 1/4 COR SEC 3, VAR 6-52 5272.74 TO NW COR SEC 3, VAR 4-57 2649.24 TO S 1/4 COR SEC 3, VAR 4-57 5298.48 TO SE COR SEC 3.
- 1971 LEE VOL 4 PG 513 DUG & FD 1/4X8" PIN ABOVE LARGE LIMESTONE SETTING ON EDGE WITH TOP BROKEN. REFERENCED SAME.
- 1971 COMBS CSM VOL 2 PG 123 THE S 1/4 COR SEC 4 WAS IN CUT AREA OF HIGHWAY. COUNTY SURVEYOR DID NOT DIG FOR IT, THW SW CORNER & SE CORNERS WERE LOCATED BY COUNTY SURVEYOR.
- 1980 COMBS CSM VOL 9 PG 313 FD 1/2 PIN @ NW COR SEC 10 THENCE EASTERLY ALONG SEC LINE 1270.85 TO POB OF CSM. STATES NOTHING ABOUT MON.
- 1980 BARNES VOL 6 PG 32 SET PK FROM TIES. N88-22-25W 2649.03 TO S 1/4 COR SEC 4, NO-53-43E 1325.94 TO 1/16TH COR, NO-53-32E 1325.70 FROM 1/16TH COR TO E 1/4 COR SEC 4, NO-53-48E 5278.60 TO NE COR SEC 4.
- 1981 WIDOT E-13 SET TIES. CALLS FOR PK
- 1984 BARNES E-13(1) SET POLY MON.
- 1982 BARNES TWP PROJ. N89-25W 2648.9X TO S 1/4 COR SEC 4, NO-08W 2651.4X TO E 1/4 COR SEC 4, SO-42E 2649.7 TO E 1/4 COR SEC 9, NO-08W 5278.3X TO NE COR SEC 4.
- 1989 SCHROEDER CSM VOL 14 PG 76 STATES NOTHING ABOUT MON.
- 1990 SCHROEDER VOL 14 PG 453 STATES NOTHING ABOUT MON.
- 1992 SCRHOEDER CSM VOL 16 PG 35 STATES NOTHING ABOUT MON. ANGLE 90-44 13 @ E 1/4 COR SEC FROM SE TO W 1/4 COR SEC 4.
- 1993 SCHROEDER #11161 STATES NOTHING ABOUT MON. ANGLE 87-53 @ NW COR SEC 10 FROM NORTH LINE SEC 10 TO W 1/4 COR SEC 10. SOUTHERLY 183.00 ALONG SEC LINE TO POB OF SURVEY.
- 1994 BARNES E-13(2) SET PK FROM TIES.
- 1996 SCHROEDER CSM VOL 19 PG 309 STATES NOTHING ABOUT MON.
- 2004 COMBS CSM VOL 28 PG 64 PK @ SW COR SEC 3. 2651.44 TO ALUM @ W 1/4 COR SEC 3

CONTACTED AFTER PVMT WAS MILLED. INSTALLED STEEL SURVEY MONUMENT SPIKE AFTER FINAL MATT WAS INSTALLED. STEEL SURVEY SPIKE IS 3" LONG, 3/8" DIAMETER, & TOP IS 1" IN DIAMETER AND STAMPED "SURVEY MARKER". RECORD TIES CHECKED VERY WELL.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED PERPETUATED LOCATION

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above. NONE

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal
Donald
Barnes

Barnes

9/22/08

SHEET 1 OF 2

CORNER CODE E-13(3)

A.E. 7.08 REQUIREMENT

