

# U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:  
T. 4 N. R. 12 E. 4th P.M.

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT  
REV 10/23/2004 USMONREC.DWG

### CORNER CODE INDEX

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	A
B		6					5					4			3			2				1				B
C																										C
D																										D
E																										E
F																										F
G																										G
H																										H
J																										J
K																										K
L																										L
M																										M
N																										N
O																										O
P																										P
Q																										Q
R																										R
S																										S
T																										T
U																										U
V																										V
W																										W
X																										X
Y																										Y
Z																										Z

FULTON TWP  
ROCK COUNTY WI

IF AVAILABLE  
ROCK COUNTY COORDINATES PREFERRED

North \_\_\_\_\_ Elev. \_\_\_\_\_

East \_\_\_\_\_

Hor. Datum \_\_\_\_\_ Vert. Datum \_\_\_\_\_

LATITUDE \_\_\_\_\_ ELLIPS. HT. \_\_\_\_\_

LONGITUDE \_\_\_\_\_

NAD83(91) \_\_\_\_\_ NETWORK ADJ. YR \_\_\_\_\_

GPS (X) \_\_\_\_\_ TRAVERSE (X) \_\_\_\_\_

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL  AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT       WITNESS MONUMENT

BEARINGS ARE BASED ON: \_\_\_\_\_

FIELD BOOK \_\_\_\_\_ PAGE # \_\_\_\_\_

SHEET 1 OF 24

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE A-9(1)

FU505 ^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 (SEP 20) MULLETT & BRINK EAST ON SOUTH SIDE SECTION 32  
12E 5N

2508 STREAM ? COURSE SE  
2640 BUR OAK 10 N16E 306.24' BUR OAK 12 N1W  
450.12'  
2937 LEAVE WET PRAIRIE  
5280 SET POST CORNER SECTIONS 32 & 33 BUR OAK 22  
N52W 270.6' BUR OAK 10 N82E 223.74' LAND  
LEVEL FIRST RATE FIRST 1/2 WET PRAIRIE LAST 1/2  
TIMBERED WITH WHITE BLACK AND BUR OAK

1833 (SEP 21ST) MULLETT & BRINK EAST ON SOUTH SIDE SECTION  
33

2640 SET QUARTER SECTION POST WHITE OAK 16 N16W  
31.02' WHITE OAK 10 N43E 52.8'  
3432 ENTER MARSH  
3630 STREAM 19.8' @ SOUTH  
3762 LEAVE MARSH  
5280 SET POST CORNER SECTIONS 33 & 34 WHITE OAK  
20 N77W 57.42' WHITE OAK 24 N45E 95.04' LAND  
ROLLING SECOND RATE THINLY TIMBERED WITH BUR  
WHITE AND BLACK OAK GOOD OBSERVATION AT THIS  
CORNER VAR 8-40

1833 (OCT/NOV) MILLER NORTH BETWEEN SECTIONS 32, 33 T5N  
R12E

1353 YEL OAK 12 IN  
2640 SET 1/4 SEC POST B.W.O 12 IN N36-30E 35.64' YEL O  
14 IN N78W 28.38'  
3579.18 YEL. O. 12 IN  
475.2 ENTER BEND IN MARSH  
5280 SET POST IN MARSH COR TO SECS 28,29,32,33  
B.W.  
O 36 IN S2-30W 528', W.O. 24 IN N76-30W 558.36'  
LAND LEVEL 2<sup>ND</sup> RATE THINLY TIMBERED B.W. & YEL  
OAK UNDERGROWTH RED ROOT, INDIGO \PRAIRIE  
GRASS

1834 (MAR/APR) HARRISON NORTH BET SECS 4 & 5

2640 QUARTER SEC COR. BEARINGS {W.O. 24 S86E  
414.48' BURR O S44W 81.84' WO 24 BURR O 8}  
MARKED  
3300 ENTER MARSH  
3907.2 BROOK @ CRS E  
5016 LEFT MARSH  
5306.4 INT. N. BDY 23.1' E OF P. {BURR O 18 S54E 290.4'  
W.O. 18 S45W 35.64' LAND LEVEL & SOMEWHAT WET  
2<sup>ND</sup> RATE TIMBER W.O. BURR O & RED O.

1873 GRAVES VOL 6 PG 349 COUNTY SURVEYOR (DANE COUNTY)

2659.8 FROM SW COR SEC 33 TO W 1/4 COR SEC 33,  
2644.62 FROM SW COR SEC 33 TO S 1/4 COR SEC 33, SET  
STONE IN THE CENTER OF RD AT THE SW COR SEC 33.

1886 BARTON VOL 6 PG 350 DANE COUNTY SURVEYOR. VAR 8-30  
1320.66 FROM S 1/4 COR SEC 32 TO S 1/16<sup>TH</sup> COR OF SE 1/4  
OF SEC 32.

1911 HINTZE ALBION T5N R12E N89-00E 2648.3 TO S 1/4 COR SEC  
33, S89-26W 2665.0 TO S 1/4 COR SEC 32, N0-24W 2662.9  
TO W 1/4 COR SEC 33. SOFT MAPLE 24" N27-30W 30.4'; SOFT  
MAPLE 18" S74-30E 97.7'; 19' WEST OF NW COR SEC 4  
SET CORNER OF SEC 32 & 33 BY SIGNS OF THE U.S.B.T.  
AND FENCES. SET CORNER 33' S & .6' EAST OF FENCE  
CORNER. AT DANE COUNTY CORNERS, HINTZE INSTALLED  
CONCRETE MONUMENTS.

THE DIFFERENCE IN BEARING OF LINES BETWEEN SECTION  
CORNERS GIVES THE TRUE DEVIATION FROM THE STRAIGHT  
LINE. SOME OF THE BEARINGS ARE MAGNETIC, CHECKED BY

SHEET 1 OF 4  
A-9(1)

Donald Barnes  
May 8 2006

FU505

- MEASUREMENTS, AND THE REST ARE TRANSIT LINES CHECKED BY OBSERVATIONS ON POLARIS. I HEREBY CERTIFY THAT THE DISTANCES AND BEARINGS ARE CORRECT ACCORDING TO SURVEY MADE UNDER THE PROVISIONS OF CHAPTER, 39 SECTION 825 OF THE REVISED STATUTES OF WISCONSIN AND IN ACCORDANCE WITH THE RULES ESTABLISHED BY THE UNITED STATES LAND OFFICE.
- 1935 ELY ASSESSOR'S PLAT OF EDGERTON. 2601.06 TO N ¼ COR SEC 4. STATES NOTHING ABOUT MON.
- 1960 ELY #13410 SUB IRON STAKE DRIVEN.
- 1967 WEIR #13557 STATES NOTHING ABOUT MON.
- 1970 BATTERMAN VOL 4 PG 467 @ NE COR SEC DUG & FD NOTHING 23' EAST OF SE COR SEC 32 & ON LINE WITH N/S FENCE TO THE SOUTH. @ SE COR SEC 32 FD LIMESTONE. SOUTH OF CENTER OF CTH N & REFERENCED SAME. ON LINE WITH N/S FENCE
- 1977? WPL #1044 CI, 23.32 EAST OF SE COR SEC 32, 2643.49 TO N ¼ COR SEC 5, INVERSE USING COORDINATES ON MAP TO N ¼ COR SEC 5 IS 2643.35. SE COR SEC 32 TO S ¼ COR SEC 32 IS 2664.98. C.I. & ? STONE OR CONC. AT SE COR SEC 32
- 1978 NORTHROP #1027 AT SW COR SEC 33 FD RR SPIKE NOTE: MON OF RECORD DUG FOR AND FD BY ROCK CO. SURVEYOR. REF V4 PG 467 ROCK C.S. RECORDS. REF TIES FOUND AND CHECKED
- 1978 NORTHROP #1025 DANE COUNTY TIES FOR SW COR SEC 33. FD R/R SPIKE AT THE ABOVE CORNER AGREEING CLOSELY WITH REF. TIES SHOWN ON PREVIOUS TIE SHEET BY R.H. BATTERMAN JR. IN VOL 4 PG 467 ROCK COUNTY SURVEYOR RECORDS AND THAT THE ABOVE SKETCH IS A TRUE REPRESENTATION OF THE FIELD MEASUREMENTS MADE.
- 1978 NORTHROP VOL 5 PG 398 RECEIVED INFORMATION FROM NORTHROP . FD RR SPIKE @ SW COR SEC 33. SHOWS TIES.
- 1978 BARNES VOL 5 PG 434 FORMER COUNTY SURVEYOR DUG & FOUND NOTHING, VOL 4 PG 467. FD R/R SPIKE ON LINE WITH SW & S ¼ COR SEC 33 @ SE COR SEC 32. @ NE COR SEC 5 SET ALUM. MON & REFERENCED SAME. 23.30 EAST OF FD R/R SPIKE. 2.8' SOUTH OF CENTER OF PVMT. 310,153.24; 2,243,395.41 & 310,152.81; 2,243,372.11 @ SW COR SEC 33. FB #1 PG 40&42 FD CARRIAGE BOLT CP#3370 OF AIR PHOTO CONTROL. ANGLE 170-45-40 @ #3370 FROM CONC. AT S ¼ COR SEC 33 TO FD R/R @ SW COR SEC 33 & 10.81' TO SW COR SEC 33.
- 1978 BARNES VOL 5 PG 447 COORDINATES PROVIDED BY SANDSNES. 310,152.98; 2,243,395.40 NAD27
- 1980 SANDSNES #7221 & #1037 & #1032 FD IRON STAKE & ANGLE 180-44-59 @ W ¼ COR SEC 4 FROM NW COR SEC 4 TO SW COR SEC 4
- 1983 BARNES VOL 6 PG 303 COORDINATES PROVIDED BY SANDSNES 310,152.97; 2,243,395.40, 310,152.81; 2,243,372.20 @ SE COR SEC 32, S88-38-34W 2622.98 TO N ¼ COR SEC 5, S2-33-43E 2665.97 TO E ¼ COR SEC 5. BEARINGS ARE NAD27
- 1985 SANDSNES A-9, I FOUND AN ALUMINUM CAPPED MONUMENT AT THE NE COR OF SEC 5. I COULD NOT FIND A TIE SHEET IN THE ROCK COUNTY SURVEYORS OFFICE FOR THIS CORNER. TIES ARE AS SHOWN ON THE REVERSE SIDE. FOUND DANE COUNTY MON AT SE COR SEC 32, 22.20' WEST OF NE COR SEC 5. MONUMENTS 3' SOUTH OF CENTER OF CTH N
- 1988 WEIR CSM VOL 13 PG 394 FD ALUM. MON.

FD ALUM. MON @ NE COR OF SEC 5 & DANE COUNTY ALUM. MON WITH "X" @ SE COR SEC 32 T5N R12E.

*Dwight Barnes*  
*May 8 2006*

SHEET 2 OF 4  
A-9(1)

FU505

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD ALUM @ NE COR SEC 5. DID NOT ACCEPT FD ALUM. @ SE COR SEC 32.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

THE RECORDS INDICATE A DISCREPANCY WITH THE SE COR OF SEC 32. IN 1873 GRAVES, DANE COUNTY SURVEYOR, SET A STONE IN THE CENTER OF THE RD. IN 1911 HINTZE DID NOT FIND GRAVES' STONE AND HE PLACE A CONCRETE MONUMENT BY USING "SIGNS OF THE U.S.B.T. AND FENCES". IN 1970 BATTERMAN, ROCK COUNTY SURVEYOR, DUG AND FD A LIMESTONE AT THE SE COR OF SEC 32 AND REFERENCED SAME. IN 1978 BARNES FD R/R SPIKE, 2 REFERENCE TIES & ACCEPTED SAME. IN 1985, SANDSNES FD ALUM. MON.

I DID NOT FIND A RECORD OF THE INSTALLATION OF THE ALUM @ THE SE COR SEC 32 IN THE ROCK COUNTY RECORDS. I DID NOT SEARCH THE DANE COUNTY RECORDS.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

NO

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal  
Donald Barnes  
May 6 2006  
Emboss

SHEET 3 OF 4

CORNER CODE

**A-9(1)**

A.E. 7.08 REQUIREMENT

