Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

T. $\#$ N. R. $\cancel{}\cancel{}$ E. 4th P.M.	WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT REV 10/23/2004 USMONREC.DWG
CORNER CODE INDEX	FULTON TWP
A 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 B C	ROCK COUNTY WI
	D IF AVAILABLE E ROCK COUNTY COORDINATES PERFERRED F
G H I	G H North Elev
K B A A B	K East
MN	M Hor. Datum Vert. Datum
P Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q	$egin{array}{ccccc} & \circ & & & & & & & \\ & P & & & & & & & & & &$
	S LONGITUDE
U	v NAD83(91)NETWORK ADJ. YR
× 3 3 3 3	
Y Z 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX	Y 7 RASED ON THE FOLLOWING CONTROL
♦ CORNER MONUMENT (a)	WITNESS MONUMENT

BEARINGS ARE BASED ON:

FIELD BOOK _____ PAGE # _____ OF ____ SHEET ___ OF ____ OF SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.
PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

FU624^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1835 (JAN 7) MULLETT & BRINK WEST SOUTH SIDE SECTION 32 T4N
R12E

66 LEAVE PRAIRIE

2344.32 B. OAK 12

2640 SET 1/4 SECTION POST B. OAK 12 N40E 31.68' B. \
OAK B N77W 40.92'

5280 SET POST ON SECTIONS 31 & 32 W. DAK 20 N45E 53.46' BUR DAK 16 N2BW 42.9' LAND GENTLY ROLLING 2ND RATE W? & BUR DAK

- 1860 RUGER VOL 1 PG 142 @ N 1/4 COR SEC 5 CALLS FOR COR BUT STATES NOTHING ABOUT IT. 2691.48 TO CEN SEC 5 JANESVILLE TWP.
- 1865 LOCKE VOL 1 PG 243 CALLS FOR BUT STATES NOTHING ABOUT MON. USED TO SUBDIVIDE SEC 32.
- 1876 RUGER VOL 2 PG 209 FD REMAINS OF OLD STAKE & STUMP OF NW BT & WHERE STUMP OF NE BT HAD BEEN DUG UP. SET LIMESTONE 16X8X2. 7.10' EAST OF N ¼ COR SEC 5 JANESVILLE TWP, VAR 6-29 2644.78 TO SE COR SEC 32, VAR 6-33 2648.42 TO SW COR SEC 32. @ N ¼ COR SEC 5 JANESVILLE TWP SET L.S. 13X12X7, VAR 6-43 2691.98' CEN SEC 5, VAR 6-29 2641.32 FROM N ¼ COR SEC 5 TO NE COR SEC 5, VAR 6-33 2641.32 FROM N ¼ COR SEC 5 TO NW COR SEC 5.
- 1972 WP&L VOL 1 PG 201 SET CI MON AT S 1/4 32-4-12 BY WPL MARCH 1972
- 1974 WP&L VOL 2 PG 209, VOL 1 PG 201, & VOL 1 PG 243 SET C.I.
 MON BY WPL MAR 1974 AT N ½ COR SEC 5 & S ½ COR SEC 32
- 1974 WPL VOL 1 PG 243 NOTE: BELOIT RECORDS. SET CI. MON AT S $^{1/4}$ COR SEC 32 4-12, SET C.I. MON AT N $^{1/4}$ COR SEC 5 3-12. CORS SET BY WPL MARCH 1974
- 1975 WPL #1444 & #2235 278,164.14; 2,241,138.30 S89-18-43W 2641.17 TO SW COR SEC 32
- 1977 SCHROEDER CSM VOL 6 PG 313 STATES NOTHING ABOUT MON. 910.70 WESTERLY OF CENTER OF NORTH RIVER RD.
- 1987 BARNES Z-7 ON JANUARY 14, 1987 MR. NORM TRUE, WPL, STATED THAT HE FD THE STONE OF RECORD & REPLACED IT WITH A CAST IRON MON. HE DID THIS IN MARCH OF 1974. TIES FOR CAST IRON MON WITH CARSONITE POST. 6.64 EAST OF N 1/4 COR SEC 5 JANESVILLE TWP.
- 1987 A-7 ON JANUARY 14, 1987 MR. NORM TRUE, WPL, STATED THAT HE FD THE STONE OF RECORD & REPLACED IT WITH A CAST IRON MON. HE DID THIS IN MARCH OF 1974. TIES FOR CAST IRON MON WITH CARSONITE POST. 6.64 EAST OF N 1/4 COR SEC 5 JANESVILLE TWP.N 1/4 COR SEC 5 278,167.27; 2,241,134.29 ELEV. 860.8 WPL 278,164.06; 2.241,131.72 ELEV 860.8 WPL
- 1987 BARNES VOL 6 PG 366 S89-55E 6.64' FROM N ¼ COR SEC 5 TO S ¼ COR SEC 32, S89-17-18W 2634.78 FROM N ¼ COR SEC 5 TO NW COR SEC 5, N89-03-46E 2640.11 FROM N ¼ COR SEC 5 TO NE COR SEC 5, & S89-17-26W 2641.42 FROM S ¼ COR SEC 32 TO SW COR SEC 32.
- 2005 LATHROP CSM VOL 28 PG 284 FD C.I. 6.64 EAST DF C.I. @ N 1 4 COR SEC 5, 2633.41 TD FD IRON PIPE @ NE COR SEC 5

SHEET 1 OF 2 CORNER CODE Z-7(1)

Dual Baines 12/04/67

FU624

USED JANESVILLE TWP OBSERVATIONS.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED RECORD CI MONUMENTS & REFERENCE MONUMENTS. WPL FD RECORD STONE & REPLACED WITH CI.

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above. NO
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location. $N \square$
- I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 2 OF 2

CORNER CODE \mathbb{Z} -7(1)

Fanos

CORNER O

12/04/07 A.E. 7.08 REQUIREMENT