ö

BASED

PUBLIC LAND U.S. SURVEY MONUMENT RECORD

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT For Public Land Survey Corners in: T. \(\sum_{N.} \), R. \(\sum_{E} \) CORNER CODE INDEX NEWARK TWP 18 19 2021 22 23 24 25 ROCK COUNTY WI IF AVAILABLE D ROCK COUNTY COORDINATES PERFERRED E North ----- Elev. East 0 Hor. Datum _____ Vert. Datum _ LATITUDE _____ELLIPS. HT. LONGITUTE ____ GPS (X) ___ TRAVERSE (X) ___ BASED ON THE FOLLOWING CONTROL: MONUMENT LOCATION ON ABOVE INDEX O WITNESS MONUMENT **CORNER MONUMENT** (a) Fd TIES 10L4 PG 535

OBSERVATION Sheet 572

SHEET ____ OF __ FIELD BOOK_ SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH. PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

NE572

(B)Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1834 MILLER

PG 11

EAST RANDOM BETWEEN SECS 13 & 24

1650 ENTER MARSH C. S.

4382.4 BROOK 6.6' C SOUTH

SEC LINE 54.12' NORTH OF POST. LAND 2ND & 3RD RATE 5214

WEST CORRECTED BETWEEN SECS 13 & 24

SET 1/4 SECTION IN MARSH. TOO WET TO MOUND 2607

3910.5 WHITE OAK 14 IN DIA.

SEC COR 5214

1863 LOCKE VOL 1 PG 185 VAR 6-45 2641.32 TO S W COR SEC 13, VAR 6-45 2641.32 TO SE COR SEC 13, N 1/4 COR SEC 24 IS ON LINE & MIDWAY BETWEEN THE NE & NW CORNERS OF SEC 24, 2657.16 TO CENTER OF SEC 24. SET 14X10X6 AND 4 SMALL HARDHEADS ON N. S. E. & W.

1863 LOCKE #3194 VAR 6-45 2641.32 TO S 1/4 COR SEC 13

1863 LOCKE VOL 1 PG 186 VAR 6-10 2666.4 TO CENTER OF SEC 13 & 5332.8 TO N 1/4 COR SEC 13

1871 COLLINS REMONUMENTATION NOTES

PG 138

EAST BETWEEN 13 & 24 VARIATION 5-55

2651.88 SET 1/4 STONE IN LINE WITH FENCE NORTH

CONTINUED EAST SAME VARIATION

5303.1 SECTION CORNER

LEE VOL 4 PG 535 DUG & FD SQ L.S. 1.5' DEEP. DROVE 1X24" PIPE IN ITS PLACE 1971 & REFERENCED SAME.

1979 LEE CSM 8 PG 349 2648.38 TO SW COR SEC 13

ED 1" PIPE 4.5' NORTH OF CENTER OF PVMT, ON LINE EAST EDGE PVMT EXTENDED NORTH.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD PERPETUATED LOCATION.

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.
- I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this US Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Number of included sheets 1

Swall Sunes cmboss

CORNER CODE N-23