U.S.

LAND **PUBLIC** SUR MONUMENT RECORD

2 3 4 5			ODE IN		1 22 23 24 25	NEWARKIWA
6			4	0		ROCK COUNTY WI
						IF AVAILABLE ROCK COUNTY COORDINATES PERFER
1	8	9	NO.		12	North Elev
18		10	10		13	East
						Hor. Datum Vert. Datum
19	20	2	22	23	24	LATITUDE ELLI
30	99	28	91	26	99	LONGITUTE
						GPS (X) TRAVERSE (X)
3	32	33	34	35	96	BASED ON THE FOLLOWING CONTR
		T SYMBOL BOVE IND		ROPER		
a)	•0	CORNER	MONUM	ENT	0	WITNESS MONUMENT
-/ 						
!						

BEARINGS ARE BASED ON:

					,	
ELD	BOOKPAGE	#			SHEET	of
lOW.	A PLAN VIEW DRAWING	DEPICTING TH	E CORNER	MONUMENT	AND SURBOUNDING	

PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH. PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

CORNER CODE

(B)Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1834 MILLER MARCH 12, 1834

PG 36 EAST RANDOM BETWEEN 8 & 17

3630 **ENTER MARSH SOUTH**

3687.42 BROOK 5.28' SOUTH

5281.32 INTERSECT SEC. LINE 3.3' SOUTH POST. LAND SAME

WEST CORRECTED

2640.66 SET 1/4 SEC POST. BUR OAK 6 YELLOW OAK 6, BUR OAK 6 IN S32W 23.1', **YELLOW OAK 6 N32E 13.86'**

3183.84 YELLOW OAK 12 IN DIAM

5281.32 SEC CORNER.

1871 COLLINS REMONUMENTATION PG 194 EAST BETWEEN 8 & 17 VARIATION 6-45

3742.20 CREEK

5303.76 SECTION CORNER

BACK TO

2651.88 SET 1/4 STONE. FOUND TRACES OF ROOTS OF WITNESS TREES.

- 1969 BATTERMAN JR. VOL 4 PG 419. DUG & FOUND STONE 1.5' DEEP. PLACED REFERENCE PIPES. SET MONUMENT BOX OVER R.R. SPIKE. PUNCH MARK.
- 1970 LEE #3135 2652.48 TO SE COR SEC 8 & 26552.48 TO SW COR SEC 8
- 1982 COMBS CSM 11 PG 57
- 1989 BARNES J-7 FD MON. BOX WITH STONE INSIDE & R.R. REFERENCED SAME. MONUMENT IS 1.5' SOUTH OF CENTER OF PVMT. FB 2 PG 3.
- BARNES VOL 6 PG 401 FD R/R IN MON. BOX. N89-19-47E (SOLAR OBSERVATION) 1989 2651.09 TO NE COR SEC 17 & S89-32-37W 2652.39 TO NW COR SEC 17. N89-32-56E 2652.46 TO ERRONEOUS CORNER @ NE COR SEC 17. ANGLE @ N 1/4 COR SEC 17 FROM NW TO NE CORNERS OF SEC 17; 179-47-10

FD PK 2.00' TO THE NORTH & PK 2.00 TO THE WEST, SET MAG NAIL. 2' SOUTH OF CENTER OF PVMT. FD REFERENCE TIES.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD PERPETUATED LOCATION.

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.
- I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Number of included sheets 1

CORNER CODE J-7(1)

A-E 7.08 REQUIREMENT