Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In: T. N. R. E. 4th P.M.	WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT REV 10/23/2004 USMONREC.DWG
CORNER CODE INDEX	P. D
A 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23	24 25, PORTER TWP
	\square_{B}^{A} ROCK COUNTY WI
	·+ C
E	D IF AVAILABLE E ROCK COUNTY COORDINATES PERFERRED
	F ROCK COUNTY COORDINATES TERFERRED
G H J	G H North Elev
K B A B A	J K East
M N	H M
	P LATITUDE ELLIPS. HT.
R S C C C C C C C C C C C C C C C C C C	R
	/ T
v	v NAD83(91)NETWORK ADJ. YR
X S S S S	W X GPS (X) TRAVERSE (X)
Z 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23	7 DACED ON THE FOLLOWING CONTROL
PLACE MONUMENT SYMBOL AT PROPER	24 25
LOCATION ON ABOVE INDEX	
♦ CORNER MONUMENT	○ WITNESS MONUMENT
(4)	
$\cdot, i \cdot i$	

FIELD BOOK _____ PAGE # _____ SHEET ___ OF SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.
PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

BEARINGS ARE BASED ON:_

PO4615 CENTER32

- (B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.
- 1875 RUGER VOL 2 PG 184 SET STAKE SURROUNDED BY 4 HH.
 VAR 6-41 2653.20 TO E 1/4 COR SEC 32, VAR 6-41 2658.15
 TO W 1/4 COR SEC 32, VAR 6-30 2658.15 TO S 1/4 COR SEC
 32, & VAR 6-30 2656.83 TO N 1/4 COR SEC 32, & SOUTH
 171.27 TO CENTER OF HWY.
- 1976 BARNES VOL 5 PG 206 FB #1 PG 17 & 24. DUG & FD 5'
 DEEP STAKE SURROUNDED BY 4 HH 5' DEEP. SET 1 1/2X24
 PIPE & REFERENCED SAME. 9.7 EAST OF WEST PVMT EDGE,
 14' NORTH OF CULVERT. SHORT PK TIES 10.00' TO NE & SE.
 SET 1 1/2X24 PIPE.
- 1976 KIENBAUM CSM 6-126 ANGLE @ E 1/4 COR SEC 32 FROM E/W 1/4 LINE TO NE COR SEC 32 IS 89-59-53
- 2007 LATHROP CSM 31-308 FD PK N89-58-57E 2657.94 TO FD ALUM @ E 1/4 COR SEC 32. FROM E 1/4 COR SEC 32 ALONG SEC LINE TO CEN OF STH 14 IS SO-08-46E 853.24.
- FD PK. & 3 REFERENCE MONUMENTS
- C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

DID NOT ACCEPT THE PK. THE RECORD INTERSECTION DISTANCES ARE IN HARMONY WITH EACH OTHER.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

AS SHOWN IN DRAWING THE PK IS N15-00-58W 0.19 OF THE CENTER OF SEC 32.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 1 OF 2

CORNER COD

Jenes Jemboss Janes 6-9-09

NO

A.E. 7.08 REQUIREMENT

