

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners in:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 1 N., R. 11 E

CORNER CODE INDEX

A	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B	6									1														
C		5																						
D																								
E																								
F																								
G	7																							
H		8																						
I																								
J																								
K																								
L	18																							
M		17																						
N																								
O																								
P	19																							
Q		20																						
R																								
S																								
T	30																							
U		29																						
V																								
W																								
X	31																							
Y		32																						
Z																								

NEWARK TWP

ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON:

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

CORNER CODE A-11

NE5Q6

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 MULLETT

WEST ON SOUTH SIDE SECTION 33

- 2640 SET QUARTER SECTION POST IN PRAIRIE AND MOUND OF EARTH AND SODS
- 3102 INDIAN PATH CS S.E.
- 5280 SET POST CORNER SECTIONS 32 & 33 MADE A MOUND OF EARTH AND SODS LAND ROLLING SECOND RATE DRY PRAIRIE
- 1868 LOCKE PLYMOUTH REMONUMENTATION SEPT 11, 1868
PG 69 WEST ON SOUTH LINE SEC 33 VAR 6-20
- 1214.4 CENTER SLUICE BRIDGE 4.62' WIDE
- 1712.04 CENTER SLUICE BRIDGE 3.96' WIDE
- 2668.71 INTERSECTED 1/4 LIEN AT COR. FOUND OLD STAKE IN CENTER OF HIGHWAY AND IN LINE WITH FENCE RUNNING NORTH. SURROUNDED MONUMENT BY HEAP OF LIMESTONE.
CONTINUED WEST WITH VAR 6-20
- 2705.34 CENTER OF SOUTH END OF BRIDGE
- 5340.39 INTERSECTED WEST BOUNDARY 12.87' SOUTH OF COR. VAR CORRECTED 6-04. 1/4 MONUMENT MARKED 33 ON ITS NORTH FACE.
- 1871 COLLENS REMONUMENTATION
PG 212 EAST ON NORTH LINE OF 4 VARIATION 5-40
- 5334.12 SECTION CORNER
BACK TO
- 2667.06 SET 1/4 STONE 31.02' EAST OF PLYMOUTH 1/4 CORNER. NOV 6, 1871
- 1871 RUGER VOL 2 PG 75 FD STONE MON @ S 1/4 COR SEC 33, 2665.41 VAR 5-20 FROM S 1/4 TO SW CORNERS SEC 33, 2667.89 VAR 5-25 FROM S 1/4 COR TO SE CORNERS SEC 33, 2660.66' VAR 6-18 FROM S 1/4 COR CENTER SEC 33, & 5321.78' FROM S 1/4 COR SEC 33 TO N 1/4 COR SEC 33.
- 1957 BATTERMAN VOL 3 PG 520 DUG TWO HOLES 5X5X2 1/2 DEEP. FD STONE MON. SET 1 1/2 PIPE ABOVE STONES IN RD. REFERENCED SAME. 30.60 BETWEEN CORNERS. PLYMOUTH WEST OF NEWARK COR. 2640.72 FROM S 1/4 COR SEC 33 TO THE WEST, 2640.72 TO THE EAST.
- 1967 BATTERMAN VOL 4 PG 316 FD 6X6 CUT L.S. & REFERENCED SAME. DIAGRAM SHOWS COR EAST OF BRIDGE.
- 1978 BARNES VOL 5 PG 473 S88-47-39E 2667.29 TO NW COR SEC 4, S89-02-54E 2640.64 TO SE COR SEC 33, FROM S 1/4 COR SEC 33 TO SW COR SEC 33 2673.85 & 2670.88 TO SE COR SEC 33.
- 1978 BARNES VOL 5 PG 481 FD CARPENTERS NAIL 0.5' DEEP AT N 1/4 COR SEC 4, FD 1 1/4" PIPE AT S 1/4 COR SEC 33. REPLACED WITH ALUM. MONUMENTS. 30.70' BETWEEN MONUMENTS. NEWARK COR IS TO THE EAST.

FD ALUM. MON. FD TIES IN VOL 4 PG 316

Ronald Barnes
7-03-01

NE506

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FOUND ALUM. MONUMENT AS PERPETUATED.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

seal

Donald Barnes

emboss

7-03-01

SHEET 2 OF 2

CORNER CODE **A-11**

A-E 7.08 REQUIREMENT