MONUMENT RECORD

For Public Land Survey Corners In: WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT T. ∠N. R. ∠/_E. CORNER CODE INDEX NEWARK **TWP** 20 21 22 23 24 25_A **ROCK COUNTY WI** C C D IF AVAILABLE D E E ROCK COUNTY COORDINATES PERFERRED F G H J K G North Elev. East L M L M Hor. Datum ___ Vert. Datum N O P Q LATITUDE ELLIPS. HT. R S LONGITUDE T U V GPS (X) TRAVERSE (X) BASED ON THE FOLLOWING CONTROL: PLACE MONUMENT SYMBOL LOCATION ON ABOVE INDEX **◆ CORNER MONUMENT WITNESS MONUMENT** (a) 2722,48 2.05 589-54-00E NEZ N84-33-09W BEARINGS ARE BASED ON: W/4COR DSEC2 SEC Z SY4 COR SEC Z OBSERVATION SHEET 519 FIELD BOOK PAGE # SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH. PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

(B)Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

WEST ON SOUTH SIDE SECTION 35

1387.32 WHITE OAK 10 IN DIAMETER

2640 SET QUARTER SECTION POST WHITE OAK 18 N69E 14.52'; WHITE OAK ` 14 N78W 23.76'

SET POST CORNER SECTION 34 & 35 WHITE OAK 20 N62E 33'; WHITE 5280 OAK 3 N62W 24.42'

1868 LOCKE PLYMOUTH REMONUMENTATION PG 15

EAST ON SOUTH LINE OF SEC 35. VAR 5-30

330 SET OFF 15.18' NORTH

1716 SET OFF 6.27' NORTH

SET OFF 4.29' NORTH 1452

1848 SET OFF 46.86' NORTH

2696.1 INTERSECTED 1/4 LINE 52.8' NORTH OF COR. FOUND STUMP OF EAST BT AND WHERE WEST BT WAS DUG OUT AND OLD STAKE. COR 3 FT NORTH OF E & W FENCE & 3 FT WEST OF N & S FENCE VAR **CORRECTED 5-56 AUG 20, 1868**

CONTINUED EAST FROM 1/4 COR WITH VAR 5-56

INTERSECTED EAST BOUNDARY 3.63' SOUTH OF COR. VAR 5346 CORRECTED 5-55 1/4 MONUMENT MARKED WITH FIGURE 35 ON NORTH FACE.

1871 COLLINS REMONUMENTATION PG 160

EAST ON NORTH LINE OF 2, VARIATION 6-16

5454.24 SEC CORNER

BACK TO

2727.12 SET 1/4 STONE 1.98 EAST OF PLYMOUTH CORNER OCT 21 1871 1882 HOLMES VOL 2PG 349 VAR 4-29 2774.31 TO CENTER OF SEC 2.

FOUND CUT LIMESTONE 0.1' ABOVE GRADE & @ S 1 COR SEC 35 PLYMOUTH TWP FD CUT LIMESTONE 0.1' ABOVE GRADE ON SOUTH SIDE OF LILAC BUSH & ABOUT 10' WEST OF N/S FENCE. IN BACK YARD OF HOME.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FOUND CUT LIMESTONE.

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.
- I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Donald Baines

Number of included sheets 1

emboss 6-29-0/

CORNER CODE A-19