Paper weight-110# (minimum)

Black nonfading ink required

U.S.

PUBLIC LAND SURVEY MONUMENT RECORD

T. <u>4</u> N. R. <u>11</u> E. 4th P.M. CORNER CODE INDEX 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25						PORTER TWP
B C D E	5	X	3	1	A B B C D D	ROCK COUNTY WI IF AVAILABLE ROCK COUNTY COORDINATES PERFERRED
F G H	8	9	10	1	F	
K L M N	\$	16	15		A I	1 Want Dotum
O P Q R	70	•	37	73		LATITUDE ELLIPS. H
S T U V	79	28	7	76	No.	TOTAL TOTAL TOTAL AND THE
W X Y Z 2 3 4 5 PLACE N	6 7 8 9 10 10 NUMENT S	11 12 13 SYMBOL		718 19 20 2 ROPER	22 23 24 25	GPS (X) TRAVERSE (X)

♦ CORNER MONUMENT

WITNESS MONUMENT

BEARINGS ARE BASED ON:_____

FIELD BOOK _____ PAGE # _____ OF _____ SHEET ____ OF ____ SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.
PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE _____ 25

PO520 E1/4-COR-SEC1

- (B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.
- 1833 (SEP 20) MULLETT & BRINK NORTH ON EAST SIDE SECTION 1 1372.14 BUR OAK 12 IN DIAMETER
 - 2640 SET QUARTER SECTION POST BUR DAK 14 S19W 22.44' BUR DAK 12 N4N 48.18'
 - 5280 SET POST CORNER TO TOWNSHIPS 4 & 5 N
 RANGES 11 & 12E BEARINGS {BUR DAK 12 N33E
 24.42' BUR DAK 16 N77W 3.3'} MARKED {BUR DAK
 18 S26E BUR DAK 18 S62W LAND LEVEL FIRST RATE
- 1865 LOCKE VOL 1 PG 226 & #1065 FD 8. BT, 2686.04 TO CEN SEC 6 & 5373.88 TO E 1/4 COR SEC 6
- 1874 RUGER VOL 2 PG 128 FD OLD STAKE & HH STONE ON THE W. SIDE OF IT. ALSO FD WHERE STUMP OF BTS HAD BEEN DUG UP. SET LIMESTONE 24X8X6 VAR 8-02 2552.22 TO CENTER SEC 6, & 5250.3 TO W 1/4 COR SEC 6
- 1886 RUGER VOL 2 PG 284 FD LIMESTONE SET BY SELF IN FORMER SURVEY VAR 5-30 2659.30 TO SW COR SEC 6, 2554.86 TO CEN SEC 1
- 1971 LEE VOL 4 PG 508 DUG & FD LS 24X8X6. REF. SAME. USGS BM IS JUST EAST OF EAST REF MON. FD W $1/16^{TH}$ COR OF SW 1/4 OF SEC 6.
- 1989 NORTHROP #12198 LIMESTONE MON IN PLACE WITH REF TIES. N89-16-34W TO ALUM MON @ W 1/4 COR SEC 1. N89-16-34W 2548.21 TO POB OF SURVEY ON NORTH SIDE OF RD.
- 1989 NORTHROP CSM VOL 13 PG 543 LS. SOO-15-OOW 2659.35 TO ALUM @ S 1/4 COR SEC 1, N89-16-34W 5255.35 TO ALUM @ W 1/4 COR SEC 1
- 1999 NORTHROP CSM VOL 22 PG 453 FD R/R SPIKE @ E 1/4 COR SEC 1 PORTER TWP, 2699.26 TO NE COR SEC 1, ANGLE 92-35-03 @ E 1/4 COR SEC 1 PORTER TWP FROM E/W 1/4 LINE SEC 1 TO NE COR SEC 1
- 2003 LATRHOP CSM VOL 27 PG 47 FD RR SPIKE 2659.29 TO ALUM @ SE COR SEC 1.
- 2006 BARNES C-1 FD BENT R/R SPIKE WITH "X" LEANING TO THE EAST & ALL 4 REFERENCE MONUMENTS. INTERSECTION OF RECORD DISTANCES TO REFERENCE MONUMENTS IS IN HARMONY WITH CALL DISTANCES AND R/R SPIKE. ACCEPTED OBLITERATED EVIDENCE LOCATION. INTERSECTION OF RECORD DISTANCES IS IN HARMONY WITH ALL RECORD DISTANCES AND WITH BENT R/R.

FD R/R SPIKE & TIES.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED PERPETUATED LOCATION AS DETERMINED BY REFERENCE TIES.

Ind Daves 4-03-09

SHEET 1 OF 3 CORNER CODE C-25

PO520 E1/4-COR-SEC1

NONE

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

 NONE- R/R SPIKE WAS HIT.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 2 OF 3

Bentoss 4-03-09

CORNER GODE C-25

A.E. 7.08 REQUIREMENT

