Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In: T. \(\frac{1}{2} \) N. R. \(\frac{1}{2} \) E. 4th P.M. CORNER CODE INDEX	WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT REV 10/23/2004 USMONREC.DWG
A	B
PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX CORNER MONUMENT (a)	

BEARINGS ARE BASED ON:_____

FIELD BOOK _____ PAGE # ____ SHEET ___ OF SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.
PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE _

R-13

FU587^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1836 (AUG) BURNHAM NORTH BETWEEN SECTIONS 21 & 22

REMARKS

NO STATIONS

2640 SET 1/4 SEC POST BUR DAK 16 S52E 45.54'

BUR OAK 24 NORTH 69.96'

2709.96? BUR OAK 24 IN DI

5280 SET POST COR TO 15,16,21,&22 YELLOW OAK

12 N49E 4.62'? BUR DAK 8 S3E 5.28'? DAK

OPENINGS VERY OPEN

1836 (AUG) BURNHAM EAST RANDOM BETWN SECS 21 & 28

4620 LEAVE PRAIRIE

5241.06 INT EAST BOUNDY AT STAKE FIRST RATE DRY

PRAIRIE & BUR DAK OPENINGS

WEST CORRECTED BETWN SECS 28 & 21

2620.2 SET 1/4 SEC POST BUR DAK 18 S61 1/2E 36.96'

NO OTHER BEARING NO STATIONS

5241.06 TO CORNERS

1836 (AUG) BURNHAM EAST RANDOM BETWEEN SECS 22 & 27

5287.26 INT EAST BOUNDARYT 36.96' N GOOD 2^{ND}

RATE W & BUR OAK OPENINGS BROKEN
WEST CORRECTED BETWN SECS 22 & 27

NO STATIONS

2643.30 SET 1/4 SEC POST BUR OAK 14 S3E 528'? NO

OTHER BEARING

5058.9 BUR OAK 12 IN DI

5287.26 TO CORNERS

1836 (AUG) BURNHAM NORTH BETWEEN SECTIONS 27 & 28

194.04 BUR OAK 12 IN DI

2640 SET 1/4 SEC POST BUR OAK 14 N9E 23.1' BUR

OAK 10 S5EW 37.62'

NO STATIONS

5280 SET POST COR TO 21,22,27,28

BUR DAK 12 N79E 178.86' BUR DAK 12 N70W

304.26' FIRST RATE BUR DAK OPENINGS

1858 CHURCH VOL 1 PG 77 CALLS FOR BUT STATES NOTHING ABOUT MON. VAR 7 $\frac{1}{2}$ 2645.94 TO S $\frac{1}{4}$ COR SEC 22

1867 LOCKE VOL 1 PG 282 FD STUMPS OF W 8T AND REMAINS OF STUMP OF E 8T AND REMAINS OF OLD STAKE (W. 8T N60W 310.2') SET STAKE SURROUNDED BY 4 FLAT LIME STONES 2640 TO N 1/4 COR SEC 27, VAR 6-40 2646.60 TO W 1/4 COR SEC 27, 883.74 NORTH OF SOUTHEASTERLY RD

1974 LEE VOL 5 PG 12 SET ALUM. BY CHECKING OCCUPATION TO E & S

- 1974 LEE VOL 5 PG 20 SET BY CHECKING OCCUPATION TO EAST & SOUTH SET C.I. MON. ANGLE OF 91-33-24 @ NW COR SEC 27 FROM N ¼ COR SEC 27 TO W ¼ COR SEC 27, 2642.68 TO W ¼ COR SEC 27 & 2627.96 TO N ¼ COR SEC 27. AT FENCE INT. ON NORTH SIDE OF PENNYCOOK RD. SHOWS TIES TO STONES OF REC 884' SOUTH OF NW COR SEC 27.
- 1975 BARNES VOL 5 PG 96 FD MON. & REF. SAME. @ SE COR OF FENCE INT.
- 1974 SCHROEDER CSM VOL 4 PG 85 STATES NOTHING ABOUT MON. SOUTH 874.41 TO CENTER OF COX RD.
- 1974 SCHROEDER #1404 1987 SCHROEDER #12843 CALLS FOR COR BUT STATES NOTHING ABOUT MON. ANGLE 91-34-XX @ NW COR SEC 27 FROM N 1/4 COR SEC 27 TO W 1/4 COR SEC 27. 914.85 FROM CENTER OF COX RD
- 1976 BARNES VOL 5 PG 97 FD MON. 2631.28 TO S ¼ COR SEC 21 & 2657.74 TO E ¼ COR SEC 21
- 1977 SCHROEDER #1324, #1326, & #6563 CALLS FOR STATES NOTHING ABOUT MON. 2628.00 TO S 1/4 COR SEC 22, ANGLE OF 91-19-43 @ S 1/4 COR SEC 22 FROM SW COR SEC 22 TO N/S 1/4 LINE SEC 22

11/14/07

PAGE 1 OF 2

CORNER CODE R-13

Donald Bours

FU587

- 1981 AERO-METRIC PHOTO CONTROL NGVD 29 ELEVATION 889.18'
- 1982 SCHROEDER CSM VOL 11 PG 125 STATES NOTHING ABOUT MON. SOUTH 874.41 TO CENTER OF COX RD.
- 1987 NORTHROP CSM VOL 13 PG 54 FD C.I. ANGLE 180-06-33 @ N $^{1}\!\!/_{\!\!4}$ COR SEC 28 FROM NE TO NW CORNERS OF SEC 28
- 1990 SCHROEDER CSM VOL 14 PG 215 STATES NOTHING ABOUT MON. EASTERLY 1314.08 TO $1/16^{TH}$ COR.
- 1993 SCHROEDER #10172 STATES NOTHING ABOUT MON.

FD CI /CARSONITE POST @ FENCE INT. & REFERENCE MONUMENTS.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD CI

Karika Baines (1/14/07

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

 NDNE
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 2 OF 2

GORNER CODE R-13