Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

T. N. R. 12 E. 4th P.M. CORNER CODE INDEX A 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 B C D D D D D D D D D D D D D D D D D D	B ROCK COUNTY WI C D IF AVAILABLE ROCK COUNTY COORDINATES PERFERRED F G H North Elev. J K East M Hor. Datum Vert. Datum O P LATITUDE ELLIPS. HT R S LONGITUDE T U NAD83(91) NETWORK ADJ. YR W GPS (X) TRAVERSE (X) Z BASED ON THE FOLLOWING CONTROL:
1 2 8 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX	
(a) CORNER MONUMENT	WITNESS MONUMENT

BEARINGS ARE BASED ON:____

ſ			
		/	7
FIELD BOOK PAGE #	SHEET	OF	
SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND S	SURROUN	DING	
PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.			
PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982			
		_	

FU622^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 (SEP15) MULLETT & BRINK SOUTH BOUNDARY TAN R12E VAR B

40' EAST ON SOUTH SIDE SECTION 31

2574 SET QUARTER SECTION POST BUR DAK 8 N50W 25.74' BUR OAK B N27E 53.46'

3451.14 SPRING STREAM @NE

4257 ROCK RIVER 297' CROSSES SE SET POST ON RIGHT BANK OF WHITE OAK 30 S82W 46.86' WHITE DAK 16 N3DW 122.1' LAND ROLLING SECOND RATE TIMBER WHITE BLACK AND BUR

OAK SEPT 15TH 1833

1835 (JANY 7TH) MULLETT & BRINK WEST ON SOUTH SIDE SECTION 31

> 460.68 ROCK RIVER OPPOSITE MEANDER POST ON RIGHT BANK & SET POST ON LEFT BANK. B. ASH 10 S30E 9.9' ELM 10 N20W 15.84'

1023 OVER RIVER TO MEANDER POST LAND @ SAME JANY 7TH 1835

- 1869 LEE VOL 1 PG 341 FD STUMPS OF BTS & OLD STAKE UNDER FENCE. [USED TO SUBDIVIDE SEC 6 JANESVILLE TWP.
- 1870 RUGER VOL 2 PG 34 & #1431 FD OLD STAKE & WEST BEARING TREE & STUMP OF EAST BEARING TREE. SET IRREGULAR HARD HEAD STONE 21X17X10 POINT UP & SURROUNDED IT WITH 5 SMALL HARD HEAD STONES. VAR 8-19 2589.51 TO SW COR SEC 31
- 1873 RUGER VOL 2 PG 106 FD STUMPS OF BTS & FD ON COR. HARD HEAD STONE 21X12X7 SURROUNDED BY 4 SMALL HHS. VAR 5-55 2680.92 TO CEN SEC 6 JANESVILLE TWP. VAR 8-07 1558.92 TO M.P. MUST OF ACCEPTED ORIG COR FOR 5 1/4 COR SEC 31 AS ALSO THE N 1/4 COR SEC 6 **JANESVILLE TWP]**
- 1883 LEE VOL 2 PG 364 & #1449 FD BT & STUMP OF BT & STONE AT COR, 1333.2 EAST IF 1/16TH COR
- 1934 SUNNY VOL 3 PG 241 FD STONE MON. 21X12X7 HH SURROUNDED BY 4 HH AT N 1/4 COR SEC 6.
- 1968 BATTERMAN VOL 4 PG 388 & VOL 6 PG 366 @ N 1/4 COR SEC 6 FD HH 21X12X7 SURROUNDED BY 4 HH. INKED ON THE PAGE WAS A STATEMENT THAT THE HH WAS REPLACED WITH A CONCRETE MON. WITH BRASS CAP. 2601.92 FROM N 1/4 COR SEC 6 TO NW COR SEC 6.
- 1969 SHIMEALL CSM VOL 1 PG 212 STATES NOTHING ABOUT MON.
- BATTERMAN VOL 4 PG 275 AT N 1/4 COR SEC 6 JANESVILLE TWP DUG & FD 21X12X7 SURROUNDED BY SM HH'S AS SET BY RUGER IN 1873. REPLACED MON WITH CONC. MON WITH **BRASS CAP**
- 1975 COMBS CSM VOL 5 PG 5 FD PIPE
- 1981 COMBS #1441 FOUND IRON PIPE. 1331.09 TO FD STONE MON @ E $1/16^{TH}$ COR OF SW $\frac{1}{4}$ SEC 31
- COMBS #1440 & 1441 FOUND IRON PIPE 1981
- COMBS CSM VOL 10 PG 409 FD PIPE
- 1982 COMBS CSM VOL 11 PG 116 FD PIPE
- 1985 COMBS #13748 FD CONC. MON AT N 1/4 COR SEC 6 JANESVILLE.
- 1987 BARNES VOL 6 PG 366 SHOWS WPL COORDINATES & THE INVERSE. S88-44-12W 2601.20 TO NW COR SEC 6 & N89-16-24E 2503.59 TO NE COR SEC 6 JANESVILLE TWP
- 1987 BARNES A-3 AT N 1/4 COR SEC 6 FD CONCRETE MON WITH BRASS DISK. 0.3' ABOVE GROUND. PLACED WHITE PLASTIC POST ON NORTH SIDE OF MON. & REFERENCED SAME. IN E/W FENCE ROW & ABOUT 11' WEST OF N/S FENCE. 278,102.94; 2,235,996.61 BY LEAST SQUARES ROTATION.

SHEET 1 OF 2 CORNER CODE Z-3

FU622

2002 COMBS CSM VOL 25 PG 102 DISK IN CONCRETE 2601.17 TO SW COR SEC 31 2003 COMBS #14696 FD CONC. MON

USED MY OLD OBSERVATIONS.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED REC. CONC. MON.

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

iosa

SHEET 2 OF 2

CORNER CODE Z-3

A.E. 7.08 REQUIREMENT