Paper weight-110# (minimum)

Black nonfading ink required

U.S.

BEARINGS ARE BASED ON:___

PUBLIC LAND SURVEY MONUMENT RECORD

MONUMENT RECORD				
For Public Land Survey Corners In: T. N. R. E. 4th P.M. CORNER CODE INDEX A	B ROCK COUNTY WI C D IF AVAILABLE E ROCK COUNTY COORDINATES PERFERRED F G H North Elev. J K East M Hor. Datum Vert. Datum O P LATITUDE ELLIPS. HT R S LONGITUDE T U NAD83(91) NETWORK ADJ. YR W GPS (X) TRAVERSE (X) Y BASED ON THE FOLLOWING CONTROL:			
(a) CORNER MONUMENT	WITNESS MONUMENT			

1		/		
FIELD BOOK PAGE #	SHEET	OF	7	
SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING				
PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.				
DI AMMINO C. ZOMBIO COMMITTED A DODGED WITH DODGE ON A CALCOLO				

FU546^

- (B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.
- 1834 (MAR/APR) HARRISON EAST ON RAND BET SECS 9 & 16 2640 TEMPY 1/4 SEC COR

5305.08 INT. E BDY 26.4' N OF P LAND & ? SAME COR WEST

2652.54 QUARTER SEC COR {W.O. 12 S52E 3.96' W.O. 10 N65W 5.28' W.O. 12 W.O 10}MARKED 5305.08 INT. SEC COR

- 1848 PIERCE TWP RD BK 1 PG 11 THIS DAY SURVEYED A RD BY DIRECTION OF THE COMMISSIONERS OF HIGHWAYS, BEGINNING AT A STAKE ON THE SEC. LINE OF 9 & 16 IN T4 OF RANGE 12 AND IN THE RD RUNNING NORTH & SOUTH BEING W. OF THE $\frac{1/4}{4}$ SECTION POST [N $\frac{1}{4}$ COR SEC 16] 1361.58 NOW FROM SAID STAKE RUN ON SECTION LINE N81-15E 2079'; THENCE S58E 528'; THENCE N60E 462'; THENCE N86-15E 660'; N58E 613.8' TO <u>SECTION</u> LINE OF 15 & 10 THEN ON SECTION LINE NB1-15E 1564.2; THENCE S62E 297'; THENCE N73-15E 1036.2' TO THE SEC LINE; THENCE NB1-15E SECTION LINE 2329.8' TO SEC CORNER; THENCE N49E 2277'; N18W 825'; THENCE N38W 363'; THENCE N7E 1395.9', N65-15E R, 2310'? THEN N73E 660'; THENCE N42-30E 759'; THENCE N63E 775.5'; THENCE S73E 1155' N83E 1645.3B; THENCE N56E 301.62'; THENCE N73E 601.26' TO THE 1/4 LINE OF SEC 12 & HIGHWAY ON NORTH BANK OF ROCK RIVER. MAKING 21,077.76'
- 1872 LEE VOL 2 PG 89 FD STAKE & BTS 2684.22 TO SW COR SEC 9, VAR 8-30 2648.58 TO SE COR SEC 9, 1316.37 SOUTH OF E/W ALLEY (CENTER OR SOUTH R/W ?) 885.72 EAST OF RD (CENTER OR EAST R/W ?)
- 1871 RUGER VOL 5 PG 431 FIELD BK R-K PG 144. SHOWS ORIG NOTES FOR BEARING TREES. STATES NOTHING ABOUT MON. NOR DID HE USE IT.
- 1872 RUGER VOL 2 PG 199 FD STAKE AT COR. ALSO FD BOTH BTS. VAR 7-53 2674.32 TO NW COR SEC 16
- 1976 BARNES VOL 5 PG 229 FD 4"X6" STONE PAINTED RED.
 AGREED WITH OCCUPATION LINE TO THE EAST & WITH REC
 DISTANCE TO THE SW COR SEC 9. REF SAME. IN RUBBISH
 PILE IN E/W FENCE NORTH OF DIRT DRIVE
- 1978 SANDSNES #1104 AIR PHOTO CONTROL FOR EDGERTON
- 1980 BARNES VOL 6 PG 42 SANDSNES S88-43-37W 2680.02 TO SW COR SEC9.
- 1985 COMBS CSM VOL 12 PG 250 & 415 STATES NOTHING ABOUT MON.
- 1992 SCHROEDER CSM VOL 16 PG 34 STATES NOTHING ABOUT MON.
- 1999 CDMBS #7401 STONE MON. S89-10-15W 2680.37 TO SW CDR SEC 9
- 2006 NORTHROP #??? FD STONE MON 2639.95 TO 2" PIPE @ NE COR SEC 16.

SHEET 1 OF 2 CORNER CODE J-11

Doneld Baines 11/05/07

FU546

FD SQUARE L.S. WITH CARSONITE POST

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD L.S. & REFERENCE MONUMENTS.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

NONE

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

ΝО

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 2 OF 2

CORNER CODE **J-11**

A.E. 7.08 REQUIREMENT