

PLAT AND RECORD

Of a Survey on Section _____ T _____ R _____ E. of the 4 P. M. in Janesville Township
 Rock County, Wisconsin, made _____ the _____ 19 _____

I hereby certify that the following is a correct record of said survey as made by me.

COUNTY BUILDING
 IN CITY OF БЕЛОIT

County Surveyor.

County Surveyor's Office
 Janesville Wis.

Aug. 13th 1875

I, Edward Ruger, County Surveyor of Rock County, State of Wisconsin, do hereby certify that on the third day of August A.D. 1875, I took levels from the top surface of skewback, next to the wall, at the N.W. Cor. of the S. abutment of the highway bridge across Rock River at Monterey, & caused marks to be cut as follows: to wit: in the S. pier of the R.R. bridge at Monterey, at the N.E. Cor. of said pier, in the wall of the stone Flour Mill at Monterey, at the N.W. Cor. of said Mill; in the N. face of the W. wing wall of the S. abutment of the highway bridge at Monterey; in the W. face of the first pier N. of the S. abutment of said highway bridge; in the W. face of the second pier N. of said S. abutment; in the S. face of the parapet wall W. of the double pier of said highway bridge, in the E. face of the Ry. pump house; and in the wall of the stone Woolen Mill at Monterey, at the N.E. Cor. of said Mill. All of the above designated marks were painted with coal tar to further identify them, and they are all in the same level horizontal plane, eight inches above the upper surface of the skewback, next to the wall, at the N.W. Cor. of the S. abutment of said highway bridge across Rock River at Monterey

I, also hereby certify that on the eleventh day of August A.D. 1875, I took levels

Copied from P. 17A County Surveyor's Record.