

## PLAT AND RECORD

Of a Survey on Section \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ E. of the 4 P. M. in Janesville Township

Rock County, Wisconsin, made \_\_\_\_\_ the \_\_\_\_\_ 19 \_\_\_\_\_

I hereby certify that the following is a correct record of said survey as made by me.

COUNTY BUILDING  
CITY OF JANESVILLE

County Surveyor.

County Surveyors Office  
Janesville, Wis.

August 13<sup>th</sup> 1875

I, Edward Ruger, County Surveyor of Rock County, State of Wisconsin, do hereby certify that on the third day of August "A.D." 1875, I took levels from the top surface of skewback, next to the wall, at the North west corner of of the South abutment of the highway bridge across Rock River at Monterey, and caused marks to be cut as follows: to wit- in the South pier of the railroad bridge at Monterey, at the North East corner of said pier; in the wall of the stone Flour Mill at Monterey, at the Northwest corner of said mill; in the North face of the west wing wall of the South abutment of the highway bridge at Monterey; in the west face of the first pier North of the South abutment of said highway bridge; in the West face of the Second pier North of said South abutment; in the South face of the parapet wall West of the double pier of said highway bridge; in the East face of the railway pump house; and in the wall of the stone Woolen Mill at Monterey, at the North East corner of said Mill. All of the above designated marks were painted with coal tar to further identify them; and they are all in the same level horizontal plane, Eight inches above the upper surface of the skewback, next to the wall, at the North west corner of the South abutment of said highway bridge across Rock River at Monterey

I also hereby certify that on the eleventh day of August A.D. 1875, I took levels

Copied from Page 174 County Surveyors Record.