

PLAT AND RECORD VOL. 5

307

Of a Survey on Section 31 4 N 10
7,13,15,16 T 3 N 10 E. of the 4 P. M. in UNION Township
 Rock County, Wisconsin, made JULY the 27 1977

I hereby certify that the following is a correct record of said survey as made by me.

COUNTY BUILDING
 CITY OF JANESVILLE

Donald Barnes



County Surveyor.

DUG FOR THE FOLLOWING CORNERS IN MAGNOLIA TOWNSHIP

- E $\frac{1}{2}$ COR SECTION 13 : found wooden stake surrounded by HH stones
- NE COR SECTION 13 : dug and found broken limestone. if not broken the stone would measure 4"x6"x12", and was surrounded by large pieces of concrete, old nails and cast iron grates. hole was 5' deep.
- N 1/16 CORNER SEC 13: 1' deep found HH stone 10"x4"x5" surrounded by 4 red bricks. also to the west found $\frac{1}{2}$ "x24" iron rod.
OF NE $\frac{1}{4}$
- S $\frac{1}{2}$ COR SECTION 15 : Dug and found nothing. The soil condition under the road indicates the ground was cut out for the road.
- S $\frac{1}{2}$ COR SECTION 16 : Dug and found many large rocks and timbers did not find rec stake and sandstones.
- S $\frac{1}{2}$ COR SECTION 7 : 1' deep solid red rock covered bottom of 4'x7' hole. Dug at fenceline and center line of road.

DUG FOR THE FOLLOWING CORNERS IN UNION TOWNSHIP

- E $\frac{1}{2}$ COR SECTION 31 : Found cut limestone 1' deep

MICROFILMED