

PLAT AND RECORD

Of a Survey on Section **33** **4N 13** **4** T **3N** R **13** E. of the 4 P. M. in **MILTON HARMONY** Township

Rock County, Wisconsin, made **NOVEMBER** the **12** 19**66**

I hereby certify that the following is a correct record of said survey as made by me.

MICROFILMED

R. B. Stamer Jr.
County Surveyor.

COUNTY BUILDING
CITY OF JANESVILLE

33

H. Combs
O. Schroeder
Found Cut Stone Mon. at
S. 1/4 Cor. Sec. 33, Milton Twp.
11-8-66.

Found Cut Stone Mon.
at N. 1/4 Cor. of Sec. 4,
Harmony Twp. 11-2-66.

Found Cut Stone Mon. at
S.E. Cor. Sec. 33 Surrounded
by Hardheads 11-8-66

MILTON - HARMONY

TOWNLINER RD.

See Page 244

SEE VOL. PAGE 306

Found Cut Stone Mon.
at N.E. Cor. Sec. 4,
Harmony Twp.
11-8-66.

Found Cut Stone

Found Pipe Over
Cut Stone Mon.
SEE VOL. 4, P. 349

Pipe

Found Red Hardhead at Center of Sec.
Dug Out Stone and Set 1" Pipe Below,
Replaced Stone and Cut Drill Hole on Top
Also Drove Steel Fence Post N.E. of Corner.

See Page 244

Found Cut Stone H.C.

See Page 156

