U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners in For Miscellaneous Corners within LIMA _____TWP. T._4__N., R.__ Sec. _____,T. ____ N. , R. ____E. CORNER CODE INDEX ! 2 3 4 **5** 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 1. Above code numbers are positioned + 21 + Meander, Claim, or Fractional corners of the section. 2. Township corner code numbers shall be applied to the corners of above typical section. EXAMPLE +33 -- 35 PLACE MONUMENT SYMBOL (*) AT PROPER LOCATION ON ABOVE INDEX IF AVAILABLE STATE PLANE COORDINATES North (Y) 288, 23/. 82 Eleve. (Z) 905 East (X)2317, 744.22 Zone South Hor. Datum _____ Vert. Datum ____ (a.) CORNER MONUMENT O WITNESS MONUMENT TIES ARE FILED IN COUNTY SURVEYOR'S RECORDS VOL 4 PAGE STH 59 SECTION CORNER DUG 3' DEEP. SOILS INDICATE AREA WAS CUT PIONEER RD BY ROAD CONSTRUCTION. FIELD BOOK 3 PAGE #

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH. THE CORNER MONUMENT SHALL HAVE THE FOLLOWING CHARACTERISTICS: 1) HAVE AT LEAST TWO PREDETERMINED BREAK-OFF POINTS. 2) IF BROKEN, LEAVE A PERMANENTLY MAGNETIZED REMNANT AT THE ORIGINAL POINT. 3) MUST BE EXTENDABLE. 4) THE CAP IS INSCRIBED: ROCK COUNTY SURVEY MONUMENT - PENALTY FOR DISTURBING MARKER. 5) OR AN EXISTING CUT LIMESTONE. AN IRON PIPE 1 × 1 × 4'O" (MINIMUM) MAY BE USED IN AREAS WHERE GROUND WATER IS WITHIN ONE FOOT OF THE SURFACE. IF THE CORNER IS OCCUPIED BY AN IMPROVEMENT (MANHOLE, BURIED CABLE, ETC.) ANY DURABLE, DISTINCT MONUMENT MAY BE USED. CORNERS SHALL BE REFERENCED WITH AT LEAST 4 DURABLE WITNESS MONUMENTS. WITNESS MONUMENTS SHALL BE MADE OF CONCRETE, NATURAL STONE, IRON OR OTHER EQUALLY DURABLE MATERIAL, EXCEPT WOOD. DESCRIBE THE CORNER AND THE WITNESS MONUMENTS.

REDUG FOR THE CORNER BECAUSE OF THE DIFFERENCES IN DISTANCES.	(b.) Describe any record evidence, monument evidence, occupational evidence any other material evidence you considered, and whether the monument	nce, testimonial evidence or t was found or placed.
65	REDUG FOR THE CORNER BECAUSE OF THE DIFFERENCES IN DISTAN	VCES.
2696.50 ORIG 2680.26 RUGGR 1859 2682.52 RUGGR 1871 2683.34 NY4 consec 27 Mas the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a	RUGER 1859 2687.52 RUGER 1871 2687.34 NY4 COR SEC 27 EY4 COR 27 EY4 COR 27 EY4 COR 27 EY4 COR 27	

(c) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) found perpetuated location?

ACCEPTED FOUND PERPETUATED LOCATION

(d.) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

NA

(e.) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location.

NO

, hereby certify that the corner points as identified by the corner code index were, in a field survey on May 20,983, established, re-established, monumented, re-monumented recovered or restored as expressed below and in conformance with the regulations and rules as required in the current manual of survey instructions of the United States Department of Interior, Bureau of Land Management.

		.
	·	
	·	
	9	
- P		3
J. 3.		F 6
3 M. T.	19 6 75	Ų.
*	garage Village (1997) George Village (1997)	

COUNTY SURVEYOR FILING DATA	
Date of Computer Entry	
Date Received	
Date Microfilmed 10/15/	1984
Treasurer's Receipt No.	
Number of Included Sheets _	

AFFIX YOUR LAND SURVEYOR SEAL. P17