Paper weight-110# (minimum)

Black nonfading ink required

U.S. **PUBLIC**

LAND SURVEY MONUMENT RECORD

roi rubic Land Survey Corners in:	WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT
T. 3 N. R. 4 E. 4th P.M.	REV 10/23/2004 USMONREC.DWG
CORNER CODE INDEX	1/00 00 04/5/ TWD
A 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24	HARM ONY TWP
B C C C C C C C C C C C C C C C C C C C	ROCK COUNTY WI
	D IF AVAILABLE
	E ROCK COUNTY COORDINATES PERFERRED
	- F
H	G H North Elev
K S A S A S	K East
M	M N Hor. Datum Vert. Datum
	$egin{array}{cccccccccccccccccccccccccccccccccccc$
Q /	1 ~
S	- R - S LONGITUDE
T	_ T
V	v NAD83(91)NETWORK ADJ. YR
x 3 3 3 3	W CDG CTD
x 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	$\begin{array}{cccccccccccccccccccccccccccccccccccc$
Z	RASED ON THE FOLLOWING CONTROL
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 PLACE MONUMENT SYMBOL AT PROPER	25 CONTROL.
LOCATION ON ABOVE INDEX	
♦ CORNER MONUMENT) WITNESS MONUMENT
(a)	,
1	

BEARINGS ARE BASED ON:___

FIELD BOOK PAGE # SHEET SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH. PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

HA564 N1/4CORSEC20

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed. FD 36" DEEP THE GUT LIMESTONE IN EXCELLENT GONDITION. A SHREADED CARSONITE WAS LAYING ON TOP OF L.S. & OLD METAL FENGE POST WAS ON THE SOUTH SIDE AND THE TOP 3' WAS BENT NORTHERLY ON WEST SIDE OF L.S. PLACED TWO MAGNETS NEAR TOP OF L.S. & ALUM ON TOP OF GUT LS. PLACED CARSONITE ON SOUTH SIDE OF L.S. FD GUT CROSS ON TOP OF LS.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTEC FD CUT L.S.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 1 OF 2

CORNER CODE N-7(1)

A.E. 7.08 REQUIREMENT

