

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners in:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 3 N., R. 10 E

CORNER CODE INDEX

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B																									
C	6																								
D																									
E																									
F																									
G	1																								
H																									
I																									
J																									
K																									
L	18																								
M																									
N																									
O																									
P	19																								
Q																									
R																									
S																									
T	30																								
U																									
V																									
W																									
X	31																								
Y																									
Z																									

MAGNOLIA TWP

ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

(a)

STATE PLANE

251,045.34

2,183,443.50

BEARINGS ARE BASED ON:

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 1

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

CORNER CODE V-11

maHUF

(E) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1869 LEE VOL 1 PG 354 SET BURR OAK STAKE SURROUNDED BY 4 L.S. VAR 7-31 2660.46 TO SW & SE CORNERS OF SEC 28.
- 1874 RUGER VOL 2 PG 133 PD COR. ESTABLISHED BY LEE. COR IS 15.84' NORTH & 14.52' WEST OF CORNER POST OF FENCE. VAR 6-41 2663.76 TO SE COR SEC 28 VAR 7-23 2661.12 TO CENTER OF SEC 33, 5315.65 VAR 7-23 TO S 1/4 COR SEC 33.
- 1973 LEE VOL 5 PG 3 CALLS FOR CORNER ON STRAIGHT LINE & MIDWAY BETWEEN THE SE & SW CORNERS OF SEC 28. 2666.45 TO SE & SW CORNERS SEC 28, 2655.92 TO CENTER OF SEC 33, 5316.38 TO S 1/4 COR SEC 33, ANGLE OF 88-23-06 @ NW COR SEC 33 FROM N 1/4 COR TO W 1/4 CORNERS OF SEC 33, ANGLE OF 90-27-01 @ NE COR SEC 33 FROM E 1/4 COR SEC 33 TO N 1/4 COR SEC 33, & ANGLE OF 88-59-30 @ N 1/4 COR SEC 33 FROM NE COR SEC 33 TO CENTER OF SEC 33.
- 1973 LEE VOL 5 PG 2 2666.45 TO SE COR SEC 28, 2666.45 TO SW COR SEC 28, 2664.16 TO CENTER OF SEC 28, 5328.31 TO N 1/4 COR SEC 28, ANGLE OF 91-37-57 @ S 1/4 COR SEC 28 FROM CENTER OF SEC 28 TO SE COR SEC 28, ANGLE OF 88-20-03 @ S 1/4 COR SEC 28 FROM SE COR SEC 28 TO CENTER OF SEC 28, ANGLE OF 91-45-20 @ SW COR SEC 28 FROM W 1/4 COR SEC 28 TO S 1/4 COR SEC 28, ANGLE OF 88-29-56 @ SE COR SEC 28 FROM S 1/4 COR OF SEC 28 TO E 1/4 COR SEC 28.
- 1985 BARNES VOL 6 PG 345 SHOWS RECORD DISTANCES
- 1988 BARNES VOL 6 PG 393 A POINT MIDWAY & ON LINE BETWEEN THE SE & SW CORNERS OF SEC 28 IS 2666.45 FROM THE SE & SW CORNERS OF SEC 28, 2658.47 TO CENTER OF SEC 33, A N/S FENCE IS 1340 WEST OF THE SE COR OF SEC 28. ANGLE OF 90-27-34 @ NE COR SEC 33 FROM E 1/4 COR TO N 1/4 CORNERS OF SEC 33, ANGLE OF 88-22-36 @ NW COR SEC 33 FROM N 1/4 TO W 1/4 CORNERS OF SEC 33, ANGLE OF 88-59-05 @ N 1/4 COR SEC 33 FROM NE COR SEC 33 TO CENTER OF SEC 33.
- 1990 BARNES VOL 6 PG 410 A POINT MIDWAY & ON LINE BETWEEN THE NE & NW CORNERS OF SEC 33, 2658.20 TO CENTER OF SEC 33 & 5320.01 (LEE 1973 5316.41) TO S 1/4 CORNER OF SEC 33.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

IN THE 1970'S, W.D.O.T. RECONSTRUCTED C.T.H. B. AT THIS LOCATION THERE IS AN EXTREMELY LARGE AMOUNT OF FILL. I ACCEPTED LEE'S 1973 PLACEMENT OF THE CORNER BUT DID NOT INSTALL A MONUMENT OR REFERENCE THE CORNER LOCATION.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(f) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

scdl

Donald Barnes

emboss

Aug 30 1999

Number of included sheets 1

CORNER CODE V-111